





report date: 2024-03-28

## General information

Make	BMW
Model	120 118D M SPORT
Colour	White
Year of manufacture	2014
Top speed	132 mph
0 - 60 mph	8.9 seconds
Gearbox	8 speed automatic

## Engine & fuel consumption

Power	141 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.995 сс
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	72.4 mpg
Consumption combined	64.2 mpg
CO2 emission	116 g/km
CO2 label	С



CarCheck.co.uk page 1/11



MOT history

MOT expiry date	2025-03-26
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	11
Total items failed	3

MOT #9	2024-03-14 12:30
MOT test number	781183011815
Result	<b>✓</b> Passed
Next expiry date	2025-03-26
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #8		2023-03-27 17:30
MOT test number		117772457498
Result		<b>✓</b> Passed
MOT #7		2023-03-27 17:30
MOT test number		191205498580
Result		<b>×</b> Failed
Pass with rectification	Nearside Front Tyre has had the tread recut (5.2.3 (g))	

MOT #6	2022-03-02 16:11
MOT test number	662924556322
Result	<b>✓</b> Passed

CarCheck.co.uk page 2/11



Result

**Advice** 

LM14WYL report date: 2024-03-28

Passed

MOT #5 2021-02-20 10:03

MOT test number 191044078431

Result \rightarrow Passed

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened both side (1.1.14 (a) (ii))

MOT #4 2019-07-29 14:27

**MOT test number** 231411431736

\_\_\_\_\_

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front Brake disc worn, but not excessively both (1.1.14 (a) (i))

MOT #3 2018-06-12 15:28

MOT test number 253198327374

**Result** ✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge 3mm and worn on outer edge (5.2.3 (e))

Advice Offside Front Road wheel slightly distorted (5.2.2 (c) (i))

Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

MOT #2 2018-06-12 11:13

MOT test number 118593454211

Result X Failed

Fail Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (i))

**Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))

**Fail** Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (i))

Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge 3mm and worn on outer edge (5.2.3

(e))

CarCheck.co.uk page 3/11



MOT #1

MOT test number

Result

Advice Nearside Rear Nail in tyre

CarCheck.co.uk page 4/11



## Tax & MOT check



Tax status	Valid until 1 March
Days left	307
MOT expiry date	26 March 2025
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 5/11



#### Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



#### Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

e union motory		
For how long did the current and previous owner(s) have this BMW? How many owners d Check it in the premium report and see all owner registrations. Download the full report <u>l</u>		
***************************************		
***************************************		
	More info >	
Plate changes  See in this check if this BMW had different number plates.		
Number of plates		,
Current registration	UK W	
Plate since		
Current registration	UK UK	
Plate since		
	More info >	

CarCheck.co.uk page 8/11



#### Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 9/11



## Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2014-05-07
Last registration	2024-03-14
Complete history	See info



Registration #1	2014-05-07	15 mi
Registration #2	2017-06-06	48.083 mi
Registration #3	2018-06-12	67.398 mi
Registration #4	2018-06-12	67.398 mi
Registration #5	2019-07-29	81.150 mi
•		
Registration #6		0.074
		11.777 ea 11.777 ea
Registration #6		11.777 ea 11.777 ea 11.777 ea
Registration #6 Registration #7		11,777-00 11,777-00 11,777-00

More info >

CarCheck.co.uk page 10/11



## Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

## Safety ratings

NCAP rating	****
Adult	91%
Children	83%
Pedestrian	63%
Safety systems	86%
Overall rating	83%
Video	see crash video



# Dimensions & weight

Width	1765 mm
Height	1421 mm
Length	4324 mm
Wheel base	2690 mm
Kerb weight	1345 kg
Max. allowed weight	1915 kg

## Additional information

Fuel tank capacity	52 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 page 3	11/11

Number of axles 2

Engine number 80969029