





report date: 2024-03-29

General information

| Make | VOLVO |
|---------------------|--------------------|
| Model | XC70 D5 SE LUX AWD |
| Colour | Silver |
| Year of manufacture | 2015 |
| Top speed | 127 mph |
| 0 - 60 mph | 7.8 seconds |
| Gearbox | 6 speed automatic |

Engine & fuel consumption

| Power | 212 BHP |
|-------------------------|---------------------|
| Max. torque | 440 Nm at 1.500 rpm |
| Engine capacity | 2.400 cc |
| Cylinders | 5 |
| Fuel type | Diesel |
| Consumption city | 32.8 mpg |
| Consumption extra urban | 54.3 mpg |
| Consumption combined | 44.1 mpg |
| CO2 emission | 169 g/km |
| CO2 label | Н |



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 1

Date 2021-10-23

Pictures 41

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



| MOT | history |
|-----|---------|
| | , |

MOT #7

| MOT expiry date | 2024-09-06 |
|--------------------|------------|
| MOT pass rate | 75 % |
| MOT passed | 6 |
| Failed MOT tests | 2 |
| Total advice items | 0 |
| Total items failed | 4 |

| MOT #8 | 2023-09-07 11:07 |
|------------------|------------------|
| MOT test number | 886957196856 |
| Result | ✓ Passed |
| Next expiry date | 2024-09-06 |

| MO1 4 | +1 | 2023-09-00 10.32 |
|-------|--|--------------------|
| MOT t | est number | 258771303433 |
| Resul | t e e e e e e e e e e e e e e e e e e e | X Failed |
| Fail | Offside Side repeater lens defective such that the emitted light is adversely affected | d (4.4.1 (b) (ii)) |
| Fail | Offside Side repeater not working (4.4.1 (a) (ii)) | |
| Fail | Nearside Side repeater not working (4.4.1 (a) (ii)) | |

| MOT #6 | 2022-02-09 18:19 |
|-----------------|------------------|
| MOT test number | 251343478926 |
| Result | ✓ Passed |
| | |
| MOT #5 | 2021-01-18 09:29 |
| MOT test number | 508033002111 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/11



MOT #4 2020-01-27 14:03 **MOT test number** 254773947251 Result ✓ Passed 2019-01-30 09:56 MOT #3 765815989187 **MOT test number** Result ✓ Passed MOT #2 2018-02-01 09:34 **MOT test number** 911337241393 Result ✓ Passed MOT #1 2018-01-23 14:04 988874321781 **MOT test number** Result **X** Failed Fail Nearside Front Side repeater not working (1.4.A.2c)

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



| Tax status | Valid until 1 February |
|------------------|------------------------|
| Days left | 278 |
| MOT expiry date | 6 September 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|---|------------|
| Band | Н |
| Single payment (12 months) | £ 290,00,- |
| Single six month payment | £ 159,50,- |
| Total payable by 12 monthly instalments | £ 304,50,- |

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

SX64EEF

report date: 2024-03-29

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report here. More info >

Plate changes

See in this check if this VOLVO had different number plates.

More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 10 |
| First mileage registration | 2015-01-29 |
| Last registration | 2023-09-07 |
| Complete history | See info |



| Registration #1 | 2015-01-29 | 20 mi |
|-----------------|------------|-----------|
| Registration #2 | 2018-01-23 | 32.524 mi |
| Registration #3 | 2018-02-01 | 32.600 mi |
| Registration #4 | 2019-01-30 | 39.243 mi |
| Registration #5 | 2020-01-27 | 44.679 mi |
| Registration #6 | | 11.777 es |
| Registration #7 | | |
| | | |
| Registration #8 | | 0.074 |
| | | 11.77 m |

More info >

CarCheck.co.uk page 10/11



Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 94% |
| Children | 79% |
| Pedestrian | 48% |
| Safety systems | 86% |
| Overall rating | 81% |
| Video | see crash video |



Dimensions & weight

| Width | 2119 mm |
|---------------------|---------|
| Height | 1604 mm |
| Length | 4838 mm |
| Wheel base | 2815 mm |
| Kerb weight | 1885 kg |
| Max. allowed weight | 2400 kg |

Additional information

| Fuel tank capacity | 70 I |
|-----------------------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 11/1 |

Number of axles 2

Engine number 1556624