



PEUGEOT



report date: 2024-03-28

General information

Make	PEUGEOT
Model	307 S HDI (90BHP)
Colour	Blue
Year of manufacture	-
Top speed	108 mph
0 - 60 mph	13.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	205 Nm at 1.900 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	39.8 mpg
Consumption extra urban	62.8 mpg
Consumption combined	52.3 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-09
Pictures	5
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

**MOT history****MOT #17** 2020-11-18 11:48**MOT test number** 312692087701**Result** ✓ Passed**Next expiry date** 2021-11-21**Advice** Rear exhaust box deteriorated**Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened NS/OS (1.1.14 (a) (ii))**Advice** Rear Tyre worn close to legal limit/worn on edge NS/OS (5.2.3 (e))**MOT #16** 2019-05-22 14:30**MOT test number** 928244670305**Result** ✓ Passed**Advice** Rear exahust poor**Advice** Both front tyres perished**Advice** Front tyres near limit**Advice** Both rear shocker bushes perished

**MOT #15**

2019-05-13 13:03

**MOT test number**

235066783798

**Result**

✗ Failed

- Fail** Indicator switch inoperative (4.4.2 (a) (ii))
- Fail** Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Both rear shocker bushes perished
- Fail** Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength outer sill (5.3.6 (a) (i))
- Advice** Rear exhaust poor
- Fail** Offside Seat belt anchorage prescribed area strength or continuity significantly reduced mid outer sill (7.1.1 (a) (i))
- Fail** Front Windscreen washer provides insufficient washer liquid (3.5 (a))
- Fail** Nearside Front Brake hose excessively chafed (1.1.12 (b) (ii))
- Fail** Nearside Front Headlamp aim too low (4.1.2 (a))
- Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail** Nearside Rear Suspension component mounting prescribed area excessively damaged significantly reducing structural strength outer sill (5.3.6 (a) (i))
- Advice** Both front tyres perished
- Fail** Seat belt anchorage prescribed area strength or continuity significantly reduced mid outer sill (7.1.1 (a) (i))
- Fail** Nearside Front Steering rack has excessive free play detected at the steering wheel (steering rack fitted) (2.3 (a) (i))

**MOT #14**

2016-07-21 09:50

**MOT test number**

412834024446

**Result**

✓ Passed

- Advice** Oil leak
- Advice** Rear exhaust bracket is corroded
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



**MOT #13** 2015-08-10 15:36**MOT test number** 447872125279**Result** ✓ Passed**Notice** Both rear shock lower bushes deteriorating**Notice** Rear box bracket corroded**Notice** Play in steering rack inner joint(s)**MOT #12** 2015-08-10 11:12**MOT test number** 278282725236**Result** ✗ Failed**Fail** Nearside Side repeater incorrect colour (1.4.A.2f)**Notice** Rear box bracket corroded**Fail** Nearside Front Direction indicator not working (1.4.A.2c)**Notice** Play in steering rack inner joint(s)**Fail** Offside Stop lamp not working (1.2.1b)**Notice** Both rear shock lower bushes deteriorating**MOT #11** 2014-08-11 11:11**MOT test number** 768733924203**Result** ✓ Passed**Notice** Play in steering rack inner joint(s)

**MOT #10** 2014-08-11 11:11**MOT test number** 568703624238**Result** ✗ Failed

- Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)
- Pass with rectification** Offside Windscreen washer provides insufficient washer liquid (8.2.3)
- Notice** Play in steering rack inner joint(s)
- Pass with rectification** Offside Headlamp aim too high (1.8)
- Pass with rectification** Nearside Windscreen washer provides insufficient washer liquid (8.2.3)

**MOT #9** 2013-08-19 11:03**MOT test number** 156091533207**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Slight play in near side of steering

**MOT #8** 2012-08-21 16:34**MOT test number** 947754232296**Result** ✓ Passed

- Advice** Nearside Track rod end ball joint has slight play (2.2.B.1f)

**MOT #7** 2011-09-23 12:04**MOT test number** 216646161216**Result** ✓ Passed

- Advice** Nearside Steering system has slight free play detected at steering wheel (2.2.A.1b)



MOT #6 2010-09-23 16:00

MOT test number 971226560211

Result ✗ Failed

**Notice** Rear seats in luggage compartment not fitted, unable to test seat belts.

**Advice** Nearside Front Side repeater slightly discoloured (1.4.A.2f)

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**Pass with rectification** Offside Rear Registration plate lamp not working (1.1.C.1d)

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #5 2010-09-23 16:00

MOT test number 124026460225

Result ✓ Passed

**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Notice** Rear seats in luggage compartment not fitted, unable to test seat belts.

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**Advice** Nearside Front Side repeater slightly discoloured (1.4.A.2f)

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #4 2009-09-26 12:06

MOT test number 820289569221

Result ✓ Passed





MOT #3	2008-07-07 17:32
MOT test number	232239588185
Result	✓ Passed

MOT #2	2008-07-07 11:56
MOT test number	231459388423
Result	✗ Failed
<div><div>Fail</div>Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)</div>	

MOT #1	2007-05-30 15:12
MOT test number	391130857126
Result	✓ Passed



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-28
Current registration	*****
Plate since	2023-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2004-06-30
Last registration	2020-11-18
Complete history	<a href="#">See info</a>



Registration #1	2004-06-30	29 mi
Registration #2	2007-05-30	29.612 mi
Registration #3	2008-07-07	44.063 mi
Registration #4	2008-07-07	44.063 mi
Registration #5	2009-09-26	51.060 mi
Registration #6	2010-09-23	58.465 mi
Registration #7	2011-09-23	67.017 mi
Registration #8	2012-08-21	74.356 mi
Registration #9	2013-08-19	82.262 mi
Registration #10	2014-08-19	90.168 mi
Registration #11	2015-08-19	98.074 mi
Registration #12	2016-08-19	105.980 mi
Registration #13	2017-08-19	113.886 mi
Registration #14	2018-08-19	121.792 mi
Registration #15	2019-08-19	129.698 mi
Registration #16	2020-08-19	137.604 mi
Registration #17	2021-08-19	145.510 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1757 mm
Height	1544 mm
Length	4419 mm
Wheel base	2708 mm
Kerb weight	1328 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

**Engine number**

DYSG3047296