



report date: 2024-03-29

General information

Make	FIAT
Model	PUNTO ACTIVE
Colour	Black
Year of manufacture	2010
Top speed	103 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.250 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	49.6 mpg
CO2 emission	132 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-10-02
Pictures	1



source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-25
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	42
Total items failed	11

MOT #18	2024-03-26 16:09
---------	------------------

MOT test number	496326144292
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2025-03-25
------------------	------------

- AdviceCoolant leak
- AdviceOffside Rear Coil spring corroded (5.3.1 (b) (i))
- AdviceNearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- AdviceNearside Rear Coil spring corroded (5.3.1 (b) (i))
- AdviceExhaust has a minor leak of exhaust gases (6.1.2 (a))
- AdviceOffside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- AdviceOffside Front Coil spring corroded (5.3.1 (b) (i))

**MOT #17**

2024-03-20 17:26

**MOT test number**

593807245809

**Result****✗ Failed**

- Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Coolant leak
- Advice** Park brake 17% efficiency only just met. Appears braking system requires adjustment or repair
- Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #16**

2024-03-18 16:02

**MOT test number**

224018154539

**Result****✗ Failed**

- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
- Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Rear Exhaust has a minor leak of exhaust gases back box (6.1.2 (a))
- Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #15** 2023-03-16 16:12**MOT test number** 522517500104**Result** ✓ Passed**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**MOT #14** 2022-03-19 10:10**MOT test number** 815827296839**Result** ✓ Passed**MOT #13** 2021-03-03 10:41**MOT test number** 465455055061**Result** ✓ Passed**MOT #12** 2020-03-17 13:46**MOT test number** 798681371273**Result** ✓ Passed**MOT #11** 2020-03-17 10:03**MOT test number** 705145943615**Result** ✗ Failed**Fail** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Shock absorbers likely to become detached TOP MOUNTINGS LOOSE? ,RATTLING NOISE ON REAR SUSPENSION (5.3.2 (a) (ii))**Fail** Offside Front Direction indicator incorrect colour (4.4.3 (a))

**MOT #10**

2019-05-28 11:11

**MOT test number**

677011054764

**Result**

✓ Passed

- Advice** Both rear shocker casings corroded
- Advice** Rear Brake hose has slight corrosion to ferrule both (1.1.12 (f) (i))
- Advice** Rear Coil spring corroded both (5.3.1 (b) (i))

**MOT #9**

2018-06-12 11:40

**MOT test number**

295850571613

**Result**

✓ Passed

- Advice** Front tyres wearing on edges
- Advice** Offside Front Tyre worn close to legal limit/worn on edge 2.4mm (5.2.3 (e))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2.4mm (5.2.3 (e))
- Advice** Rear exhaust outer skin corroded but not blowing
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #8**

2017-06-19 11:12

**MOT test number**

502999571793

**Result**

✓ Passed

- Advice** Nearside Rear coil spring corroded (2.4.C.1b)
- Advice** Rear exhaust silencer outer skin corroded but not blowing
- Advice** Rear Brake hose has slight corrosion to ferrules both (3.6.B.4e)
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**MOT #7** 2017-06-19 08:47**MOT test number** 261185343795**Result** ✗ Failed**Advice** Rear Brake hose has slight corrosion to ferrules both (3.6.B.4e)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Fail** Offside Front coil spring broken (2.4.C.1a)**Advice** Nearside Rear coil spring corroded (2.4.C.1b)**Advice** Rear exhaust silencer outer skin corroded but not blowing**MOT #6** 2016-06-20 09:06**MOT test number** 103687559417**Result** ✓ Passed**Advice** Both rear tyre walls cracking**Advice** Rear exhaust silencer outer skin corroded but not blowing**MOT #5** 2015-06-22 10:37**MOT test number** 466163875109**Result** ✓ Passed**MOT #4** 2015-06-22 10:37**MOT test number** 328413275180**Result** ✗ Failed**Pass with rectification** Nearside Steering rack gaiter insecure (2.2.D.2d)**Pass with rectification** Offside Steering rack gaiter insecure (2.2.D.2d)**MOT #3** 2014-06-23 15:53**MOT test number** 688004674160**Result** ✓ Passed



MOT #2	2014-06-23 09:28
MOT test number	949034674101
Result	✗ Failed
<div><div>Fail</div>Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)</div>	

MOT #1	2013-06-24 13:24
MOT test number	186775973148
Result	✓ Passed





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
25 March 2025

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	154
<b>MOT expiry date</b>	25 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-06-30
Last registration	2024-03-26
Complete history	<a href="#">See info</a>



Registration #1	2010-06-30	28 mi
Registration #2	2013-06-24	18.262 mi
Registration #3	2014-06-23	26.237 mi
Registration #4	2014-06-23	26.237 mi
Registration #5	2015-06-22	33.082 mi
Registration #6	2016-06-20	37.549 mi
Registration #7	2017-06-19	42.968 mi
Registration #8	2017-06-19	42.968 mi
Registration #9	2018-06-12	47.818 mi
Registration #10	2019-05-28	52.634 mi
Registration #11	2019-05-28	52.634 mi
Registration #12	2019-05-28	52.634 mi
Registration #13	2019-05-28	52.634 mi
Registration #14	2019-05-28	52.634 mi
Registration #15	2019-05-28	52.634 mi
Registration #16	2019-05-28	52.634 mi
Registration #17	2019-05-28	52.634 mi
Registration #18	2019-05-28	52.634 mi
Registration #19	2019-05-28	52.634 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1040 kg
Max. allowed weight	1600 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	5839116