





report date: 2024-03-29

General information

Make	MAZDA
Model	MX-5 SE-L NAV
Colour	Black
Year of manufacture	2015
Top speed	133 mph
0 - 60 mph	7.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	158 BHP
Max. torque	200 Nm at 4.600 rpm
Engine capacity	1.998 сс
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	51.4 mpg
Consumption combined	40.9 mpg
CO2 emission	161 g/km
CO2 label	G



CarCheck.co.uk page 1/11



Internet history

Entry 2

Date 2021-09-17

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date 2021-09-16

Pictures 38

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-11-29
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	17
Total items failed	0

MOT #7		2023-11-29 15:52
MOT test	number	888323099888
Result		✓ Passed
Next expi	y date	2024-11-29
Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))		
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #6)23-11-28 13:59
MOT test	number	434999372804
Result		X Failed
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))	
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14	l (a) (ii))
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
MAJOR	Nearside Rear Service brake excessively binding (1.2.1 (f))	
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

CarCheck.co.uk page 3/11



MOT #5 2022-11-29 12:08

MOT test number 799779439114

Result \rightarrow Passed

Advice

Rear Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))

MOT #4 2021-11-30 16:22

MOT test number 760504679895

Result \(\sqrt{Passed} \)

MOT #3 2020-10-19 11:27

MOT test number 927245852619

Advice Front Tyre worn close to legal limit/worn on edge both 3mm (205/45 R17 88W) (5.2.3 (e))

Advice Offside Front Nail in tyre

Advice Rear Tyre worn close to legal limit/worn on edge both 2mm (205/45 R17 88W) (5.2.3 (e))

Advice Offside Rear Nail in tyre

MOT #2 2019-10-15 08:49

MOT test number 641516254323

Result

Passed

MOT #1 2018-10-19 15:51

MOT test number 375648766860

Advice Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 4/11





Tax & MOT check





Expires: 29 November 2024

Tax status	Valid until 1 December
Days left	215
MOT expiry date	29 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

e union mestery	
For how long did the current and previous owner(s) have this MAZDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full it	

	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	,
Current registration	NK SIK
Plate since	
Current registration	NK SIN
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-10-20
Last registration	2023-11-29
Complete history	See info



Registration #1	2015-10-20	27 mi
Registration #2	2018-10-19	44.155 mi
Registration #3	2019-10-15	56.112 mi
Registration #4	2020-10-19	62.555 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es

More info >

CarCheck.co.uk page 10/11



Safety ratings

NCAP rating	***
Adult	84%
Children	80%
Pedestrian	93%
Safety systems	64%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1735 mm
Height	1230 mm
Length	3915 mm
Wheel base	2310 mm
Kerb weight	1000 kg
Max. allowed weight	1260 kg

Additional information

Fuel tank capacity	45 I
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	PE 30817606

CarCheck.co.uk page 11/11