



PEUGEOT




report date: 2024-03-28

General information

Make	PEUGEOT
Model	207 CC SPORT
Colour	Silver
Year of manufacture	2011
Top speed	118 mph
0 - 60 mph	10.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	160 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	53.3 mpg
Consumption combined	43.5 mpg
CO2 emission	149 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-02-03
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-05-16
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	31
Total items failed	3

MOT #13	2023-05-12 13:15
MOT test number	640411311762
Result	✓ Passed
Next expiry date	2024-05-16
Advice	Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened inner faces (1.1.14 (a) (ii))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge also cracking (5.2.3 (e))

MOT #12	2023-05-12 09:14
MOT test number	186176886315
Result	✗ Failed
DANGEROUS	Offside Front Tyre has ply or cords exposed outer wall (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge also cracking (5.2.3 (e))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened inner faces (1.1.14 (a) (ii))
Advice	Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #11** 2022-05-16 08:47**MOT test number** 439244181468**Result** ✓ Passed**Advice** Offside Front Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Brake pad(s) wearing thin Both front. (1.1.13 (a) (ii))**Advice** Exhaust has a minor leak of exhaust gases Centre pipe to rear box. (6.1.2 (a))**MOT #10** 2021-05-17 15:26**MOT test number** 587574442905**Result** ✓ Passed**Advice** Nearside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))**MOT #9** 2021-01-06 12:59**MOT test number** 612790034343**Result** ✓ Passed**Advice** Nearside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Exhaust mounting defective (6.1.2 (a))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Central Rear Exhaust mounting defective (6.1.2 (a))

**MOT #8** 2021-01-06 12:59**MOT test number** 978129971281**Result** ✗ Failed**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Central Rear Exhaust mounting defective (6.1.2 (a))**Advice** Nearside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Exhaust mounting defective (6.1.2 (a))**Pass with rectification** Nearside Front Headlamp aim too high (4.1.2 (a))**MOT #7** 2019-06-26 15:25**MOT test number** 253192996095**Result** ✓ Passed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #6** 2019-06-26 15:24**MOT test number** 723906336007**Result** ✗ Failed**Pass with rectification** Front Exhaust system insecure (6.1.2 (a))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Pass with rectification** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #5** 2018-07-04 16:20**MOT test number** 161134173438**Result** ✓ Passed

**MOT #4** 2017-06-28 14:23**MOT test number** 141690946716**Result** ✓ Passed**Advice** Offside Front tyre worn on inner and outer edges**Advice** Offside Rear tyre starting to crack**MOT #3** 2016-07-04 14:51**MOT test number** 430918775880**Result** ✓ Passed**Advice** Corrosion to rear exhaust mounting bracket**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2015-07-06 10:46**MOT test number** 927897985189**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2014-06-05 12:12**MOT test number** 826016454143**Result** ✓ Passed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 May 2025

✓  
**MOT**  
**Expires:**  
16 May 2024

<b>Tax status</b>	Valid until 1 May
<b>Days left</b>	367
<b>MOT expiry date</b>	16 May 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-06-30
Last registration	2023-05-12
Complete history	<a href="#">See info</a>



Registration #1	2011-06-30	12 mi
Registration #2	2014-06-05	18.004 mi
Registration #3	2015-07-06	23.988 mi
Registration #4	2016-07-04	28.940 mi
Registration #5	2017-06-28	33.883 mi
Registration #6	2018-07-04	37.949 mi
Registration #7	2019-06-26	42.776 mi
Registration #8	2019-06-26	42.776 mi
Registration #9	2019-06-26	42.776 mi
Registration #10	2019-06-26	42.776 mi
Registration #11	2019-06-26	42.776 mi
Registration #12	2019-06-26	42.776 mi
Registration #13	2019-06-26	42.776 mi
Registration #14	2019-06-26	42.776 mi
Registration #15	2019-06-26	42.776 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1972 mm
Height	1387 mm
Length	4037 mm
Wheel base	2540 mm
Kerb weight	1417 kg
Max. allowed weight	1709 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4

<b>Number of axles</b>	2
<b>Engine number</b>	FHCA1105552