



Mercedes-Benz



report date: 2024-03-29

General information

Make	MERCEDES
Model	ML ML 280 CDI SPORT
Colour	Black
Year of manufacture	2009
Top speed	127 mph
0 - 60 mph	9.8 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	188 BHP
Max. torque	440 Nm at 2.800 rpm
Engine capacity	2.987 cc
Cylinders	6
Fuel type	Diesel
Consumption city	21.9 mpg
Consumption extra urban	35.3 mpg
Consumption combined	28.8 mpg
CO2 emission	254 g/km
CO2 label	L






Internet history

Entry 2

Date	2021-02-02
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)

Entry 1

Date	2021-02-02
Pictures	1
Listing price	View report



source: [autoonline.co.uk](#)

**MOT history**

MOT expiry date	2025-02-24
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	29
Total items failed	13

MOT #18 2024-02-22 13:38**MOT test number** 682370151764**Result** ✓ Passed**Next expiry date** 2025-02-24

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
Rear Bush (5.3.4 (a) (i))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
Rear Bush (5.3.4 (a) (i))

MOT #17 2023-02-25 08:49**MOT test number** 205181237296**Result** ✓ Passed

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
Rear Bush (5.3.4 (a) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
Rear Bush (5.3.4 (a) (i))

MOT #16 2022-02-11 11:05**MOT test number** 424029252244**Result** ✓ Passed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))



MOT #15	2021-02-19 15:51
MOT test number	999849375162
Result	✓ Passed
Minor	Windscreen damaged but not adversely affecting driver's view chip (3.2 (a) (i))

MOT #14	2021-02-17 07:56
MOT test number	373207584786
Result	✗ Failed
Fail	Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Fail	Nearside Rear Service brake excessively binding (1.2.1 (f))
Fail	Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
Minor	Windscreen damaged but not adversely affecting driver's view chip (3.2 (a) (i))
Fail	Nearside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))
Advice	Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #13	2020-06-18 13:41
MOT test number	352612792405
Result	✓ Passed

MOT #12	2020-06-18 13:41
MOT test number	217455278342
Result	✗ Failed
Pass with rectification	Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
Pass with rectification	Offside Rear Direction indicator not working (4.4.1 (a) (ii))

MOT #11	2019-07-05 10:34
MOT test number	254051870864
Result	✓ Passed

**MOT #10** 2018-06-13 15:23**MOT test number** 860789226145**Result** ✓ Passed**MOT #9** 2018-06-13 09:01**MOT test number** 373318982631**Result** ✗ Failed**Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Fail** Nearside Front Side repeater not working (4.4.1 (a) (ii))**MOT #8** 2017-06-16 10:35**MOT test number** 760834669850**Result** ✓ Passed**MOT #7** 2016-06-25 10:32**MOT test number** 455770886215**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit 2.MM (4.1.E.1)**MOT #6** 2015-11-23 14:04**MOT test number** 495605835386**Result** ✓ Passed**Advice** Child seat fitted to rear**Advice** N/s/f tyre outer edge worn

**MOT #5** 2015-11-23 11:56**MOT test number** 213564379251**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Child seat fitted to rear**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #4** 2014-11-27 13:49**MOT test number** 488071334420**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Oil leak**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #3** 2013-11-14 16:06**MOT test number** 606938913340**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Nail in offside rear tyre



MOT #2	2013-11-14 15:44
MOT test number	398958413352
Result	✗ Failed
Fail	Offside Rear Direction indicator incorrect colour (1.4.A.2f)
Notice	Child seat fitted not allowing full inspection of adult belt
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Fail	Nearside Rear Direction indicator incorrect colour (1.4.A.2f)
Fail	Emissions not tested (7.0)
Notice	Nail in offside rear tyre
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2012-06-13 11:16
MOT test number	296795862457
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
24 February 2025

Tax status	Valid until 1 February
Days left	278
MOT expiry date	24 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 W20SJA
Plate since	2024-03-29
Current registration	 W20SJA
Plate since	2024-03-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2009-06-30
Last registration	2024-02-22
Complete history	See info



Registration #1	2009-06-30	10 mi
Registration #2	2012-06-13	35.872 mi
Registration #3	2013-11-14	45.048 mi
Registration #4	2013-11-14	45.048 mi
Registration #5	2014-11-27	52.316 mi
Registration #6	2015-11-23	59.441 mi
Registration #7	2015-11-23	59.450 mi
Registration #8	2016-06-25	62.610 mi
Registration #9	2017-06-16	70.762 mi
Registration #10	2018-06-13	78.968 mi
Registration #11	2018-06-13	78.969 mi
Registration #12	2019-06-13	87.175 mi
Registration #13	2019-06-13	87.177 mi
Registration #14	2019-06-13	87.177 mi
Registration #15	2019-06-13	87.177 mi
Registration #16	2019-06-13	87.177 mi
Registration #17	2019-06-13	87.177 mi
Registration #18	2019-06-13	87.177 mi
Registration #19	2019-06-13	87.177 mi
Registration #20	2019-06-13	87.177 mi
Registration #21	2019-06-13	87.177 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1911 mm
Height	1884 mm
Length	4780 mm
Wheel base	2915 mm

Additional information

Fuel tank capacity	95 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	64294040785848