




report date: 2024-03-28

General information

Make	VAUXHALL
Model	MOVANO F3300 L2H2 P/V CDTi
Colour	White
Year of manufacture	2015
Gearbox	6 speed Manual

Engine & fuel consumption

Power	123 BHP
Max. torque	310 Nm at 2.500 rpm
Engine capacity	2.299 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.0 mpg
Consumption extra urban	39.8 mpg
Consumption combined	36.2 mpg
CO2 emission	207 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-07-10
Pictures	3
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-26
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	5
Total items failed	7

MOT #9	2023-08-22 12:28
MOT test number	200787539137
Result	✓ Passed
Next expiry date	2024-08-26

MOT #8	2023-08-18 10:13
MOT test number	315309036312
Result	✗ Failed
Fail	Offside Front Position lamp not working (4.2.1 (a) (ii))
Fail	Offside Front Windscreen washer not working (3.5 (a))
Fail	Nearside Front Windscreen washer not working (3.5 (a))
Minor	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #7	2022-08-20 10:40
MOT test number	692657686548
Result	✓ Passed

MOT #6	2021-08-27 06:30
MOT test number	503702368408
Result	✓ Passed

**MOT #5** 2020-11-02 16:13**MOT test number** 559654208666**Result** ✓ Passed**MOT #4** 2020-10-30 13:48**MOT test number** 651799428601**Result** ✗ Failed**Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Offside Headlamp aim not tested dip beam not working (4.1.2 (b))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #3** 2019-11-04 15:51**MOT test number** 799814055688**Result** ✓ Passed**Advice** Rear suspension sitting on bump stops**Advice** Exhaust bent and damaged**MOT #2** 2018-11-06 14:44**MOT test number** 612152297430**Result** ✓ Passed**MOT #1** 2018-11-06 11:32**MOT test number** 656372176717**Result** ✗ Failed**Advice** Offside Rear lens cluster broken**Fail** Nearside Rear Rear fog lamp does not emit a steady red light (4.5.4 (a))



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
26 August 2024

Tax status	Valid until 1 October
Days left	156
MOT expiry date	26 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	DU65GXP
Plate since	2019-06-29
Current registration	DU65GXP
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-10-06
Last registration	2023-08-22
Complete history	See info



Registration #1	2015-10-06	8 mi
Registration #2	2018-11-06	57.194 mi
Registration #3	2018-11-06	57.195 mi
Registration #4	2019-11-04	73.307 mi
Registration #5	2020-10-30	86.706 mi
Registration #6	2020-11-02	86.804 mi
Registration #7	2023-08-22	86.804 mi
Registration #8	2023-08-22	86.804 mi
Registration #9	2023-08-22	86.804 mi
Registration #10	2023-08-22	86.804 mi
Registration #11	2023-08-22	86.804 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	96%
Children	90%
Pedestrian	67%
Safety systems	100%
Overall rating	89%
Video	see crash video



Dimensions & weight

Width	2470 mm
Height	2500 mm
Length	5548 mm
Kerb weight	1885 kg
Max. allowed weight	3300 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	M9T -C136049 LWL