




report date: 2024-03-28

General information

Make	CITROEN
Model	GRAND C4 PICASSO HDI EXCLUSIVE EGS GRAND PICASSO
Colour	Red
Year of manufacture	2010
Top speed	112 mph
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	110 BHP
Max. torque	285 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	46.3 mpg
Consumption extra urban	57.7 mpg
Consumption combined	53.3 mpg
CO2 emission	139 g/km
CO2 label	E





MOT history

MOT expiry date	2024-11-05
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	43
Total items failed	13

MOT #16	2023-11-06 15:56
MOT test number	226325434582
Result	✓ Passed
Next expiry date	2024-11-05
Minor	Headlamp cleaning device inoperative (4.1.6 (a) (i))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #15	2023-11-04 11:14
MOT test number	873420627838
Result	✗ Failed
MAJOR	Battery insecure and likely to cause a short circuit (4.13 (a) (ii))
MAJOR	Offside Rear Service brake excessively binding (1.2.1 (f))
MAJOR	Parking brake efficiency below requirements (1.4.2 (a) (i))
MAJOR	Offside Front Headlamp light source and lamp not compatible (4.1.4 (c))
MAJOR	Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
Minor	Headlamp cleaning device inoperative (4.1.6 (a) (i))
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
MAJOR	Nearside Front Headlamp light source and lamp not compatible (4.1.4 (c))

**MOT #14**

2022-10-24 10:40

MOT test number

423189218365

Result

✓ Passed

Minor

Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Minor

Offside Rear Registration plate lamp throwing direct white light to the rear (4.7.1 (a))

MOT #13

2021-10-15 12:39

MOT test number

987284331182

Result

✓ Passed

MOT #12

2020-10-27 17:23

MOT test number

213329720047

Result

✓ Passed

Advice

Offside Lower Driver's door hinge deteriorated but the door can still be readily opened and closed (6.2.3 (c) (i))

Advice

Steering rack has slight free play detected at steering wheel (2.3 (a) (i))

Advice

Rear Brake pad(s) wearing thin Both sides. (1.1.13 (a) (ii))

Advice

Front Wheel hub spigot mounting slightly worn Both sides. (5.2.1 (b) (i))

Advice

Front Suspension arm pin or bush worn but not resulting in excessive movement Both sides. (5.3.4 (a) (i))

**MOT #11**

2020-10-27 17:23

MOT test number

386525688393

Result**✗ Failed****Pass with rectification** Nearside Front Seat belt installation anchorage insecure (10.1 (d))**Advice** Rear Brake pad(s) wearing thin Both sides. (1.1.13 (a) (ii))**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement Both sides. (5.3.4 (a) (i))**Advice** Front Wheel hub spigot mounting slightly worn Both sides. (5.2.1 (b) (i))**Advice** Offside Lower Driver's door hinge deteriorated but the door can still be readily opened and closed (6.2.3 (c) (i))**Advice** Steering rack has slight free play detected at steering wheel (2.3 (a) (i))**Pass with rectification** Front Registration plate insecure (0.1 (a))**MOT #10**

2019-02-13 12:08

MOT test number

560872783154

Result**✓ Passed****Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 215/50r17 (5.2.3 (e))**MOT #9**

2018-02-20 08:50

MOT test number

368188509732

Result**✓ Passed****Advice** Nearside Front Tyre worn close to the legal limit 215/50r17 (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit 2.5mm 215/50r17 (4.1.E.1)

**MOT #8** 2017-03-07 11:00**MOT test number** 342041101547**Result** ✓ Passed**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #7** 2016-03-09 14:51**MOT test number** 500053564279**Result** ✓ Passed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #6** 2016-03-08 15:04**MOT test number** 314137315509**Result** ✗ Failed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #5** 2015-03-03 13:46**MOT test number** 757732465031**Result** ✓ Passed

**MOT #4** 2015-02-20 14:00**MOT test number** 506851955080**Result** ✗ Failed**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Stop lamp not working (1.2.1b)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #3** 2014-02-26 15:32**MOT test number** 906867454094**Result** ✓ Passed**MOT #2** 2013-06-21 11:34**MOT test number** 586612373191**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Notice** Under-trays fitted obscuring some underside components**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Engine covers fitted obscuring some components in the engine bay



MOT #12013-06-20 14:37

MOT test number216221473158

Result		✗ Failed
Fail	Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Notice	Under-trays fitted obscuring some underside components	
Advice	Rear Brake pad(s) wearing thin (3.5.1g)	
Fail	Nearside Headlamp not working on dipped beam (1.7.5a)	
Advice	Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Notice	Engine covers fitted obscuring some components in the engine bay	
Fail	Windscreen washer provides insufficient washer liquid (8.2.3)	



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
5 November 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	5 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	WG60JJZ
Plate since	2019-09-28
Current registration	WG60JJZ
Plate since	2019-09-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-12-24
Last registration	2023-11-06
Complete history	See info



Registration #1	2010-12-24	28 mi
Registration #2	2013-06-20	40.498 mi
Registration #3	2013-06-21	40.959 mi
Registration #4	2014-02-26	47.524 mi
Registration #5	2015-02-20	63.005 mi
Registration #6	2015-03-03	63.486 mi
Registration #7	2016-03-08	81.615 mi
Registration #8	2016-03-09	81.615 mi
Registration #9	2017-03-07	91.200 mi
Registration #10	2018-03-07	101.200 mi
Registration #11	2018-03-07	101.200 mi
Registration #12	2018-03-07	101.200 mi
Registration #13	2018-03-07	101.200 mi
Registration #14	2018-03-07	101.200 mi
Registration #15	2018-03-07	101.200 mi
Registration #16	2018-03-07	101.200 mi
Registration #17	2018-03-07	101.200 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	85%
Pedestrian	43%
Safety systems	97%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1830 mm
Height	1710 mm
Length	4590 mm
Wheel base	2728 mm
Kerb weight	1520 kg
Max. allowed weight	2250 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	JBCJ3030006