



General information

Make	NISSAN
Model	370 Z V6 GT
Colour	Black
Year of manufacture	2012
Top speed	155 mph
0 - 60 mph	5.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	328 BHP
Max. torque	363 Nm at 5.200 rpm
Engine capacity	3.696 cc
Cylinders	6
Fuel type	Petrol
Consumption city	18.5 mpg
Consumption extra urban	35.8 mpg
Consumption combined	26.7 mpg
CO2 emission	248 g/km
CO2 label	L





Internet history

Entry 1

Date	2022-01-03
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-03-07
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	30
Total items failed	11

MOT #13	2024-03-08 12:27
MOT test number	429970016686
Result	✓ Passed
Next expiry date	2025-03-07

MOT #12	2024-03-07 15:54
MOT test number	139430155605
Result	✗ Failed
Fail	Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

MOT #11	2023-02-24 09:34
MOT test number	209651384978
Result	✓ Passed
Advice	Offside Rear Brake pipe corroded, covered in grease or other material flexi-caliper (1.1.11 (c))
Advice	Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material flexi-caliper (1.1.11 (c))
Advice	Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #10**

2022-01-28 13:54

MOT test number

439200732745

Result

✓ Passed

Advice Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Rear subframe corroded**MOT #9**

2022-01-25 15:43

MOT test number

793915029630

Result

✗ Failed

Advice Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Fail** Offside Front Brake pipe excessively corroded (1.1.11 (c))**Advice** Rear subframe corroded**Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))**Fail** Nearside Front Brake pipe excessively corroded (1.1.11 (c))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** TPMS light on

**MOT #8**

2022-01-19 09:05

MOT test number

430028468614

Result**✗ Failed**

- Fail** Offside Front Brake pipe excessively corroded Inner wing (1.1.11 (c))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Brake pipe excessively corroded Inner wing (1.1.11 (c))
- Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced Rear crossmember (6.1.1 (c) (i))

MOT #7

2021-03-11 09:01

MOT test number

327818882447

Result**✓ Passed**

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Various areas and components on underside corroded

**MOT #6** 2020-03-13 10:05**MOT test number** 665005654762**Result** ✓ Passed**Advice** Nearside Hydraulic leak, but not excessive Slight leak from N/S steering rack area. (8.4.1 (a) (i))**Advice** Unable to visually inspect front or rear brake pads due to caliper design.**Advice** Front Brake pipe corroded, covered in grease or other material Both front Brake pipes corroded, from Caliper to ABS unit. (1.1.11 (c))**MOT #5** 2019-03-28 15:29**MOT test number** 551321696736**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge on 2mm (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge on 3mm (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge on 2mm (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge on 3mm (5.2.3 (e))**MOT #4** 2018-03-30 08:40**MOT test number** 771300290984**Result** ✓ Passed**MOT #3** 2017-03-28 17:36**MOT test number** 844390119427**Result** ✓ Passed



MOT #2	2016-09-16 12:13
MOT test number	862549218166
Result	✓ Passed
Advice	Nearside wiper torn and streaky
Advice	Parking brake lever has little reserve travel (3.1.6b)
Advice	Bonnet catches nearside wing when opened

MOT #1	2015-09-08 15:41
MOT test number	524688135651
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
7 March 2025

Tax status	Valid until 1 January
Days left	248
MOT expiry date	7 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-28
Current registration	
Plate since	2019-09-28

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-09-29
Last registration	2024-03-08
Complete history	See info



Registration #1	2012-09-29	21 mi
Registration #2	2015-09-08	24.447 mi
Registration #3	2016-09-16	31.328 mi
Registration #4	2017-03-28	33.068 mi
Registration #5	2018-03-30	40.755 mi
Registration #6	2019-03-28	48.862 mi
Registration #7	2020-03-13	57.814 mi
Registration #8	2021-03-11	64.487 mi
Registration #9	2022-03-29	75.277 mi
Registration #10	2023-03-29	85.277 mi
Registration #11	2023-03-29	95.277 mi
Registration #12	2023-03-29	105.277 mi
Registration #13	2023-03-29	115.277 mi
Registration #14	2023-03-29	125.277 mi
Registration #15	2023-03-29	135.277 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1845 mm
Height	1315 mm
Length	4250 mm
Wheel base	2550 mm
Kerb weight	1496 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	72 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	2
Number of axles	2
Engine number	49199A