



RENAULT

SH60UXF

report date: 2024-03-28

General information

Make	RENAULT
Model	SCENIC DYNAMIQUE TOMTOM BOSE PACK DCI
Colour	Bronze
Year of manufacture	2011
Top speed	112 mph
0 - 100 km/h	12.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	78 kW / 106 HP / 110 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	48.7 mpg
Consumption extra urban	64.2 mpg
Consumption combined	57.7 mpg
CO2 emission	128 g/km
CO2 label	D





Internet history

Entry 2

Date	2023-07-28
Pictures	20
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date	2022-04-30
Pictures	12
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://www.cargurus.co.uk)



MOT history

MOT expiry date	2024-07-17
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	23
Total items failed	14

MOT #17	2023-07-18 10:57
MOT test number	729950102018
Result	✓ Passed
Next expiry date	2024-07-17
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Rear Brake disc worn, but not excessively both discs inner faces (1.1.14 (a) (i))

**MOT #16**

2023-07-17 13:05

**MOT test number**

850158002557

**Result****✗ Failed****Pass with rectification**

Nearside Headlamp aim too low (4.1.2 (a))

**Fail**

Offside Rear Brake pipe excessively corroded at brake hose by fuel tank (1.1.11 (c))

**Fail**

Offside Front Tyre has ply or cords exposed outer edge and treads low (5.2.3 (d) (ii))

**Advice**

Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**Advice**

Offside Rear Coil spring corroded (5.3.1 (b) (i))

**Fail**

Rear Exhaust system insecure clamp loose (6.1.2 (a))

**Fail**

Nearside Front Tyre has ply or cords exposed outer edge and treads on the legal limit (5.2.3 (d) (ii))

**Advice**

Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

**Advice**

Rear axle plastic trim loose and likely to become detached posing a risk to following vehicles

**Advice**

Rear Brake disc worn, but not excessively both discs inner faces (1.1.14 (a) (i))

**MOT #15**

2022-05-27 13:56

**MOT test number**

822647962057

**Result****✓ Passed****MOT #14**

2022-05-27 12:23

**MOT test number**

461127148134

**Result****✗ Failed****Fail**

Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

**Fail**

Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

**MOT #13**

2021-07-06 12:11

**MOT test number**

674505466595

**Result****✓ Passed**



<b>MOT #12</b>	2021-07-06 12:11
<b>MOT test number</b>	592121736187
<b>Result</b>	✗ Failed
<b>Pass with rectification</b>	Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

<b>MOT #11</b>	2020-08-05 08:57
<b>MOT test number</b>	809755999308
<b>Result</b>	✓ Passed

<b>MOT #10</b>	2019-10-18 08:15
<b>MOT test number</b>	881665162104
<b>Result</b>	✓ Passed
<b>Advice</b>	Both rear shocker casings corroding
<b>Advice</b>	Exhaust heat shield loose
<b>Advice</b>	Brake disc worn, but not excessively both front (1.1.14 (a) (i))

<b>MOT #9</b>	2019-10-16 13:25
<b>MOT test number</b>	649992221990
<b>Result</b>	✗ Failed
<b>Fail</b>	Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
<b>Fail</b>	Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
<b>Advice</b>	Brake disc worn, but not excessively both front (1.1.14 (a) (i))
<b>Advice</b>	Exhaust heat shield loose
<b>Fail</b>	Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
<b>Advice</b>	Both rear shocker casings corroding

**MOT #8** 2018-11-09 15:43**MOT test number** 688384845440**Result** ✓ Passed**Advice** Offside Front Lower Suspension component ball joint has slight play (5.3.4 (a) (i))**MOT #7** 2018-11-08 11:36**MOT test number** 781423666221**Result** ✗ Failed**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Front Lower Suspension component ball joint has slight play (5.3.4 (a) (i))**MOT #6** 2017-11-01 11:11**MOT test number** 115804154526**Result** ✓ Passed**Advice** Offside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**MOT #5** 2017-10-30 13:59**MOT test number** 471457055839**Result** ✗ Failed**Advice** Offside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**Fail** Nearside Rear Stop lamp not working (1.2.1b)**MOT #4** 2016-11-15 13:04**MOT test number** 577442071247**Result** ✓ Passed**Advice** Offside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)



MOT #3	2015-11-16 13:23
MOT test number	887894251781
Result	✓ Passed
Advice	Offside Drag link end ball joint has slight play (2.2.B.1f)
Advice	Offside Rear Direction indicator slightly discoloured (1.4.A.2f)
Advice	Front Brake pad(s) wearing thin (3.5.1g)

MOT #2	2014-11-18 10:36
MOT test number	135502624398
Result	✓ Passed
Notice	Both front tyres getting low

MOT #1	2013-11-18 13:38
MOT test number	434565433795
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
17 July 2024

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	94
<b>MOT expiry date</b>	17 July 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	D
<b>Single payment (12 months)</b>	£ 150,00,-
<b>Single six month payment</b>	£ 82,50,-
<b>Total payable by 12 monthly instalments</b>	£ 157,50,-





Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2011-01-08
Last registration	2023-07-18
Complete history	<a href="#">See info</a>



Registration #1	2011-01-08	8 mi
Registration #2	2013-11-18	6.974 mi
Registration #3	2014-11-18	22.114 mi
Registration #4	2015-11-16	37.353 mi
Registration #5	2016-11-15	55.327 mi
Registration #6	2017-10-30	68.244 mi
Registration #7	2017-11-01	68.244 mi
Registration #8	2018-11-08	79.148 mi
Registration #9	2018-11-09	79.148 mi
Registration #10	2019-10-16	90.769 mi
Registration #11	2019-10-16	90.769 mi
Registration #12	2019-10-16	90.769 mi
Registration #13	2019-10-16	90.769 mi
Registration #14	2019-10-16	90.769 mi
Registration #15	2019-10-16	90.769 mi
Registration #16	2019-10-16	90.769 mi
Registration #17	2019-10-16	90.769 mi
Registration #18	2019-10-16	90.769 mi
Registration #19	2019-10-16	90.769 mi
Registration #20	2019-10-16	90.769 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1486 mm
Height	1637 mm
Length	4344 mm
Wheel base	2703 mm
Kerb weight	1385 kg
Max. allowed weight	1944 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	D246598