



report date: 2024-03-29

General information

Make	NISSAN
Model	PRIMERA SE
Colour	Silver
Year of manufacture	2005
Top speed	119 mph
Gearbox	1 speed CVT

Engine & fuel consumption

Power	138 BHP
Max. torque	192 Nm at 4.000 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Petrol
Consumption city	23.7 mpg
Consumption extra urban	40.4 mpg
Consumption combined	32.1 mpg
CO2 emission	209 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-10-12
Pictures	10
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-02-14
MOT pass rate	82 %
MOT passed	18
Failed MOT tests	4
Total advice items	48
Total items failed	5

MOT #22	2024-02-15 12:59
---------	------------------

MOT test number	521331114027
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2025-02-14
------------------	------------

- Advice** Offside Front Side repeater slightly discoloured (4.4.3 (a))
- Advice** Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Handbrake requires adjustment
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Side repeater slightly discoloured (4.4.3 (a))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Front Play in steering rack inner joint(s)
- Advice** Rear Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

**MOT #21**

2024-02-15 12:59

MOT test number

226185257552

Result**✗ Failed**

- Advice** Rear Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Nearside Front Play in steering rack inner joint(s)
- Pass with rectification** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Offside Front Side repeater slightly discoloured (4.4.3 (a))
- Advice** Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Offside Front Side repeater slightly discoloured (4.4.3 (a))
- Advice** Handbrake requires adjustment
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

MOT #20

2023-04-11 14:30

MOT test number

336036899722

Result**✓ Passed**

- Advice** Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #19**

2023-03-15 10:43

MOT test number

820194095336

Result**✗ Failed****MAJOR** Nearside Front Service brake excessively binding (1.2.1 (f))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**DANGEROUS** Nearside Front Anti-roll bar linkage fractured drop link (5.3.3 (b) (ii))**Advice** Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))**MAJOR** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**Advice** Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))**MOT #18**

2022-03-30 13:11

MOT test number

526061186450

Result**✓ Passed****Advice** Offside Front Power steering component has slight seepage from a component rack (2.1.5 (a))**Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**MOT #17**

2021-04-06 09:15

MOT test number

417599820908

Result**✓ Passed****MOT #16**

2020-03-25 09:16

MOT test number

105000856016

Result**✓ Passed****Advice** Surface corrosion to inner sills and suspension arms

**MOT #15** 2019-04-01 09:08**MOT test number** 394656008382**Result** ✓ Passed**Advice** Wiper blades in poor condition**Advice** Poor washer aim**MOT #14** 2018-04-13 10:39**MOT test number** 685116269905**Result** ✓ Passed**MOT #13** 2017-04-12 10:07**MOT test number** 375415481440**Result** ✓ Passed**MOT #12** 2016-04-07 11:04**MOT test number** 831892687914**Result** ✓ Passed**MOT #11** 2015-03-25 09:35**MOT test number** 159464585461**Result** ✓ Passed**MOT #10** 2014-04-16 10:00**MOT test number** 149686704100**Result** ✓ Passed**Notice** Front tyres worn on inside edges**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Notice** Poor washer aim**Advice** Nearside Front Lower Suspension arm synthetic bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #9** 2013-04-09 15:08**MOT test number** 926219193079**Result** ✓ Passed

Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #8 2013-04-04 12:21**MOT test number** 477744393073**Result** ✗ Failed

Advice Rear Exhaust has a minor leak of exhaust gases (7.1.2)

Fail Brakes imbalanced across an axle (3.7.B.5b)

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

Fail Offside front brake binding (3.7.B.1)

Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #7 2013-01-07 12:27**MOT test number** 107697503493**Result** ✓ Passed

Advice Exhaust has a minor leak of exhaust gases (7.1.2)

Advice Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

Advice Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #6 2012-01-11 12:22**MOT test number** 797771312084**Result** ✓ Passed

**MOT #5** 2012-01-09 09:48**MOT test number** 869359402053**Result** ✗ Failed**Fail** Offside Stop lamp not working (1.2.1b)**Advice** Offside Front Anti-roll bar has slight play in a ball joint (2.4.G.2)**Fail** Offside Track rod end ball joint has excessive play (2.2.B.1f)**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #4** 2011-01-07 09:42**MOT test number** 476327001071**Result** ✓ Passed**MOT #3** 2010-01-04 11:34**MOT test number** 551644800021**Result** ✓ Passed**Notice** Wipers starting to split at ends but are clearing Ok. Early replacement recommended**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #2** 2009-01-06 09:59**MOT test number** 372406109046**Result** ✓ Passed**MOT #1** 2008-01-11 11:07**MOT test number** 213001218022**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
14 February 2025

Tax status	Valid until 1 October
Days left	154
MOT expiry date	14 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2005-01-12
Last registration	2024-02-15
Complete history	See info



Registration #1	2005-01-12	28 mi
Registration #2	2008-01-11	26.813 mi
Registration #3	2009-01-06	25.539 mi
Registration #4	2010-01-04	36.910 mi
Registration #5	2011-01-07	41.409 mi
Registration #6	2012-01-09	45.700 mi
Registration #7	2012-01-11	45.700 mi
Registration #8	2013-01-07	50.546 mi
Registration #9	2013-04-04	51.278 mi
Registration #10	2013-04-09	51.278 mi
Registration #11	2014-04-16	53.589 mi
Registration #12	2015-03-25	54.942 mi
Registration #13	2015-05-20	55.277 mi
Registration #14	2015-05-20	55.277 mi
Registration #15	2015-05-20	55.277 mi
Registration #16	2015-05-20	55.277 mi
Registration #17	2015-05-20	55.277 mi
Registration #18	2015-05-20	55.277 mi
Registration #19	2015-05-20	55.277 mi
Registration #20	2015-05-20	55.277 mi
Registration #21	2015-05-20	55.277 mi
Registration #22	2015-05-20	55.277 mi
Registration #23	2015-05-20	55.277 mi
Registration #24	2015-05-20	55.277 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1760 mm
Height	1488 mm
Length	4567 mm
Wheel base	2680 mm
Kerb weight	1399 kg
Max. allowed weight	1910 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	537304