



RENAULT



report date: 2024-03-28

General information

Make	RENAULT
Model	KANGOO EXPRESSION 16V
Colour	Green
Year of manufacture	2005
Top speed	101 mph
0 - 60 mph	12.4 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	95 BHP
Max. torque	148 Nm at 3.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.7 mpg
Consumption extra urban	44.8 mpg
Consumption combined	35.3 mpg
CO2 emission	190 g/km
CO2 label	J





Internet history

Entry 2

Date	2022-12-17
Pictures	50
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date	2022-06-21
Pictures	50
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://www.cargurus.co.uk)



## MOT history

MOT expiry date	2024-12-13
MOT pass rate	73 %
MOT passed	16
Failed MOT tests	6
Total advice items	19
Total items failed	21

MOT #22 2023-12-13 12:09

MOT test number 821007757063

Result ✓ Passed

Next expiry date 2024-12-13

- Advice** Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Oil leak, but not excessive engine (8.4.1 (a) (i))

MOT #21 2022-12-14 13:22

MOT test number 953725524327

Result ✓ Passed

- Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #20**

2022-12-13 12:52

**MOT test number**

332609772627

**Result****✗ Failed****Fail**

Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

**Minor**

Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice**

Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Fail**

Nearside Front Anti-roll bar linkage damaged and seriously weakened (5.3.3 (b) (i))

**Fail**

Offside Front Inner Brake disc contaminated (1.1.14 (b))

**Fail**

Offside Front Inner Tyre has ply or cords damaged (5.2.3 (d) (ii))

**Fail**

Offside Front Anti-roll bar linkage damaged and seriously weakened (5.3.3 (b) (i))

**Advice**

Nearside Rear Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice**

Front Upper Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #19**

2021-07-28 14:09

**MOT test number**

218200783643

**Result****✓ Passed****MOT #18**

2021-07-21 15:56

**MOT test number**

188278482136

**Result****✗ Failed****Fail**

Rear Brakes imbalanced across an axle (1.2.1 (b) (i))

**Fail**

Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))

**Fail**

Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #17** 2020-07-22 15:38**MOT test number** 404864811839**Result** ✓ Passed**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**MOT #16** 2019-03-29 11:01**MOT test number** 299756575827**Result** ✓ Passed**MOT #15** 2019-03-25 17:15**MOT test number** 746572452949**Result** ✗ Failed**Fail** Nearside Front Position lamp not working (4.2.1 (a))**Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Minor** Nearside Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**MOT #14** 2018-03-29 16:17**MOT test number** 962474263681**Result** ✓ Passed**Advice** Parking brake lever has little reserve travel (3.1.6b)**MOT #13** 2017-03-28 11:44**MOT test number** 191470906366**Result** ✓ Passed**Advice** Both rear tyres deteriorated**Advice** Nearside Front Anti-roll bar linkage rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #12** 2017-03-17 13:07**MOT test number** 140503061563**Result** ✗ Failed**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**Fail** Nearside Front Suspension arm has excessive play in a ball joint (2.4.G.2)**Fail** Power steering fluid level below minimum (2.3.1)**Advice** Both rear tyres deteriorated**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Front Anti-roll bar linkage rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #11** 2016-03-31 13:54**MOT test number** 212196320385**Result** ✓ Passed**MOT #10** 2016-03-31 12:27**MOT test number** 258625011668**Result** ✗ Failed**Fail** Offside Front Track rod end ball joint has excessive play (2.2.B.1f)**Fail** Offside Front Tyre has a bulge, caused by separation or partial failure of its structure tread out of shape (4.1.D.1b)**MOT #9** 2015-03-10 10:28**MOT test number** 267199365022**Result** ✓ Passed**MOT #8** 2014-03-24 11:44**MOT test number** 165663084030**Result** ✓ Passed



<b>MOT #7</b>	2014-03-18 17:11
<b>MOT test number</b>	879907774068
<b>Result</b>	✗ Failed
<b>Fail</b>	Nearside Registration plate lamp not working (1.1.C.1d)
<b>Fail</b>	Front brake disc in such a condition that it is seriously weakened (3.5.1i)
<b>Fail</b>	Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
<b>MOT #6</b>	2013-07-11 14:28
<b>MOT test number</b>	557312293117
<b>Result</b>	✓ Passed
<b>MOT #5</b>	2012-07-03 15:28
<b>MOT test number</b>	956565582142
<b>Result</b>	✓ Passed
<b>MOT #4</b>	2011-07-06 12:00
<b>MOT test number</b>	229977481430
<b>Result</b>	✓ Passed
<b>MOT #3</b>	2010-07-15 09:02
<b>MOT test number</b>	181996090173
<b>Result</b>	✓ Passed
<b>MOT #2</b>	2009-07-10 09:24
<b>MOT test number</b>	172691299123
<b>Result</b>	✓ Passed
<b>MOT #1</b>	2008-07-23 09:24
<b>MOT test number</b>	482045808270
<b>Result</b>	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
13 December 2024

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	337
<b>MOT expiry date</b>	13 December 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	J
<b>Single payment (12 months)</b>	£ 365,00,-
<b>Single six month payment</b>	£ 200,75,-
<b>Total payable by 12 monthly instalments</b>	£ 383,25,-





Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	YK55WNZ
Plate since	2019-09-28
Current registration	YK55WNZ
Plate since	2019-09-28

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT FINANCE
Date of agreement	2024-03-28
Agreement type	RENT TO BUY
Agreement term	36 months
Agreement number	123456789
Contact info	01234 567890

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2005-09-13
Last registration	2023-12-13
Complete history	<a href="#">See info</a>



Registration #1	2005-09-13	15 mi
Registration #2	2008-07-23	8.802 mi
Registration #3	2009-07-10	15.356 mi
Registration #4	2010-07-15	22.860 mi
Registration #5	2011-07-06	29.771 mi
Registration #6	2012-07-03	37.371 mi
Registration #7	2013-07-11	41.606 mi
Registration #8	2014-03-18	44.488 mi
Registration #9	2014-03-24	44.488 mi
Registration #10	2015-03-10	51.644 mi
Registration #11	2016-03-31	55.387 mi
Registration #12	2016-03-31	55.387 mi
Registration #13	2017-03-17	58.887 mi
Registration #14	2018-03-20	61.337 mi
Registration #15	2018-03-20	61.337 mi
Registration #16	2018-03-20	61.337 mi
Registration #17	2018-03-20	61.337 mi
Registration #18	2018-03-20	61.337 mi
Registration #19	2018-03-20	61.337 mi
Registration #20	2018-03-20	61.337 mi
Registration #21	2018-03-20	61.337 mi
Registration #22	2018-03-20	61.337 mi
Registration #23	2018-03-20	61.337 mi
Registration #24	2018-03-20	61.337 mi
Registration #25	2018-03-20	61.337 mi



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1672 mm
Height	1855 mm
Length	4035 mm
Wheel base	2600 mm
Kerb weight	1120 kg
Max. allowed weight	1645 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	D011141