



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	PASSAT TDI SPORT 5 STR
Colour	Black
Year of manufacture	2009
Top speed	122 mph
0 - 60 mph	10.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	46.3 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-07-14
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-08-03
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	25
Total items failed	3

MOT #16	2023-08-03 17:11
MOT test number	487589575484
Result	✓ Passed
Next expiry date	2024-08-03

MOT #15	2022-08-04 07:30
MOT test number	228064609872
Result	✓ Passed
Advice	Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #14	2022-08-03 15:22
MOT test number	749300655094
Result	✗ Failed
Advice	Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
MAJOR	Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))
DANGEROUS	Rear Brake pad(s) less than 1.5 mm thick Both (1.1.13 (a) (ii))
Advice	Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
MAJOR	Nearside Front Wheel bearing has excessive play (5.1.3 (a) (i))

**MOT #13** 2021-08-02 09:47**MOT test number** 955689853912**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #12** 2021-07-20 15:01**MOT test number** 892072893406**Result** ✗ Failed**MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #11** 2020-07-20 09:10**MOT test number** 315337404536**Result** ✓ Passed**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect slight leak (5.3.2 (b))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Tyre slightly damaged/cracking or perishing all 4 tyres have perishing to tread area (5.2.3 (d) (ii))**MOT #10** 2019-07-16 12:25**MOT test number** 902885140184**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #9** 2018-07-27 13:59**MOT test number** 924594952100**Result** ✓ Passed

**MOT #8** 2017-07-22 09:21**MOT test number** 522941927216**Result** ✓ Passed**MOT #7** 2016-07-11 13:59**MOT test number** 269465994945**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #6** 2016-07-11 12:38**MOT test number** 748229251633**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #5** 2015-07-02 15:03**MOT test number** 717843085164**Result** ✓ Passed**Notice** Emissions not detected**Notice** Under-trays fitted obscuring some underside components**Notice** Front discs partly corroded inner surface

**MOT #4** 2015-07-02 11:09**MOT test number** 418493385133**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Notice** Under-trays fitted obscuring some underside components**Notice** Front discs partly corroded inner surface**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Nearside Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)**Notice** Emissions not detected**MOT #3** 2014-07-28 10:26**MOT test number** 356839204457**Result** ✓ Passed**MOT #2** 2013-06-11 13:28**MOT test number** 695302063189**Result** ✓ Passed**MOT #1** 2012-06-20 10:25**MOT test number** 757162872133**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
3 August 2024

Tax status	Valid until 1 August
Days left	93
MOT expiry date	3 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-29
Current registration	 XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-07-01
Last registration	2023-08-03
Complete history	See info



Registration #1	2009-07-01	8 mi
Registration #2	2012-06-20	37.470 mi
Registration #3	2013-06-11	50.291 mi
Registration #4	2014-07-28	67.171 mi
Registration #5	2015-07-02	79.243 mi
Registration #6	2015-07-02	79.243 mi
Registration #7	2016-07-11	86.614 mi
Registration #8	2016-07-11	86.619 mi
Registration #9	2017-07-22	100.110 mi
Registration #10	2018-06-20	100.110 mi
Registration #11	2018-06-20	100.110 mi
Registration #12	2018-06-20	100.110 mi
Registration #13	2018-06-20	100.110 mi
Registration #14	2018-06-20	100.110 mi
Registration #15	2018-06-20	100.110 mi
Registration #16	2018-06-20	100.110 mi
Registration #17	2018-06-20	100.110 mi
Registration #18	2018-06-20	100.110 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2066 mm
Height	1635 mm
Length	4391 mm
Wheel base	2677 mm
Kerb weight	1561 kg
Max. allowed weight	2260 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	7
Engine number	BKD C72007