



Mercedes-Benz

REI3UXV

report date: 2024-03-28

General information

Make	MERCEDES-BENZ
Model	VIANO 116 CDI TRAVELINER
Colour	Silver
Year of manufacture	2013
Top speed	113 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	120 kW / 163 HP / 163 BHP
Max. torque	360 Nm at 1.600 rpm
Engine capacity	2.143 cc
Cylinders	4
Fuel type	Diesel
Consumption city	30.4 mpg
Consumption extra urban	43.5 mpg
Consumption combined	37.7 mpg
CO2 emission	214 g/km
CO2 label	K






Internet history

Entry 2

Date	2022-01-13
Pictures	17
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2022-01-10
Pictures	0
Listing price	View report

source: autotrader.co.uk



MOT history

MOT expiry date	2025-01-16
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	11
Total items failed	5

MOT #12	2024-01-15 10:37
MOT test number	431014427495
Result	✓ Passed
Next expiry date	2025-01-16
Advice	Rear wiper not working
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11	2023-01-09 08:57
MOT test number	528686517440
Result	✓ Passed
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement lower wishbone front bush (5.3.4 (a) (i))
Advice	Nearside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement lower wishbone front bush (5.3.4 (a) (i))
Advice	Front Exhaust mounting defective (6.1.2 (a))

**MOT #10** 2023-01-06 10:31**MOT test number** 667181402582**Result** ✗ Failed

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement lower wishbone front bush (5.3.4 (a) (i))

Advice Front Exhaust mounting defective (6.1.2 (a))

Fail Offside Front Tyre tread depth below requirements of 1.6mm worn down to cords 225/55/17 101y (5.2.3 (e))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement lower wishbone front bush (5.3.4 (a) (i))

Fail Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))

Advice Nearside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))

MOT #9 2022-01-17 16:55**MOT test number** 603877427088**Result** ✓ Passed**MOT #8** 2021-11-15 16:38**MOT test number** 560602148273**Result** ✗ Failed

Fail Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))

MOT #7 2020-12-10 10:04**MOT test number** 721002664378**Result** ✓ Passed**MOT #6** 2019-12-07 11:55**MOT test number** 194137964819**Result** ✓ Passed

**MOT #5** 2019-12-07 11:55**MOT test number** 772950552035**Result** ✗ Failed**Pass with rectification** Headlamp levelling device inoperative (4.1.5 (a))**MOT #4** 2018-12-11 15:09**MOT test number** 356227184383**Result** ✓ Passed**MOT #3** 2018-12-11 11:21**MOT test number** 111961649217**Result** ✗ Failed**Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**MOT #2** 2017-12-22 09:52**MOT test number** 863092768814**Result** ✓ Passed**Advice** Both front tyres worn at edges**MOT #1** 2016-12-21 12:30**MOT test number** 357085884013**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
16 January 2025

Tax status	Valid until 1 July
Days left	63
MOT expiry date	16 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES-BENZ had different number plates.

Number of plates	1
Current registration	 RE13UXV
Plate since	2019-03-28
Current registration	 RE13UXV
Plate since	2019-03-28

More info >



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES-BENZ is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-07-23
Last registration	2024-01-15
Complete history	See info



Registration #1	2013-07-23	11 mi
Registration #2	2016-12-21	59.846 mi
Registration #3	2017-12-22	86.871 mi
Registration #4	2018-12-11	110.181 mi
Registration #5	2018-12-11	110.184 mi
Registration #6	2019-12-07	123.970 mi
Registration #7	2019-12-07	123.970 mi
Registration #8	2020-12-10	132.669 mi
Registration #9	2020-01-01	132.669 mi
Registration #10	2020-01-01	132.669 mi
Registration #11	2020-01-01	132.669 mi
Registration #12	2020-01-01	132.669 mi
Registration #13	2020-01-01	132.669 mi
Registration #14	2020-01-01	132.669 mi
Registration #15	2020-01-01	132.669 mi

More info >



Car features

The MERCEDES-BENZ factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MERCEDES-BENZ factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	2253 mm
Height	1875 mm
Length	5008 mm
Wheel base	3430 mm
Kerb weight	2085 kg
Max. allowed weight	3050 kg

Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	9
Number of axles	2
Engine number	65194031095051