





report date: 2024-03-28

General information

Make	FIAT
Model	PUNTO TWINAIR
Colour	Green
Year of manufacture	2012
Top speed	107 mph
0 - 60 mph	12.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	85 BHP
Max. torque	145 Nm at 2.000 rpm
Engine capacity	875 cc
Cylinders	2
Fuel type	Petrol
Consumption city	57.7 mpg
Consumption extra urban	74.3 mpg
Consumption combined	67.3 mpg
CO2 emission	98 g/km
CO2 label	Α



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-10-28

Pictures 10

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-11-04
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	15
Total items failed	1

MOT #10		2023-10-20 12:33
MOT test	number	369434437337
Result		✓ Passed
Next expi	ry date	2024-11-04
Advice	Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Front Exhaust has a minor leak of exhaust gases FLEXI PIPE (6.1.2 (a))	
Advice	Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i)))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Coolant leak EXPANSION BOTTLE REAR PIPE	

MOT #9	2022-11-02 16:52
MOT test number	959279332269
Result	✓ Passed
MOT #8	2021-10-26 16:36
MOT test number	336493798455
Result	✓ Passed

CarCheck.co.uk page 3/12



MOT #7 2020-11-05 15:52

MOT test number 675003861547

MOT #6 2019-06-24 07:24

MOT test number 338525570460

Result
✓ Passed

MOT #5 2019-06-20 13:13

MOT test number 993503738810

Result X Failed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge @ 3 mm , slightly scrubbed on outer edge and outer tyre wall has slight cracking. (5.2.3 (e))

MAJOR Brake pedal anti-slip provision missing (1.1.2 (c))

Advice Nearside Front Direction indicator slightly discoloured (4.4.3 (a))

MAJOR Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge @ 2.6 mm and scrubbed on both edges.

(5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge @ 3 mm and scrubbed on edges. (5.2.3

(e))

MAJOR Offside Front Direction indicator incorrect colour (4.4.3 (a))

MAJOR Offside Rear Direction indicator incorrect colour (4.4.3 (a))

MAJOR Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents

the ingress of dirt (6.1.7 (g) (ii))

MOT #4 2018-04-13 11:18

MOT test number 718818872107

Result

Passed

CarCheck.co.uk page 4/12



 MOT #3
 2018-04-13 11:18

 MOT test number
 777844068834

 Result
 X Failed

Pass with rectification

Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

 MOT #2
 2017-04-11 10:29

 MOT test number
 689990142880

 Result
 ✓ Passed

 MOT #1
 2015-12-08 11:57

 MOT test number
 508430267812

 Result
 ✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 November
Days left	187
MOT expiry date	4 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report <u>I</u>		e?
manage of the same		

	More info	>
Plate changes		
See in this check if this FIAT had different number plates.		
Number of plates		9
Current registration	UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info


More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2012-11-26
Last registration	2023-10-20
Complete history	See info



Registration #1	2012-11-26	25 mi
Registration #2	2015-12-08	25.415 mi
Registration #3	2017-04-11	44.689 mi
Registration #4	2018-04-13	53.467 mi
Registration #5	2018-04-13	53.467 mi
Registration #6	2019-06-20	65.113 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1075 kg
Max. allowed weight	1635 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Number of axles CarCheck.co.uk	2 page 12/12