





report date: 2024-03-28

### General information

Make	FORD
Model	KA TITANIUM
Colour	Red
Year of manufacture	2015
Top speed	99 mph
0 - 100 km/h	13.2 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	51 kW / 69 HP / 68 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	48.7 mpg
Consumption extra urban	64.2 mpg
Consumption combined	57.7 mpg
CO2 emission	115 g/km
CO2 label	С



CarCheck.co.uk page 1/12



## Internet history

Ei	'n	tı	r	,	1

Elitiy 1	
Date	2021-02-28
Pictures	0
Listing price	View report

source: yesauto.com

CarCheck.co.uk page 2/12



report date: 2024-03-28

B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2025-01-20
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	16
Total items failed	0

MOT #9	2024-01-08 12:12
MOT test number	261595732635
Result	✓ Passed
Next expiry date	2025-01-20

MOT #8	2023-01-11 11:13
MOT test number	273995390102
Result	✓ Passed
Advice Nearside Front Top strut mounting has slight play	

MOI #/	2022-01-21 07:42
MOT test number	858138964264
Result	✓ Passed

MOT #6	2021-03-02 16:39
MOT test number	593805177597
Result	<b>✓</b> Passed

MOT #5	2021-03-02 09:13
MOT test number	318140516290
Result	<b>X</b> Failed

MAJOR Window damaged and affecting the driver's view of an obligatory external mirror (3.2 (a) (ii))

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT test number

Result

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))

Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT** #3 2020-08-05 10:35 **MOT** test number 950397145700 Result × Failed **DANGEROUS** Nearside Rear Tyre tread depth below requirements of 1.6mm 175/65x14 (5.2.3 (e)) Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) **Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b)) **MAJOR** Emissions not tested due to engine over heating (8.2.1.2 (d)) Advice Engine over heated during test Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i)) Advice Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))

MOT #2		2019-03-27 09:23
MOT test	number	578353275913
Result		✓ Passed
Advice	Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))	
Advice	N/s/f top strut mounting has slight play	

CarCheck.co.uk page 4/12



**MOT #1** 2018-04-02 14:27

**MOT test number** 192920000931

**Result** ✓ Passed

CarCheck.co.uk page 5/12



#### Tax & MOT check



Tax status	Valid until 1 December
Days left	216
MOT expiry date	20 January 2025
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner	history
O WILCI	,

*		
For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is		ave?
THE PARTY OF THE P		
***************************************		
	More info	>
Plate changes		
See in this check if this FORD had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	NK NK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-03-30
Last registration	2024-01-08
Complete history	See info



Registration #1	2015-03-30	25 mi
Registration #2	2018-04-02	19.581 mi
Registration #3	2019-03-27	29.667 mi
Registration #4	2020-08-05	37.490 mi
Registration #5	2020-08-06	37.490 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 esi
Registration #10		11.777 es
Registration #11		11.177 es

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1702 mm
Height	1505 mm
Length	3620 mm
Wheel base	2300 mm
Kerb weight	840 kg

# Additional information

Fuel tank capacity	35 l
Number of axles	2
Engine number	1361424

CarCheck.co.uk page 12/12