





report date: 2024-03-28

General information

Make	MINI
Model	COUNTRYMAN COOPER D ALL4
Colour	Yellow
Year of manufacture	2011
Top speed	110 mph
0 - 60 mph	11.9 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	112 BHP
Max. torque	270 Nm at 2.250 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.9 mpg
CO2 emission	158 g/km
CO2 label	G



CarCheck.co.uk page 1/12



Internet history

Entry 2

Date 2021-07-31

Pictures 12

Listing price <u>View report</u>









source: yesauto.com

Entry 1

Date	2021-07-18
Pictures	13

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

Advice

MOT expiry date	2024-09-07
MOT pass rate	91 %
MOT passed	10
Failed MOT tests	1
Total advice items	13
Total items failed	1

MOT #11	2023-08-25 08:48
MOT test number	584983943500
Result	✓ Passed
Next expiry date	2024-09-07
Advice Both front brake discs worn with 'lips' on edges.	

MOT #10	2022-09-08 07:51
MOT test number	712174852320
Result	✓ Passed

MOT #9	2021-09-07 15:40
MOT test number	436106730105
Result	✓ Passed

MOT #8	2021-03-03 16:58
MOT test number	137004167029

Result	✓ Passed
Advice	Offside Rear Inner Tyre slightly damaged/cracking or perishing Side wall damaged (5.2.3 (d) (ii))
Minor (g) (i))	Nearside Rear Drive shaft joint constant velocity boot severely deteriorated Leaking grease (6.1.7
Advice	Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 3/12

Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))



Minor

(g) (i))

LL61AYS report date: 2024-03-28

MOT test number

544320428185

Result

Advice Offside Rear Inner Tyre slightly damaged/cracking or perishing Side wall damaged (5.2.3 (d) (ii))

Advice Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Nearside Rear Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))

Nearside Rear Drive shaft joint constant velocity boot severely deteriorated Leaking grease (6.1.7

 MOT #6
 2020-02-28 14:43

 MOT test number
 943669087112

 Result
 ✓ Passed

 MOT #5
 2019-03-04 14:15

 MOT test number
 341359312834

Result

✓ Passed

Minor

Nearside Rear Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #4

MOT test number

Result

Advice Nearside Rear Outer constant velocity gaiter deteriorated

2017-11-17 15:08

267200894868

✓ Passed

MOT test number

Result

Advice (2.5.B.1b)

Offside Front Macpherson strut has slight movement in the upper support bearing assembly split (2.5.B.1b)

CarCheck.co.uk page 4/12



MOT #2	2015-11-20 10:08
MOT test number	722692386731
Result	✓ Passed
MOT #1	2014-11-11 09:41
MOT test number	649525314395
Result	✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



lax status	valid until 1 September
Days left	126
MOT expiry date	7 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	
Current registration	NIE UK
Plate since	
Current registration	NK SIK
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >


CarCheck.co.uk page 10/12



Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-11-21
Last registration	2023-08-25
Complete history	See info



Registration #1	2011-11-21	28 mi
Registration #2	2014-11-11	10.714 mi
Registration #3	2015-11-20	27.747 mi
Registration #4	2016-11-04	47.486 mi
Registration #5	2017-11-17	67.036 mi
Registration #6	2019-03-04	88.187 mi
Registration #7	2020-02-28	103.504 mi
Registration #8		77,777 44
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		D.777 es
Registration #13		D.327 es

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4097 mm
Wheel base	2595 mm
Kerb weight	1405 kg
Max. allowed weight	1875 kg

Additional information

Fuel tank capacity	47 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 12/12