



report date: 2024-03-28

General information

Make	CITROEN
Model	DISPATCH 1200 L2H1 LWB P/V HDI 90
Colour	White
Year of manufacture	-
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	180 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-23
Pictures	11
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT #21	2022-09-17 11:53
MOT test number	757752210846
Result	✓ Passed
Next expiry date	2023-09-20
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #20	2022-09-17 11:53
MOT test number	386909637513
Result	✗ Failed
Pass with rectification	Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii))
Pass with rectification	Offside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #19	2021-09-17 09:37
MOT test number	582695803875
Result	✓ Passed
Advice	Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Front Power steering pipe/hose has slight seepage (2.1.5 (a))
Advice	Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Fluid leak, but not excessive (8.4.1 (a) (i))

MOT #18	2020-09-17 13:11
MOT test number	705033710057
Result	✓ Passed

**MOT #17** 2020-09-17 13:11**MOT test number** 200864127789**Result** ✗ Failed**Pass with rectification** Offside Obligatory mirror seriously damaged, affecting the rear view (3.3 (b) (ii))**MOT #16** 2019-09-19 14:16**MOT test number** 406318345299**Result** ✓ Passed**MOT #15** 2019-09-18 08:07**MOT test number** 279313468135**Result** ✗ Failed**Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge 215/60/r16c 103/101 t (5.2.3 (e))**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #14** 2018-09-04 11:32**MOT test number** 922768928861**Result** ✓ Passed**MOT #13** 2017-09-21 12:55**MOT test number** 245456936125**Result** ✓ Passed**MOT #12** 2017-02-09 15:06**MOT test number** 175673837034**Result** ✓ Passed

**MOT #11** 2016-01-20 10:08**MOT test number** 432985580392**Result** ✓ Passed**MOT #10** 2016-01-20 10:08**MOT test number** 489559580401**Result** ✗ Failed**Pass with rectification** Centre Stop lamp not working (1.2.1b)**MOT #9** 2015-01-21 10:35**MOT test number** 138601925014**Result** ✓ Passed**MOT #8** 2014-01-22 15:12**MOT test number** 396202524034**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #7	2014-01-21 12:35
MOT test number	127091024066
Result	✗ Failed
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Notice	High level brake light not working
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Advice	Offside Rear Direction indicator slightly discoloured (1.4.A.2f)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Notice	Child seat fitted not allowing full inspection of adult belt
Notice	Oil level on minimum

MOT #6	2013-08-28 15:55
MOT test number	126120043201
Result	✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Notice	Nail in nearside rear tyre

**MOT #5** 2013-08-19 15:57**MOT test number** 876081833200**Result** ✗ Failed**Advice** Offside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Nearside front brake hose slightly twisted**Fail** Offside Front Lower Ball joint has excessive play (2.2.B.1f)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Nail in nearside rear tyre**MOT #4** 2012-08-24 11:27**MOT test number** 846387532219**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Offside Outer Front Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**MOT #3** 2011-08-26 09:28**MOT test number** 229178531220**Result** ✓ Passed**Advice** Offside Front Front constant velocity joint gaiter deteriorated (2.5.C.1a)**MOT #2** 2010-08-23 15:39**MOT test number** 174425530296**Result** ✓ Passed



MOT #1	2010-08-23 15:39
MOT test number	761455430281
Result	✗ Failed
Pass with rectification	Nearside Headlamp not working on dipped beam (1.7.5a)
Pass with rectification	Headlamp aim too low (1.8)



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	FH07MKK
Plate since	2019-03-28
Current registration	FH07MKK
Plate since	2019-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-07-27
Last registration	2022-09-17
Complete history	See info



Registration #1	2007-07-27	14 mi
Registration #2	2010-08-23	53.674 mi
Registration #3	2011-08-26	59.525 mi
Registration #4	2012-08-24	63.161 mi
Registration #5	2013-08-19	66.742 mi
Registration #6	2013-08-28	66.800 mi
Registration #7	2014-01-21	68.742 mi
Registration #8	2014-01-22	68.764 mi
Registration #9	2015-01-21	72.578 mi
Registration #10	2016-01-20	76.892 mi
Registration #11	2016-01-20	76.892 mi
Registration #12	2016-01-20	76.892 mi
Registration #13	2016-01-20	76.892 mi
Registration #14	2016-01-20	76.892 mi
Registration #15	2016-01-20	76.892 mi
Registration #16	2016-01-20	76.892 mi
Registration #17	2016-01-20	76.892 mi
Registration #18	2016-01-20	76.892 mi
Registration #19	2016-01-20	76.892 mi
Registration #20	2016-01-20	76.892 mi
Registration #21	2016-01-20	76.892 mi
Registration #22	2016-01-20	76.892 mi

More info >



Dimensions & weight

Width	2194 mm
Height	1942 mm
Length	5135 mm

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	3
Engine number	JB500039596