





report date: 2024-03-28

### General information

Make	JAGUAR
Model	X-TYPE S
Colour	Grey
Year of manufacture	2009
Top speed	125 mph
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	130 BHP
Max. torque	330 Nm at 1.800 rpm
Engine capacity	1.998 сс
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	62.8 mpg
Consumption combined	50.4 mpg
CO2 emission	149 g/km
CO2 label	F



CarCheck.co.uk page 1/14



report date: 2024-03-28

### Internet history

#### Entry 3

Date 2023-02-19

Pictures 10

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 2

Date	2023-02-03
------	------------

Pictures 10

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date	2021-08-24

Pictures 20

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-28

# MOT history

MOT expiry date	2024-09-10
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	24
Total items failed	10

MOT #19	2023-09-11 16:16
MOT test number	781393375815
Result	✓ Passed
Next expiry date	2024-09-10
Advice Rear Coil spring corroded Both sides (5.3.1 (b) (i))	

MOT #18	2023-09-02 15:07
MOT test number	911627327385
Result	<b>×</b> Failed
Fail Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))	
Fail Offside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))	
Fail Rear Exhaust silencer insecure Clamp broken (8.1.1 (b) (i))	
Advice Rear Coil spring corroded Both sides (5.3.1 (b) (i))	
Minor Nearside Front Tyre obviously under inflated (5.2.3 (I))	

CarCheck.co.uk page 3/14



report date: 2024-03-28

MOT #17		2022-09-08 15:22
MOT test	number	105366100752
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1	.14 (a) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	

MOT #16		2022-02-04 08:48
MOT test number		477719097607
Result		✓ Passed
MOT #15		2022-02-04 08:48
MOT test number		827878337568
Result		<b>X</b> Failed
Pass with rectification	Nearside Rear Position lamp not working (4.2.1 (a) (ii))	
Pass with rectification	Front Headlamp aim too low both (4.1.2 (a))	

MOT #14	2022-01-07 17:34
MOT test number	288817999160
Result	<b>✓</b> Passed

CarCheck.co.uk page 4/14



report date: 2024-03-28

**MOT #13** 2022-01-07 11:11

**MOT test number** 312026692760

Result X Failed

Fail Offside Front Inner Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Nearside Front Inner Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #12** 2021-02-11 09:52

MOT test number 163807813395

**Result** 
✓ Passed

**Advice** Front tyres worn off on inner edges

**Advice** Slight bearing /transmission rumble noise

**MOT #11** 2020-02-22 11:41

MOT test number 516969858191

Result \( \sqrt{Passed} \)

Advice Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #10 2020-02-22 11:41

MOT test number 661416949307

**Result** X Failed

**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**Pass with rectification** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

CarCheck.co.uk page 5/14



report date: 2024-03-28

MOT #9	2019-03-15 13:37
MOT test number	533089907842
Result	<b>✓</b> Passed
Advice Rear coil springs corroded	

***	****
MOT #8	2018-03-19 15:38
MOT test number	798984485750
Result	✓ Passed
MOT #7	2017-03-16 09:35
MOT test number	619184319213
Result	<b>✓</b> Passed
Advice Corrosion in rear coil springs	

MOT #6	2016-03-16 14:32
MOT test number	777746307132
Result	<b>✓</b> Passed
MOT #5	2015-03-23 13:46
MOT test number	988672685069
Result	<b>✓</b> Passed
MOT #4	2014-03-14 12:22
MOT test number	505653474029
Result	<b>✓</b> Passed
Notice Both rear tyres starting to go out of shape	

CarCheck.co.uk page 6/14



report date: 2024-03-28

MOT #3

MOT test number

Result

Notice Rear brake discs are corroded on the face

Notice Rear number plate is deteriated

MOT #2 2013-03-01 10:22 **MOT** test number 736070863099 Result **X** Failed **Notice** Rear brake discs are corroded on the face Fail Nearside Front Lower Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2) Notice Rear number plate is deteriated Fail Offside Front Upper Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

MOT #1

MOT test number

Result

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 7/14





report date: 2024-03-28

### Tax & MOT check



Tax status	Valid until 1 March
Days left	307
MOT expiry date	10 September 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 8/14



report date: 2024-03-28

#### Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

 $\quad \text{More info} \quad > \quad$ 

CarCheck.co.uk page 10/14



report date: 2024-03-28

<b>O</b>	history
IWADAL	
	IIISLUIV

For how long did the current and previous owner(s) have this JAGUAR? How many owners have? Check it in the premium report and see all owner registrations. Download the full re		ΛR
***************************************		
THE REAL PROPERTY AND ADDRESS OF THE PERTY ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY		
***************************************		
************		
	More info	>
Plate changes		
See in this check if this JAGUAR had different number plates.		
Number of plates		
Current registration	NK SIE	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 11/14



YD09MKZ report date: 2024-03-28

#### Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2009-03-30
Last registration	2023-09-11
Complete history	See info



Registration #1	2009-03-30	15 mi
Registration #2	2012-03-22	58.196 mi
Registration #3	2013-03-01	65.414 mi
Registration #4	2013-03-01	65.414 mi
Registration #5	2014-03-14	67.509 mi
Registration #6	2015-03-23	71.758 mi
Registration #7	2016-03-16	76.483 mi
Registration #8	2017-03-16	79.779 mi
Registration #9	2018-03-19	84.620 mi
Registration #10	2019-03-15	89.733 mi
Registration #11	2020-02-22	93.712 mi
Registration #12	2020-02-22	93.712 mi
Registration #13		11.177 es
Registration #14		11.117 es
Registration #15		11.177 mi
Registration #16		
		0.00
Registration #17		11.777 es
Registration #17 Registration #18		71.77 m
		11.777 es 11.777 es 11.777 es
Registration #18		11.777 es 11.777 es 11.777 es
Registration #18 Registration #19		11.777 es 11.777 es 11.777 es 11.777 es 11.777 es
Registration #18 Registration #19 Registration #20		11.777 es 11.777 es 11.777 es 11.777 es 11.777 es

More info >

CarCheck.co.uk page 13/14



YD09MKZ report date: 2024-03-28

## Safety ratings

NCAP rating	***
Video	see crash video



# Dimensions & weight

Width	2003 mm
Height	1395 mm
Length	4672 mm
Wheel base	2710 mm
Kerb weight	1502 kg
Max. allowed weight	2015 kg

## Additional information

Fuel tank capacity	61 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	0810291657186G

CarCheck.co.uk page 14/14