



report date: 2024-03-28

General information

Make	VOLVO
Model	C30 T5 R-DESIGN
Colour	Orange
Year of manufacture	2011
Top speed	149 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	230 BHP
Max. torque	320 Nm at 1.500 rpm
Engine capacity	2.521 cc
Cylinders	5
Fuel type	Petrol
Consumption city	22.4 mpg
Consumption extra urban	44.1 mpg
Consumption combined	32.5 mpg
CO2 emission	203 g/km
CO2 label	K






Internet history

Entry 1

Date	2022-05-22
Pictures	13
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-30
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	15
Total items failed	5

MOT #14 2024-01-25 16:12

MOT test number 913033112146

Result ✓ Passed

Next expiry date 2025-01-30

Advice Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #13 2024-01-25 16:12

MOT test number 889836978598

Result ✗ Failed**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Pass with rectification** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

MOT #12 2023-01-10 15:23

MOT test number 373318378072

Result ✓ Passed

**MOT #11** 2022-01-26 09:39**MOT test number** 401432538020**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #10** 2021-01-19 09:35**MOT test number** 735898695620**Result** ✓ Passed**MOT #9** 2020-01-29 14:06**MOT test number** 385806384665**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge 0MM ON INNER EDGE (5.2.3 (e))**MOT #8** 2020-01-29 14:06**MOT test number** 371854698892**Result** ✗ Failed**Pass with rectification** Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge 0MM ON INNER EDGE (5.2.3 (e))**Pass with rectification** Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**MOT #7** 2019-01-31 10:20**MOT test number** 490108915267**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #6** 2019-01-31 10:20**MOT test number** 951369999246**Result** ✗ Failed**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #5** 2018-01-31 12:02**MOT test number** 105702149717**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit ON INNER AND OUTER EDGES (4.1.E.1)**MOT #4** 2017-01-24 14:22**MOT test number** 985721953223**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2016-01-19 10:36**MOT test number** 125319011517**Result** ✓ Passed**Advice** Offside Rear tyre slightly perishing 205/50/17 pirelli**MOT #2** 2015-01-19 10:42**MOT test number** 179389615027**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #1	2014-01-09 09:31
MOT test number	655879404097
Result	✓ Passed
<div>Notice</div> Front pads getting low	



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
30 January 2025

Tax status	Valid until 1 June
Days left	33
MOT expiry date	30 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-




Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2023-03-28
Current registration	 *****
Plate since	2023-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-01-21
Last registration	2024-01-25
Complete history	See info



Registration #1	2011-01-21	25 mi
Registration #2	2014-01-09	31.315 mi
Registration #3	2015-01-19	38.670 mi
Registration #4	2016-01-19	44.536 mi
Registration #5	2017-01-24	49.211 mi
Registration #6	2018-01-31	56.679 mi
Registration #7	2019-01-31	65.632 mi
Registration #8	2019-01-31	65.632 mi
Registration #9	2020-01-20	75.000 mi
Registration #10	2020-01-20	75.000 mi
Registration #11	2020-01-20	75.000 mi
Registration #12	2020-01-20	75.000 mi
Registration #13	2020-01-20	75.000 mi
Registration #14	2020-01-20	75.000 mi
Registration #15	2020-01-20	75.000 mi
Registration #16	2024-01-25	75.000 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1444 kg
Max. allowed weight	1860 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	4422627