



report date: 2024-03-29

General information

Make	CITROEN
Model	DS3 E-HDI DSTYLE
Colour	Grey
Year of manufacture	2015
Top speed	113 mph
0 - 60 mph	12.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	85.6 mpg
Consumption combined	76.4 mpg
CO2 emission	95 g/km
CO2 label	A






Internet history

Entry 1

Date	2021-10-29
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-27
MOT pass rate	62 %
MOT passed	8
Failed MOT tests	5
Total advice items	21
Total items failed	1

MOT #13	2024-01-20 12:46
MOT test number	205283150954
Result	✓ Passed
Next expiry date	2025-01-27

MOT #12	2024-01-18 10:22
MOT test number	456711594581
Result	✗ Failed
MAJOR Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt offside front outer (6.1.7 (g) (ii))	
MAJOR Position lamp not working offside front (4.2.1 (a) (ii))	

MOT #11	2023-01-25 09:25
MOT test number	481454509587
Result	✓ Passed
Advice	Offside Front Tyre slightly damaged/cracking or perishing tread. (5.2.3 (d) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing tread and outer wall. (5.2.3 (d) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #10** 2023-01-21 09:08**MOT test number** 706708364818**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing tread and outer wall. (5.2.3 (d) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre slightly damaged/cracking or perishing tread. (5.2.3 (d) (ii))**MOT #9** 2022-01-28 17:00**MOT test number** 564224189212**Result** ✓ Passed**MOT #8** 2022-01-28 10:01**MOT test number** 428752779894**Result** ✗ Failed**MAJOR** Rear Exhaust system insecure (6.1.2 (a))**MAJOR** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #7** 2021-09-22 12:34**MOT test number** 328646496136**Result** ✓ Passed**Minor** Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #6** 2021-09-20 16:35**MOT test number** 488228318677**Result** ✗ Failed**MAJOR** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Minor** Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MOT #5** 2020-09-21 15:34**MOT test number** 340838633664**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened N/S AND O/S WORN AND CORRODED ON INNER FACES (1.1.14 (a) (ii))**Advice** Front Brake pad(s) wearing thin N/S AND O/S WORN CLOSE TO MINIMUM (1.1.13 (a) (ii))**MOT #4** 2019-09-18 11:01**MOT test number** 920428012929**Result** ✓ Passed**MOT #3** 2018-09-12 10:53**MOT test number** 791947179479**Result** ✓ Passed**MOT #2** 2017-09-22 08:04**MOT test number** 961273659084**Result** ✓ Passed



MOT #1	2017-09-16 07:21
MOT test number	401626939312
Result	✗ Failed
Advice	Nearside Front Nail in tyre
Fail	Tyre pressure monitoring system warning lamp indicates a fault (4.1.D.4)



Tax & MOT check

✓
Taxed

Tax due:
1 January 2025

✓
MOT

Expires:
27 January 2025

Tax status	Valid until 1 January
Days left	246
MOT expiry date	27 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2015-01-22
Last registration	2024-01-20
Complete history	See info



Registration #1	2015-01-22	8 mi
Registration #2	2017-09-16	14.063 mi
Registration #3	2017-09-22	14.063 mi
Registration #4	2018-09-12	17.881 mi
Registration #5	2019-09-18	20.778 mi
Registration #6	2020-09-21	25.692 mi
Registration #7	2021-09-20	35.067 mi
Registration #8	2021-09-22	35.067 mi
Registration #9	2022-09-20	35.067 mi
Registration #10	2022-09-20	35.067 mi
Registration #11	2022-09-20	35.067 mi
Registration #12	2022-09-20	35.067 mi
Registration #13	2022-09-20	35.067 mi
Registration #14	2022-09-20	35.067 mi
Registration #15	2022-09-20	35.067 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1728 mm
Height	1524 mm
Length	3941 mm
Wheel base	2464 mm
Kerb weight	1085 kg
Max. allowed weight	1602 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	JBFM0107961