





report date: 2024-03-29

General information

| Make | HONDA |
|---------------------|---------------------|
| Model | JAZZ I-VTEC EX NAVI |
| Colour | Red |
| Year of manufacture | 2018 |
| Top speed | 118 mph |
| 0 - 60 mph | 11.5 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 101 BHP |
|-------------------------|---------------------|
| Max. torque | 123 Nm at 5.000 rpm |
| Engine capacity | 1.318 сс |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 46.3 mpg |
| Consumption extra urban | 60.1 mpg |
| Consumption combined | 47.9 mpg |
| CO2 emission | 119 g/km |
| CO2 label | С |



CarCheck.co.uk page 1/10



report date: 2024-03-29


Internet history

Entry 1


Date 2021-12-14

Pictures 38

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/10



report date: 2024-03-29

MOT history

| MOT expiry date | 2025-01-20 |
|--------------------|------------|
| MOT pass rate | 100 % |
| MOT passed | 4 |
| Failed MOT tests | 0 |
| Total advice items | 5 |
| Total items failed | 0 |

| MOT #4 | | 2023-12-22 13:02 |
|--|---|------------------|
| MOT test | number | 239125287258 |
| Result | | ✓ Passed |
| Next expi | ry date | 2025-01-20 |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i)) | | |
| Advice | Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |

| MOT #3 | 2023-01-06 11 | :57 |
|----------|---|-----|
| MOT test | number 4042876579 | 979 |
| Result | ✓ Pass | sed |
| Advice | Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i)) | |

| MOT #2 | 2022-01-21 08:58 |
|-----------------|------------------|
| MOT test number | 814114561898 |
| Result | ✓ Passed |
| | |
| MOT #1 | 2021-09-02 14:11 |
| MOT test number | 406202520762 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/10



report date: 2024-03-29

Tax & MOT check



| Tax status | Valid until 1 January |
|------------------|-----------------------|
| Days left | 248 |
| MOT expiry date | 20 January 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|-------------------------------|------------|
| Band | G |
| First licence fee (12 months) | £ 210,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |
| | |

CarCheck.co.uk page 4/10



report date: 2024-03-29

Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 6/10



report date: 2024-03-29

| \sim | | - La : | | |
|------------------|-----|--------|-----|-----|
| $ \cup$ \wedge | ner | nı | SIO | ı۲۱ |

| For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report here. | | |
|---|---------------------|---|
| nave: Check it in the premium report and see an owner registrations. Download the full r | eport <u>nere</u> . | |
| | | |
| | | |
| | | |
| | | |
| ********* | | |
| *************************************** | | |
| *************************************** | | |
| | | |
| | More info > | |
| Plate changes | | |
| See in this check if this HONDA had different number plates. | | |
| Number of plates | | 9 |
| Current registration | UK UK | |
| Plate since | | |
| Current registration | NK NA | |
| Plate since | | |
| | More info > | |

CarCheck.co.uk page 7/10



report date: 2024-03-29

Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info >

CarCheck.co.uk page 8/10



report date: 2024-03-29

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 6 |
| First mileage registration | 2018-09-26 |
| Last registration | 2023-12-22 |
| Complete history | See info |



| Registration #1 | 2018-09-26 | 19 mi |
|-----------------|------------|-----------|
| Registration #2 | 2021-09-02 | 5.296 mi |
| Registration #3 | | 11.777 es |
| Registration #4 | | 11.777 es |
| Registration #5 | | 11.777 es |
| Registration #6 | | 11.777 es |

More info >

CarCheck.co.uk page 9/10



report date: 2024-03-29

Safety ratings

| NCAP rating | **** | |
|----------------|-----------------|--|
| Adult | 93% | |
| Children | 85% | |
| Pedestrian | 73% | |
| Safety systems | 71% | |
| Overall rating | 83% | |
| Video | see crash video | |



Dimensions & weight

| Width | 1694 mm |
|---------------------|---------|
| Height | 1550 mm |
| Length | 4028 mm |
| Wheel base | 2530 mm |
| Kerb weight | 1110 kg |
| Max. allowed weight | 1605 kg |

Additional information

| Fuel tank capacity | 40 I |
|--------------------|-----------------------|
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | L13B21280699 |

CarCheck.co.uk page 10/10