



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	AVENSIS VVTI T3-X
Colour	Red
Year of manufacture	-
Top speed	124 mph
0 - 60 mph	10.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	127 BHP
Max. torque	166 Nm at 4.200 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	30.1 mpg
Consumption extra urban	48.7 mpg
Consumption combined	39.2 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-11
Pictures	1
Listing price	<a href="#">View report</a>

How buying a car with us works

Find a car you like on our website.

Give us a ring to book an appointment to suit your convenience.

Finally we'll bring the vehicle from our secure compound to the showroom, ready for you to view.



source: [autotrader.co.uk](#)



## MOT history

MOT #24	2022-08-15 14:41
MOT test number	839957181173
Result	✓ Passed
Next expiry date	2023-08-14
<b>Advice</b>	Offside Front Coil spring corroded (5.3.1 (b) (i))
<b>Minor</b>	Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
<b>Advice</b>	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
<b>Advice</b>	Nearside Front Coil spring corroded (5.3.1 (b) (i))
<b>Minor</b>	Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #23	2022-08-12 09:09
MOT test number	612622871753
Result	✗ Failed
<b>MAJOR</b>	Front Windscreen washer provides insufficient washer liquid (3.5 (a))
<b>Advice</b>	Nearside Front Coil spring corroded (5.3.1 (b) (i))
<b>Minor</b>	Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
<b>MAJOR</b>	Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
<b>MAJOR</b>	Central Upper Stop lamp(s) not working (4.3.1 (a) (ii))
<b>Minor</b>	Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
<b>Advice</b>	Offside Front Coil spring corroded (5.3.1 (b) (i))
<b>MAJOR</b>	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
<b>Advice</b>	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #22	2021-08-13 14:24
MOT test number	113275137709
Result	✓ Passed

**MOT #21** 2021-08-13 14:24**MOT test number** 785740164280**Result** ✗ Failed**Pass with rectification** Front Windscreen washer not working (3.5 (a))**MOT #20** 2020-09-24 14:07**MOT test number** 607711227061**Result** ✓ Passed**MOT #19** 2020-09-24 11:20**MOT test number** 895539538337**Result** ✗ Failed**MAJOR** Nearside Rear Service brake excessively binding (1.2.1 (f))**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened pitted (1.1.14 (a) (ii))**DANGEROUS** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened pitted (1.1.14 (a) (ii))**MOT #18** 2019-03-12 15:58**MOT test number** 158935758016**Result** ✓ Passed**MOT #17** 2019-03-12 15:58**MOT test number** 683593907723**Result** ✗ Failed**Pass with rectification** Front Undertray likely to become detached (6.2.1 (a) (ii))

**MOT #16** 2018-04-03 08:21**MOT test number** 682442802785**Result** ✓ Passed**MOT #15** 2017-04-04 08:31**MOT test number** 514745952073**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Slight cracks in nearside and offside rear tyres**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #14** 2016-04-11 08:26**MOT test number** 714371486603**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #13** 2015-03-13 10:33**MOT test number** 946542475046**Result** ✓ Passed**MOT #12** 2015-03-13 09:45**MOT test number** 378142075052**Result** ✗ Failed**Fail** Electronic stability system warning lamp indicates a fault (3.4.1c)**MOT #11** 2014-04-03 10:43**MOT test number** 617593794078**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #10** 2014-04-03 10:43**MOT test number** 579913694007**Result** ✗ Failed**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #9** 2013-03-26 12:20**MOT test number** 908215283059**Result** ✓ Passed**MOT #8** 2012-04-12 13:30**MOT test number** 609333002132**Result** ✓ Passed**MOT #7** 2012-04-11 17:12**MOT test number** 267162502498**Result** ✗ Failed**Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Bonnet cannot be secured in the closed position (8.4.1)**Fail** Offside Headlamp not working on main beam (1.7.5a)**MOT #6** 2012-01-25 10:26**MOT test number** 809625722063**Result** ✓ Passed**Notice** Plastic over sills unable to fully examine**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #5** 2011-02-10 09:46**MOT test number** 655481441080**Result** ✓ Passed**MOT #4** 2010-08-04 15:01**MOT test number** 331656010492**Result** ✓ Passed**Notice** Nail in offside front tyre**MOT #3** 2009-08-06 12:36**MOT test number** 203238019204**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2008-07-31 12:31**MOT test number** 321573518294**Result** ✓ Passed**MOT #1** 2007-07-27 11:41**MOT test number** 833448207285**Result** ✓ Passed



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	
Plate since	2019-01-01
Current registration	
Plate since	2019-01-01

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2004-09-22
Last registration	2022-08-15
Complete history	<a href="#">See info</a>



Registration #1	2004-09-22	17 mi
Registration #2	2007-07-27	11.019 mi
Registration #3	2008-07-31	17.664 mi
Registration #4	2009-08-06	26.255 mi
Registration #5	2010-08-04	30.194 mi
Registration #6	2011-02-10	31.786 mi
Registration #7	2012-01-25	44.566 mi
Registration #8	2012-04-11	47.322 mi
Registration #9	2012-04-12	47.322 mi
Registration #10	2013-03-26	52.334 mi
Registration #11	2014-04-03	58.452 mi
Registration #12	2015-03-13	63.438 mi
Registration #13	2015-03-13	63.438 mi
Registration #14	2016-03-20	65.377 mi
Registration #15	2016-03-20	65.377 mi
Registration #16	2016-03-20	65.377 mi
Registration #17	2016-03-20	65.377 mi
Registration #18	2016-03-20	65.377 mi
Registration #19	2016-03-20	65.377 mi
Registration #20	2016-03-20	65.377 mi
Registration #21	2016-03-20	65.377 mi
Registration #22	2016-03-20	65.377 mi
Registration #23	2016-03-20	65.377 mi
Registration #24	2016-03-20	65.377 mi
Registration #25	2016-03-20	65.377 mi



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1760 mm
Height	1480 mm
Length	4630 mm
Wheel base	2700 mm
Kerb weight	1245 kg
Max. allowed weight	1820 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	1ZZU565110