



report date: 2024-03-29

## General information

Make	VAUXHALL
Model	TIGRA 16V EXCLUSIV
Colour	Black
Year of manufacture	2007
Top speed	127 mph
0 - 60 mph	9.4 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	123 BHP
Max. torque	165 Nm at 4.600 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.9 mpg
Consumption extra urban	48.7 mpg
Consumption combined	36.7 mpg
CO2 emission	185 g/km
CO2 label	I





## MOT history

MOT expiry date	2021-03-27
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	25
Total items failed	5

MOT #15	2020-03-06 11:01
MOT test number	351110938768
Result	✓ Passed
Next expiry date	2021-03-27

MOT #14	2019-03-08 09:14
MOT test number	266641835861
Result	✓ Passed
Advice	Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #13	2018-03-09 08:53
MOT test number	582668685538
Result	✓ Passed

MOT #12	2018-03-09 08:53
MOT test number	400234866342
Result	✗ Failed
Pass with rectification	Offside Registration plate lamp not working (1.1.C.1d)

**MOT #11** 2017-03-28 09:14**MOT test number** 299129900562**Result** ✓ Passed**Advice** Nearside front and rear tyres inner side walls perishing**MOT #10** 2016-05-05 08:45**MOT test number** 561353485596**Result** ✓ Passed**Advice** Centre Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #9** 2015-05-06 16:46**MOT test number** 378906625167**Result** ✓ Passed**Advice** Nearside Front Track rod end ball joint has slight play (2.2.B.1f)**Advice** Nearside Rear coil spring corroded (2.4.C.1b)**Notice** Rear brake discs worn**MOT #8** 2015-05-06 10:51**MOT test number** 206366325405**Result** ✗ Failed**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)**Advice** Nearside Rear coil spring corroded (2.4.C.1b)**Notice** Rear brake discs worn**Fail** Offside Front Track rod end ball joint has excessive play (2.2.B.1f)**Advice** Nearside Front Track rod end ball joint has slight play (2.2.B.1f)

**MOT #7** 2014-05-08 16:27**MOT test number** 639278824193**Result** ✓ Passed

- Notice** O/s/f tyre inner edge worn
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

**MOT #6** 2014-05-07 16:16**MOT test number** 817447324156**Result** ✗ Failed

- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Notice** O/s/f tyre inner edge worn
- Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)
- Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)
- Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #5** 2013-05-09 15:45**MOT test number** 438229423153**Result** ✓ Passed

**MOT #4** 2012-07-13 14:46**MOT test number** 756295692188**Result** ✓ Passed**MOT #3** 2011-09-01 09:16**MOT test number** 987894941272**Result** ✓ Passed**MOT #2** 2011-08-30 15:43**MOT test number** 725732941242**Result** ✗ Failed

**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

**Notice** Nail in nearside rear tyre

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #1** 2010-09-04 09:55**MOT test number** 801697440210**Result** ✓ Passed

**Notice** O/s/r tyre starting to perish



Tax & MOT check

✕  
Untaxed

Tax expired:  
2 December 2020

✕  
MOT

Expired:  
27 March 2021

Tax status	Expired at 2 December 2020
Days left	1245 days too late
MOT expiry date	27 March 2021
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >





Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 <b>GK57VBU</b>
Plate since	2019-03-29
Current registration	 <b>GK57VBU</b>
Plate since	2019-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2007-09-14
Last registration	2020-03-06
Complete history	<a href="#">See info</a>



Registration #1	2007-09-14	27 mi
Registration #2	2010-09-04	24.251 mi
Registration #3	2011-08-30	31.258 mi
Registration #4	2011-09-01	31.292 mi
Registration #5	2012-07-13	38.002 mi
Registration #6	2013-05-09	43.851 mi
Registration #7	2014-05-07	48.191 mi
Registration #8	2014-05-08	48.200 mi
Registration #9	2015-05-20	55.277 mi
Registration #10	2015-05-20	55.277 mi
Registration #11	2015-05-20	55.277 mi
Registration #12	2015-05-20	55.277 mi
Registration #13	2015-05-20	55.277 mi
Registration #14	2015-05-20	55.277 mi
Registration #15	2015-05-20	55.277 mi
Registration #16	2015-05-20	55.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1905 mm
Height	1364 mm
Length	3921 mm
Wheel base	2491 mm
Max. allowed weight	1505 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	20JM3354