



report date: 2024-03-29

General information

|                     |                      |
|---------------------|----------------------|
| Make                | FORD                 |
| Model               | GALAXY TITANIUM TDCI |
| Colour              | Silver               |
| Year of manufacture | 2010                 |
| Top speed           | 122 mph              |
| 0 - 60 mph          | 9.8 seconds          |
| Gearbox             | 6 speed Manual       |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 138 BHP             |
| Max. torque             | 320 Nm at 3.250 rpm |
| Engine capacity         | 1.997 cc            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 39.2 mpg            |
| Consumption extra urban | 57.6 mpg            |
| Consumption combined    | 49.6 mpg            |
| CO2 emission            | 159 g/km            |
| CO2 label               | G                   |





Internet history

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-09-25                  |
| Pictures      | 50                          |
| Listing price | <a href="#">View report</a> |



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2024-10-04 |
| MOT pass rate      | 63 %       |
| MOT passed         | 12         |
| Failed MOT tests   | 7          |
| Total advice items | 41         |
| Total items failed | 14         |

|                  |  |
|------------------|--|
| MOT #19          | 2023-10-05 11:51   |
| MOT test number  | 439858589751   |
| Result           | ✓ Passed   |
| Next expiry date | 2024-10-04   |
| Advice           | Front Brake pad(s) wearing thin (1.1.13 (a) (ii))  |
| Advice           | Front Brake disc worn, but not excessively (1.1.14 (a) (i))  |
| Advice           | Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))  |
| Minor            | Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) |

|                 |   |
|-----------------|---|
| MOT #18         | 2023-10-02 14:42  |
| MOT test number | 304878114118  |
| Result          | ✗ Failed  |
| Advice          | Front Brake disc worn, but not excessively (1.1.14 (a) (i))   |
| Advice          | Front Brake pad(s) wearing thin (1.1.13 (a) (ii))   |
| Minor           | Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))                    |
| Fail            | Offside Side repeater not working In mirror (4.4.1 (a) (ii))  |
| Advice          | Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm front bush (5.3.4 (a) (i)) |
| Advice          | Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))   |
| Fail            | Offside Rear Suspension arm pin or bush excessively worn Trailing arm front bush (5.3.4 (a) (i))                              |

**MOT #17**

2022-10-03 13:11

**MOT test number**

999897157552

**Result**

✓ Passed

**Advice** Nearside Rear Outer Tyre has a cut but not deep enough to reach the ply or cords Tyre wall (5.2.3 (d) (i))

**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Minor** Nearside Windscreen damaged but not adversely affecting driver's view Stone chip (3.2 (a) (i))

**Advice** Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement o/s and n/s trailing arm front bushes deteriorated (5.3.4 (a) (i))

**MOT #16**

2022-09-26 11:21

**MOT test number**

208406640091

**Result**

✗ Failed

**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))

**Advice** Nearside Rear Outer Tyre has a cut but not deep enough to reach the ply or cords Tyre wall (5.2.3 (d) (i))

**Minor** Nearside Windscreen damaged but not adversely affecting driver's view Stone chip (3.2 (a) (i))

**Fail** Front Windscreen washer provides insufficient washer liquid (3.5 (a))

**Fail** Nearside Side repeater not working In mirror (4.4.1 (a) (ii))

**Advice** Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement o/s and n/s trailing arm front bushes deteriorated (5.3.4 (a) (i))

**MOT #15**

2021-09-24 09:44

**MOT test number**

427236289386

**Result**

✓ Passed

**Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

**Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))

**Advice** Suspension arm pin or bush worn but not resulting in excessive movement both rear trailing arm bushes (5.3.4 (a) (i))

**MOT #14** 2021-01-13 11:53**MOT test number** 978564924886**Result** ✓ Passed

**Advice** Suspension arm pin or bush worn but not resulting in excessive movement both rear trailing arms (5.3.4 (a) (i))

**MOT #13** 2021-01-13 11:53**MOT test number** 953258862192**Result** ✗ Failed

**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))

**Pass with rectification** Windscreen washer not working (3.5 (a))

**Advice** Suspension arm pin or bush worn but not resulting in excessive movement both rear trailing arms (5.3.4 (a) (i))

**MOT #12** 2020-01-22 09:06**MOT test number** 345634482616**Result** ✓ Passed

**Advice** Both front and O/S/R tyre worn inner edge

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Suspension arm pin or bush worn but not resulting in excessive movement Both rear trailing arm (5.3.4 (a) (i))

**MOT #11** 2018-08-06 16:09**MOT test number** 582493818916**Result** ✓ Passed

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #10** 2018-08-06 10:22**MOT test number** 341798114718**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #9** 2017-08-01 14:13**MOT test number** 114460617158**Result** ✓ Passed**Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #8** 2016-08-15 09:39**MOT test number** 237415194516**Result** ✓ Passed**MOT #7** 2015-08-10 16:41**MOT test number** 726952225271**Result** ✓ Passed**MOT #6** 2015-08-10 13:49**MOT test number** 898612125242**Result** ✗ Failed**Fail** Nearside Front Front position lamp(s) not working (1.1.A.3b)**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Offside Front Tie bar/rod severely distorted (2.4.G.1)

**MOT #5** 2015-01-14 10:45**MOT test number** 236944015048**Result** ✓ Passed**MOT #4** 2014-01-10 09:39**MOT test number** 267150614068**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #3** 2014-01-09 16:54**MOT test number** 469949104039**Result** ✗ Failed**Notice** Under-trays fitted obscuring some underside components**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #2** 2013-06-14 13:19**MOT test number** 415375863178**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



|                         |  |
|-------------------------|--|
| MOT #1                  | 2013-06-14 13:19   |
| MOT test number         | 719075663152   |
| Result                  | ✗ Failed   |
| Pass with rectification | Headlamp aim too high (1.8)                                |
| Advice                  | Offside Rear Tyre worn close to the legal limit (4.1.E.1)  |
| Advice                  | Nearside Rear Tyre worn close to the legal limit (4.1.E.1) |
| Advice                  | Rear Brake pad(s) wearing thin (3.5.1g)                    |





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
4 October 2024

|                         |                                 |
|-------------------------|---------------------------------|
| <b>Tax status</b>       | Valid until 1 November          |
| <b>Days left</b>        | 185                             |
| <b>MOT expiry date</b>  | 4 October 2024                  |
| <b>Full MOT history</b> | <a href="#">See MOT history</a> |

Tax calculation

|  |            |
|--|------------|
| <b>Vehicle class</b>                           | 49         |
| <b>Band</b>                                    | G          |
| <b>Single payment (12 months)</b>              | £ 240,00,- |
| <b>Single six month payment</b>                | £ 132,00,- |
| <b>Total payable by 12 monthly instalments</b> | £ 252,00,- |



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |       |
|-------|-------|
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |

More info >

Plate changes

See in this check if this FORD had different number plates.

|                      |            |
|----------------------|------------|
| Number of plates     | 1          |
| Current registration | *****      |
| Plate since          | 2019-03-29 |
| Current registration | *****      |
| Plate since          | 2019-03-29 |

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

|                   |            |      |
|-------------------|------------|------|
| Finance company   | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type    | XXXXXXXXXX | XXXX |
| Agreement term    | XXXXXXXXXX | XXXX |
| Agreement number  | XXXXXXXXXX | XXXX |
| Contact info      | XXXXXXXXXX | XXXX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 20                       |
| First mileage registration | 2010-07-22               |
| Last registration          | 2023-10-05               |
| Complete history           | <a href="#">See info</a> |



|                  |            |            |
|------------------|------------|------------|
| Registration #1  | 2010-07-22 | 17 mi      |
| Registration #2  | 2013-06-14 | 41.948 mi  |
| Registration #3  | 2014-01-09 | 44.521 mi  |
| Registration #4  | 2014-01-10 | 44.521 mi  |
| Registration #5  | 2015-01-14 | 69.378 mi  |
| Registration #6  | 2015-08-10 | 75.666 mi  |
| Registration #7  | 2015-08-10 | 75.666 mi  |
| Registration #8  | 2016-08-15 | 90.350 mi  |
| Registration #9  | 2017-08-01 | 104.181 mi |
| Registration #10 | 2018-08-06 | 118.508 mi |
| Registration #11 | 2019-08-06 | 132.835 mi |
| Registration #12 | 2020-08-06 | 147.162 mi |
| Registration #13 | 2021-08-06 | 161.489 mi |
| Registration #14 | 2022-08-06 | 175.816 mi |
| Registration #15 | 2023-08-06 | 190.143 mi |
| Registration #16 | 2024-08-06 | 204.470 mi |
| Registration #17 | 2025-08-06 | 218.797 mi |
| Registration #18 | 2026-08-06 | 233.124 mi |
| Registration #19 | 2027-08-06 | 247.451 mi |
| Registration #20 | 2028-08-06 | 261.778 mi |

More info >



Car features

The FORD factory car options list is only available in the premium report.

|       |                  |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1884 mm |
| Height              | 1658 mm |
| Length              | 4768 mm |
| Wheel base          | 2850 mm |
| Max. allowed weight | 2505 kg |

Additional information

|                    |                  |
|--------------------|------------------|
| Fuel tank capacity | 70 l             |
| Fuel delivery      | Direct Injection |
| Number of doors    | 5                |
| Number of seats    | 7                |
| Number of axles    | 2                |

Engine number

AU21080