



report date: 2024-03-29

General information

Make	VOLVO
Model	S60 D4 R-DESIGN LUX NAV
Colour	Grey
Year of manufacture	2016
Top speed	143 mph
0 - 60 mph	7.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	188 BHP
Max. torque	400 Nm at 1.750 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption city	67.3 mpg
Consumption extra urban	78.5 mpg
Consumption combined	74.3 mpg
CO2 emission	99 g/km
CO2 label	A






Internet history

Entry 1

Date	2021-06-05
Pictures	36
Listing price	View report



source: yesauto.com

**MOT history**

MOT expiry date	2024-10-22
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	12
Total items failed	2

MOT #6	2023-10-23 15:22
MOT test number	523836945339
Result	✓ Passed
Next expiry date	2024-10-22

MOT #5	2023-10-20 17:04
MOT test number	295201160356
Result	✗ Failed
Fail	Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

MOT #4	2022-10-19 10:35
MOT test number	960174892316
Result	✓ Passed
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #3** 2021-09-28 15:44**MOT test number** 899659558534**Result** ✓ Passed**Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Emissions too clean for reading**Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))**MOT #2** 2020-10-13 12:09**MOT test number** 210959837084**Result** ✓ Passed**Advice** Nearside Front Anti-roll bar linkage damaged but not seriously weakened (5.3.3 (b) (i))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #1** 2019-10-09 08:07**MOT test number** 435321728609**Result** ✓ Passed**Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Engine covers/undertrays**Advice** Rear Brake pad(s) wearing thin nearside very worn (1.1.13 (a) (ii))**Minor** Nearside Lower Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
22 October 2024

Tax status	Valid until 1 June
Days left	32
MOT expiry date	22 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2016-10-17
Last registration	2023-10-23
Complete history	See info



Registration #1	2016-10-17	12 mi
Registration #2	2019-10-09	35.243 mi
Registration #3	2020-10-13	39.737 mi
Registration #4	2020-10-13	39.737 mi
Registration #5	2020-10-13	39.737 mi
Registration #6	2020-10-13	39.737 mi
Registration #7	2020-10-13	39.737 mi
Registration #8	2020-10-13	39.737 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	98%
Children	75%
Pedestrian	88%
Safety systems	100%
Overall rating	92%
Video	see crash video



Dimensions & weight

Width	2041 mm
Height	1439 mm
Length	4369 mm
Wheel base	2647 mm
Kerb weight	1500 kg
Max. allowed weight	2005 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1542860