





report date: 2024-03-29

General information

Make	FORD
Model	RANGER XLT 4X4 TD
Colour	Silver
Year of manufacture	2005
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	266 Nm at 2.000 rpm
Engine capacity	2.500 cc
Cylinders	4
Fuel type	Diesel



CarCheck.co.uk page 1/16



report date: 2024-03-29


Internet history

Entry 1


Date 2021-07-16

Pictures 15

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/16



report date: 2024-03-29

MOT history

MOT expiry date	2022-07-26
MOT pass rate	58 %
MOT passed	14
Failed MOT tests	10
Total advice items	46
Total items failed	24

MOT #24		2021-07-27 15:53
MOT test	number	437892002351
Result		✓ Passed
Next expi	ry date	2022-07-26
Advice	Nearside Front Lower Shock absorbers has a slightly worn bush (5.3.2 (c))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))	
Advice	Radiator support panel corroded and holed	
Advice	Exhaust mounting defective center box clamp broken (6.1.2 (a))	
Advice	Front Brake pad(s) wearing thin on min thickness (1.1.13 (a) (ii))	

CarCheck.co.uk page 3/16



report date: 2024-03-29

MOT #23 2021-07-27 14:58 679124252156 **MOT** test number Result **★** Failed **Advice** Radiator support panel corroded and holed Advice Oil leak, but not excessive (8.4.1 (a) (i)) Advice Front Brake pad(s) wearing thin on min thickness (1.1.13 (a) (ii)) Fail Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i)) **Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e)) Advice Exhaust mounting defective center box clamp broken (6.1.2 (a)) Nearside Front Lower Shock absorbers has a slightly worn bush (5.3.2 (c)) Advice **Advice** Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))

MOT #22		2020-07-21 15:35
MOT test	number	515757894393
Result		✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Spare tyre defective flat	

MOT #21		2019-07-26 16:30
MOT test n	umber	647216292234
Result		✓ Passed
Advice	Spare tyre defective flat	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	

CarCheck.co.uk page 4/16



report date: 2024-03-29

MOT #20 2019-07-16 13:37

MOT test number 317908816674

Result ★ Failed

Fail Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Spare tyre defective flat

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #19 2018-07-17 16:56

MOT test number 721590833673

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Front tyres slight perishing

Advice Steering box has slight free play detected at steering wheel (2.3 (a) (i))

Advice Oil leak, but not excessive rear differential (8.4.1 (a) (i))

CarCheck.co.uk page 5/16



Advice

Front tyres slight perishing

WK05YMF

report date: 2024-03-29

MOT #18 2018-07-13 09:36 **MOT** test number 203980577904 Result × Failed Fail Rear fog lamp missing Broken off (4.5.1 (a) (ii)) **Advice** Oil leak, but not excessive rear differential (8.4.1 (a) (i)) Nearside Front Shock absorbers insecurely attached Lower bush failed (5.3.2 (a) (i)) Fail Fail Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii)) Fail Offside Front Position lamp not working (4.2.1 (a)) **Advice** Oil leak, but not excessive (8.4.1 (a) (i)) Fail Exhaust emissions exceed level of metered smoke for a turbo charged engine (8.2.2.2 (b)) Fail Offside Front Shock absorbers insecurely attached Lower bush failed (5.3.2 (a) (i)) **Advice** Steering box has slight free play detected at steering wheel (2.3 (a) (i))

MOT #17

MOT test number

Result

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT #16

MOT test number

751882393646

Result

Advice

Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice

Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

CarCheck.co.uk page 6/16



report date: 2024-03-29

MOT test number

883123484193

Result

Fail Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Fail Offside Front Inner Steering locking device missing Steering arm (2.2.C.1g)

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #14

MOT test number

Result

Pass with rectification

Windscreen washer provides insufficient washer liquid (8.2.3)

 MOT #13
 2015-06-20 11:48

 MOT test number
 548531875154

 Result
 ✓ Passed

 MOT #12
 2014-07-08 15:15

 MOT test number
 736039184146

 Result
 ✓ Passed

 Notice
 Rear exhuast mount very corroded

MOT #11

MOT test number

Result

Pass with rectification

Brake servo vacuum pipe collapsed (3.6.C.1b)

CarCheck.co.uk page 7/16



report date: 2024-03-29

 MOT #10
 2013-04-04 14:28

 MOT test number
 655194393085

MOT #9 2012-04-11 08:52

MOT test number 767642402110

Result ✓ Passed

MOT #8 2012-04-11 08:52

MOT test number 146772202184

Result X Failed

Pass with rectification Nearside Rear Direction indicator incorrect colour (1.4.A.2f)

MOT #7 2011-04-21 15:03

MOT test number 306361611184

Result
✓ Passed

Notice Off side rear leaf spring slightly displaced

Advice Steering system has slight free play detected at steering wheel (2.2.A.1a)

MOT #6 2010-04-22 08:30

MOT test number 302822410134

Result \(\sqrt{Passed} \)

Notice Nail in offside front tyre

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Shock absorber has a light misting of oil (2.7.3)

Notice Wear to inner edge of o/s/f tyre advise tracking check

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 8/16



report date: 2024-03-29

2009-04-24 17:56

2010-04-21 11:28 **MOT #5** 922671410187 **MOT** test number Result × Failed **Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1) Notice Nail in offside front tyre **Pass with rectification** Offside Front Headlamp not working on dipped beam (1.7.5a) Pass with rectification Front Windscreen washer provides insufficient washer liquid (8.2.3) Advice Nearside Rear Shock absorber has a light misting of oil (2.7.3) Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1) Notice Wear to inner edge of o/s/f tyre advise tracking check Pass with rectification Nearside Front Headlamp aim too low (1.8) Fail Centre Exhaust system not adequately supported (7.1.1)

MO1 #4	2009-04-24 17:56
MOT test number	294194319158
Result	✓ Passed
MOT #3	2009-04-21 15:04
MOT test number	774431919159
Result	X Failed
Fail Nearside Front position lamp(s) not working (1.1.A.3b)	
Fail Offside Rear position lamp(s) incorrect colour (1.1.A.3e)	
Fail Nearside Rear position lamp(s) incorrect colour (1.1.A.3e)	
Fail Offside Rear fog lamp not working (1.3.2b)	
Fail Nearside Rear position lamp(s) incorrect colour (1.1.A.3e)	

CarCheck.co.uk page 9/16



report date: 2024-03-29

MOT #	2	2008-02-21 11:30
MOT te	est number	434242358058
Result		✓ Passed
MOT #	1	2008-02-21 10:44
MOT te	est number	921132958091
Result		× Failed
Fail	Front registration plate character(s) likely to be misread (6.3.4b)	
Fail	Rear Rear fog lamp not working (1.3.2b)	
Fail	Windscreen washer provides insufficient washer liquid (8.2.3)	

CarCheck.co.uk page 10/16



report date: 2024-03-29

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 11/16



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 12/16



report date: 2024-03-29

\sim		
Owner	hictory	7
OWITCE	1113601	1

,		
For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report		ave?

	More info	>
Plate changes		
See in this check if this FORD had different number plates.		
Number of plates		
Current registration	NK SIE	III
Plate since		
Current registration	NK NK	
Plate since		
	More info	>

CarCheck.co.uk page 13/16



report date: 2024-03-29

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >


CarCheck.co.uk page 14/16



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2005-03-18
Last registration	2021-07-27
Complete history	See info



Registration #1	2005-03-18	18 mi
Registration #2	2008-02-21	72.751 mi
Registration #3	2008-02-21	72.751 mi
Registration #4	2009-04-21	51.143 mi
Registration #5	2009-04-24	51.148 mi
Registration #6	2010-04-21	62.026 mi
Registration #7	2010-04-22	62.026 mi
Registration #8	2011-04-21	71.176 mi
Registration #9	2012-04-11	78.461 mi
Registration #10	2013-04-04	82.865 mi
Registration #11	2014-07-08	88.390 mi
Registration #12	2015-06-20	94.257 mi
Registration #13		11.177 es
Registration #14		11.177 es
Registration #15		11.177 es
Registration #16		11.117 es
Registration #17		11.177 es
Registration #18		11.177 es
Registration #19		
Registration #20		0.074
Registration #20 Registration #21		11.777 es
-		11.777-00 11.777-00 11.777-00

More info >

CarCheck.co.uk page 15/16



report date: 2024-03-29

Car features

50225	Air conditioning
50295	
60482	
0501	
0566	
0567	
60569	

Additional information

Fuel tank capacity	70 I
Fuel delivery	Indirect Injection
Number of doors	4
Number of seats	5
Engine number	551939

CarCheck.co.uk page 16/16