



report date: 2024-03-28

General information

Make	NISSAN
Model	ALMERA SE
Colour	Silver
Year of manufacture	-
Top speed	108 mph
0 - 60 mph	13.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	121 BHP
Max. torque	128 Nm at 2.800 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	51.4 mpg
Consumption combined	42.8 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-05
Pictures	1
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT #17	2021-07-06 13:44
MOT test number	978552839125
Result	✓ Passed
Next expiry date	2022-07-05

MOT #16	2020-11-26 11:58
MOT test number	409646042717
Result	✓ Passed
Advice Nearside Rear Brake pipe corroded, covered in grease or other material near flexi. as marked. (1.1.11 (c))	
Advice Offside Rear Brake pipe corroded, covered in grease or other material near flexi. as marked. (1.1.11 (c))	

MOT #15	2019-11-27 12:02
MOT test number	406421101027
Result	✓ Passed
Advice Offside Rear Brake pipe corroded, covered in grease or other material slightly corroded to flexible hose pipe (1.1.11 (c))	
Advice Nearside Rear Brake pipe corroded, covered in grease or other material slightly corroded to flexible hose pipe (1.1.11 (c))	
Advice Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive near trailing arm front bush (5.3.6 (a) (i))	

MOT #14	2018-11-26 14:46
MOT test number	297108343375
Result	✓ Passed
Advice Offside Rear Tyre worn close to legal limit/worn on edge wearing on edges of tyre tread face (5.2.3 (e))	
Advice Note;- Nearside rear alloy corroded on inner wheel.	
Advice Nearside Rear Nail in tyre on tyre tread face	
Advice Note;- Offside rear alloy corroded on inner wheel.	

**MOT #13** 2017-11-30 15:16**MOT test number** 662841845998**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #12** 2017-11-30 11:59**MOT test number** 587353992179**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened brake discs severely pitted and corroded (3.5.1i)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #11** 2016-11-28 14:05**MOT test number** 623374745764**Result** ✓ Passed**MOT #10** 2015-11-24 10:45**MOT test number** 609933186793**Result** ✓ Passed**Advice** Rear registration plate faded but not likely to be misread (6.3.1d)

**MOT #9** 2014-11-17 13:16**MOT test number** 248111624395**Result** ✓ Passed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Rear registration plate faded but not likely to be misread (6.3.1d)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #8** 2013-11-25 13:04**MOT test number** 277919123375**Result** ✓ Passed**MOT #7** 2013-11-25 13:04**MOT test number** 199649723392**Result** ✗ Failed**Pass with rectification** Parking brake lever has no reserve travel (3.1.6b)**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #6** 2012-11-22 15:05**MOT test number** 269567622331**Result** ✓ Passed**MOT #5** 2011-11-23 10:44**MOT test number** 747177421383**Result** ✓ Passed**MOT #4** 2010-11-26 16:27**MOT test number** 872220130380**Result** ✓ Passed

**MOT #3** 2010-11-25 14:49**MOT test number** 480799820368**Result** ✗ Failed**Notice** Nail in nearside rear tyre**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Notice** Off side front tyre worn to 3mm PLUS worn on edges**Notice** Rear brake pads replaced on service**MOT #2** 2009-11-23 11:56**MOT test number** 923467129366**Result** ✓ Passed**Notice** Off side rear outer brake pad approx 60% to 70% worn**Notice** Off side front tyre worn to 3mm**Notice** Nail in nearside rear tyre**MOT #1** 2008-11-18 10:54**MOT test number** 214333328368**Result** ✓ Passed**Notice** Note;- rear brakes squealing.**Advice** Front brake disc slightly scored (3.5.1h)



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2005-11-30
Last registration	2021-07-06
Complete history	See info



Registration #1	2005-11-30	13 mi
Registration #2	2008-11-18	14.552 mi
Registration #3	2009-11-23	16.561 mi
Registration #4	2010-11-25	18.295 mi
Registration #5	2010-11-26	18.300 mi
Registration #6	2011-11-23	19.883 mi
Registration #7	2012-11-22	21.697 mi
Registration #8	2013-11-25	23.120 mi
Registration #9	2014-11-17	24.899 mi
Registration #10	2015-11-17	26.377 mi
Registration #11	2016-11-17	27.855 mi
Registration #12	2017-11-17	29.333 mi
Registration #13	2018-11-17	30.811 mi
Registration #14	2019-11-17	32.289 mi
Registration #15	2020-11-17	33.767 mi
Registration #16	2021-07-06	35.245 mi
Registration #17	2021-07-06	35.245 mi
Registration #18	2021-07-06	35.245 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1706 mm
Height	1448 mm
Length	4184 mm
Wheel base	2535 mm
Kerb weight	1190 kg
Max. allowed weight	1710 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	319019