




report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	BEETLE LUNA 8V
Colour	Black
Year of manufacture	2007
Top speed	111 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	102 BHP
Max. torque	147 Nm at 3.800 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.7 mpg
Consumption extra urban	46.3 mpg
Consumption combined	36.2 mpg
CO2 emission	185 g/km
CO2 label	I





## Internet history

### Entry 3

Date	2022-07-27
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)

### Entry 2


Date	2022-04-27
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)

### Entry 1

Date	2021-06-07
Pictures	1
Listing price	<a href="#">View report</a>



source: [yesauto.com](#)



## MOT history

MOT expiry date	2024-05-17
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	24
Total items failed	2

MOT #18	2023-05-18 09:53
MOT test number	860191250756
Result	✓ Passed
Next expiry date	2024-05-17

MOT #17	2022-06-14 10:48
MOT test number	963370337638
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16	2021-06-25 13:02
MOT test number	991341345421
Result	✓ Passed

**MOT #15** 2021-06-15 11:54**MOT test number** 985019471736**Result** ✗ Failed

**MAJOR** Nearside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

**MAJOR** Nearside Front Inner Suspension arm pin or bush excessively worn rear (5.3.4 (a) (i))

**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**Advice** Nearside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MAJOR** Offside Side repeater not working (4.4.1 (a) (ii))

**MAJOR** Offside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

**MAJOR** Offside Front Inner Suspension arm pin or bush excessively worn rear (5.3.4 (a) (i))

**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**MAJOR** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

**Advice** Offside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #14** 2020-08-06 08:50**MOT test number** 447237909537**Result** ✓ Passed**MOT #13** 2019-08-13 08:01**MOT test number** 348046940697**Result** ✓ Passed**MOT #12** 2018-08-14 15:21**MOT test number** 139159403975**Result** ✓ Passed

**MOT #11** 2018-08-10 10:30**MOT test number** 704869813808**Result** ✗ Failed**MAJOR** Windscreen washer provides insufficient washer liquid (3.5 (a))**MAJOR** Emissions not tested due to misfire (8.2.1.2 (d))**MAJOR** Driver's view of the road through the swept area of the windscreen materially affected by an obstruction (3.1 (a) (ii))**MOT #10** 2017-08-12 09:33**MOT test number** 476343169371**Result** ✓ Passed**MOT #9** 2016-08-27 13:29**MOT test number** 340413113703**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Child Seat fitted not allowing full inspection of adult belt**MOT #8** 2015-08-26 09:33**MOT test number** 614599364421**Result** ✓ Passed**MOT #7** 2015-08-25 13:39**MOT test number** 606334149282**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Rear coil spring broken (2.4.C.1a)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #6** 2014-12-18 10:58**MOT test number** 309452854330**Result** ✓ Passed**Notice** Nearside rear tyre cracking**Notice** Nearside front tyre wearing on outer edge**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #5** 2013-12-03 12:03**MOT test number** 419727833437**Result** ✓ Passed**MOT #4** 2012-12-20 10:41**MOT test number** 497455952424**Result** ✓ Passed**MOT #3** 2011-12-06 15:25**MOT test number** 319740041382**Result** ✓ Passed**MOT #2** 2011-12-06 09:06**MOT test number** 499590341437**Result** ✗ Failed**Fail** Offside Obligatory mirror insecure (8.1.1)**Notice** Front brake discs slightly corroded**MOT #1** 2010-12-08 10:56**MOT test number** 140232940355**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
17 May 2024

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	63
<b>MOT expiry date</b>	17 May 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 EN57KXX
Plate since	2019-06-29
Current registration	 EN57KXX
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-12-24
Last registration	2023-05-18
Complete history	<a href="#">See info</a>



Registration #1	2007-12-24	22 mi
Registration #2	2010-12-08	19.337 mi
Registration #3	2011-12-06	22.681 mi
Registration #4	2011-12-06	22.681 mi
Registration #5	2012-12-20	24.356 mi
Registration #6	2013-12-03	25.248 mi
Registration #7	2014-12-18	29.506 mi
Registration #8	2015-08-25	31.726 mi
Registration #9	2015-08-26	31.726 mi
Registration #10	2016-08-27	41.819 mi
Registration #11	2017-08-12	50.890 mi
Registration #12	2018-05-22	55.377 mi
Registration #13	2018-05-22	55.377 mi
Registration #14	2018-05-22	55.377 mi
Registration #15	2018-05-22	55.377 mi
Registration #16	2018-05-22	55.377 mi
Registration #17	2018-05-22	55.377 mi
Registration #18	2018-05-22	55.377 mi
Registration #19	2018-05-22	55.377 mi
Registration #20	2018-05-22	55.377 mi
Registration #21	2018-05-22	55.377 mi
Registration #22	2018-05-22	55.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1724 mm
Height	1502 mm
Length	4081 mm
Wheel base	2516 mm
Kerb weight	1393 kg
Max. allowed weight	1770 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	2

Number of seats	4
Number of axles	2
Engine number	BFS 062004