




report date: 2024-03-28

General information

Make	VOLVO
Model	S40 SPORT D V50
Colour	White
Year of manufacture	2009
Top speed	127 mph
0 - 60 mph	9.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	49.6 mpg
CO2 emission	153 g/km
CO2 label	G





Internet history

Entry 2

Date	2023-12-11
Pictures	8



source: g3remarketing.co.uk

Entry 1

Date	2021-06-08
Pictures	13
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-01-27
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	34
Total items failed	8

**MOT #16**

2024-04-15 14:59

MOT test number

972440154239

Result**✗ Failed****MAJOR** Brake performance unable to be tested (1.2.1 (g))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))**MAJOR** Nearside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))**MAJOR** Nearside Rear Tyre fouling a part of the vehicle (5.2.3 (f))**MAJOR** Offside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**MAJOR** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**MAJOR** Emissions unable to be completed (8.2.2.2 (e))**DANGEROUS** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MAJOR** Front Windscreen washer provides insufficient washer liquid (3.5 (a))**MAJOR** Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))**MAJOR** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**MAJOR** Nearside Front Tyre(s) of different sizes are fitted on the same axle. (5.2.3 (b))**DANGEROUS** Offside Front Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))**MAJOR** Nearside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**MAJOR** Offside Rear Tyre fouling a part of the vehicle (5.2.3 (f))**MAJOR** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MAJOR** Front Registration plate does not conform to the specified requirements not fitted (0.1 (d))**MAJOR** Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Minor** Front fog lamp insecure not working due to no bulb in one and not connected (4.5.1 (c) (i))**DANGEROUS** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MAJOR** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

**MOT #15** 2023-01-05 16:00**MOT test number** 481878588148**Result** ✓ Passed**Advice** Rear Tyre worn close to legal limit/worn on edge both (5.2.3 (e))**MOT #14** 2022-01-28 16:47**MOT test number** 816311701826**Result** ✓ Passed**MOT #13** 2020-12-22 10:36**MOT test number** 608530986700**Result** ✓ Passed**Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #12** 2019-06-24 14:47**MOT test number** 770357099854**Result** ✓ Passed**MOT #11** 2018-07-04 12:02**MOT test number** 163499668619**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))**MOT #10** 2018-07-04 12:02**MOT test number** 821115746290**Result** ✗ Failed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))**Pass with rectification** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**MOT #9** 2017-07-06 08:41**MOT test number** 186889997175**Result** ✓ Passed**MOT #8** 2016-07-14 15:18**MOT test number** 617205654763**Result** ✓ Passed**Advice** Nearside Rear tyre worn on inner edge**MOT #7** 2016-07-13 09:53**MOT test number** 892611627246**Result** ✗ Failed**Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)**Advice** Nearside Rear Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)**Advice** Nearside Rear tyre worn on inner edge**Fail** Nearside Front Valve stem seriously damaged (4.1.D.1e)**Fail** Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Advice** Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**MOT #6** 2015-05-07 17:28**MOT test number** 945297325165**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Nearside Rear Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)

**MOT #5** 2015-05-07 17:28**MOT test number** 519207825186**Result** ✗ Failed**Notice** Child seat fitted not allowing full inspection of adult belt**Pass with rectification** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Rear Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)**Pass with rectification** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #4** 2014-04-23 14:13**MOT test number** 485633714162**Result** ✓ Passed**MOT #3** 2013-04-12 09:33**MOT test number** 946912803118**Result** ✓ Passed**MOT #2** 2012-04-12 15:29**MOT test number** 308623702166**Result** ✓ Passed**MOT #1** 2012-04-12 14:29**MOT test number** 585383102111**Result** ✗ Failed**Fail** Nearside Inner Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**Fail** Offside Inner Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✗
MOT

Expired:
27 January 2024

Tax status	Valid until 1 June
Days left	34
MOT expiry date	27 January 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	PE09VVG
Plate since	2024-03-28
Current registration	PE09VVG
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-05-08
Last registration	2024-04-15
Complete history	See info



Registration #1	2009-05-08	24 mi
Registration #2	2012-04-12	40.843 mi
Registration #3	2012-04-12	40.843 mi
Registration #4	2013-04-12	53.464 mi
Registration #5	2014-04-23	68.380 mi
Registration #6	2015-05-07	79.357 mi
Registration #7	2016-07-13	89.522 mi
Registration #8	2016-07-14	89.524 mi
Registration #9	2017-07-06	97.128 mi
Registration #10	2018-05-22	100,000
Registration #11	2019-05-22	100,000
Registration #12	2020-05-22	100,000
Registration #13	2021-05-22	100,000
Registration #14	2022-05-22	100,000
Registration #15	2023-05-22	100,000
Registration #16	2024-05-22	100,000
Registration #17	2025-05-22	100,000

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1489 kg
Max. allowed weight	1960 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	521737