



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	GOLF LUNA TDI (90BHP)
Colour	Grey
Year of manufacture	2008
Top speed	114 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	103 BHP
Max. torque	250 Nm at 1.900 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	39.8 mpg
Consumption extra urban	58.9 mpg
Consumption combined	50.4 mpg
CO2 emission	146 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-06-18
Pictures	11
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-07-23
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	27
Total items failed	3

MOT #16 2023-07-24 13:32

MOT test number 934324667480

Result ✓ Passed

Next expiry date 2024-07-23

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #15 2022-07-09 12:59

MOT test number 620570179092

Result ✓ Passed

Minor Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt x1

Minor Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Offside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #14** 2021-07-19 10:03**MOT test number** 456019745030**Result** ✓ Passed**MOT #13** 2020-06-17 11:50**MOT test number** 471500299821**Result** ✓ Passed

Minor Offside Front Windscreen damaged but not adversely affecting driver's view Offside front area of windscreen has multiple small stone chips less than 10mm in diameter in zone "a", and scratched. (3.2 (a) (i))

Minor Nearside Front Lower Windscreen damaged but not adversely affecting driver's view Nearside lower area of front windscreen has a stone chip larger than 10mm, but smaller than 40mm and is outside zone "a". (3.2 (a) (i))

MOT #12 2019-06-11 14:41**MOT test number** 150083487604**Result** ✓ Passed

Advice Stone chip outside zone "a" and less than 40mm in diameter.

Advice Stone chip in nearside front of windscreen, outside "zone a" and less than 40mm in diameter.

MOT #11 2018-06-18 14:42**MOT test number** 350549490124**Result** ✓ Passed**MOT #10** 2017-06-05 13:05**MOT test number** 126093028379**Result** ✓ Passed

Advice Nearside Lower Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #9 2016-06-09 13:11**MOT test number** 495879544247**Result** ✓ Passed

Advice
(8.3.1d)

Nearside Front Lower Windscreen has damage to an area less than a 40mm circle outside zone 'A'

**MOT #8** 2015-06-02 11:45**MOT test number** 888293755108**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #7** 2014-06-03 16:43**MOT test number** 319964454102**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #6** 2014-06-03 11:24**MOT test number** 318804354170**Result** ✗ Failed**Notice** Under-trays fitted obscuring some underside components**Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)**Notice** Engine undertray loose,two fixing bolts missing.**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2013-06-06 16:13**MOT test number** 266807853474**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**MOT #4** 2012-06-02 09:30**MOT test number** 799784152161**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #3** 2012-06-01 15:43**MOT test number** 439313452134**Result** ✗ Failed**Notice** Nail in nearside rear tyre**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #2** 2011-06-07 13:51**MOT test number** 326738451197**Result** ✓ Passed**MOT #1** 2011-06-06 16:09**MOT test number** 657507651172**Result** ✗ Failed**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
23 July 2024

Tax status	Valid until 1 July
Days left	62
MOT expiry date	23 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 LB08XSW
Plate since	2024-03-29
Current registration	 LB08XSW
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-06-28
Last registration	2023-07-24
Complete history	See info



Registration #1	2008-06-28	13 mi
Registration #2	2011-06-06	17.030 mi
Registration #3	2011-06-07	17.030 mi
Registration #4	2012-06-01	24.069 mi
Registration #5	2012-06-02	24.069 mi
Registration #6	2013-06-06	30.746 mi
Registration #7	2014-06-03	37.435 mi
Registration #8	2014-06-03	37.435 mi
Registration #9	2015-06-02	45.606 mi
Registration #10	2015-06-02	45.606 mi
Registration #11	2015-06-02	45.606 mi
Registration #12	2015-06-02	45.606 mi
Registration #13	2015-06-02	45.606 mi
Registration #14	2015-06-02	45.606 mi
Registration #15	2015-06-02	45.606 mi
Registration #16	2015-06-02	45.606 mi
Registration #17	2015-06-02	45.606 mi
Registration #18	2015-06-02	45.606 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1759 mm
Height	1580 mm
Length	4206 mm
Wheel base	2578 mm
Kerb weight	1395 kg
Max. allowed weight	2000 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	BXE 704307