



report date: 2024-03-28

General information

|                     |                |
|---------------------|----------------|
| Make                | VOLKSWAGEN     |
| Model               | GOLF GT TDI    |
| Colour              | White          |
| Year of manufacture | 2010           |
| Top speed           | 130 mph        |
| Gearbox             | 6 speed Manual |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 140 BHP             |
| Max. torque             | 320 Nm at 1.750 rpm |
| Engine capacity         | 1.968 cc            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 44.1 mpg            |
| Consumption extra urban | 70.6 mpg            |
| Consumption combined    | 57.7 mpg            |
| CO2 emission            | 126 g/km            |
| CO2 label               | D                   |





Internet history

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-02-06                  |
| Pictures      | 1                           |
| Listing price | <a href="#">View report</a> |



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2024-12-09 |
| MOT pass rate      | 68 %       |
| MOT passed         | 13         |
| Failed MOT tests   | 6          |
| Total advice items | 32         |
| Total items failed | 18         |

|                  |  |
|------------------|--|
| MOT #19          | 2023-12-08 15:26   |
| MOT test number  | 266521663395   |
| Result           | ✓ Passed   |
| Next expiry date | 2024-12-09   |
| Advice           | Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush both sides (5.3.4 (a) (i)) |
| Advice           | Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))  |
| Advice           | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))   |

|                 |  |
|-----------------|--|
| MOT #18         | 2023-12-08 11:33   |
| MOT test number | 943255547437   |
| Result          | ✗ Failed   |
| Advice          | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))   |
| Fail            | Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))   |
| Advice          | Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush both sides (5.3.4 (a) (i)) |
| Advice          | Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))  |

**MOT #17**

2022-12-07 17:12

**MOT test number**

305847635881

**Result**

✓ Passed

**Advice**

Front Service brake fluctuating, but not excessively Both fronts (1.2.1 (e))

**Advice**

Rear Suspension arm corroded but not seriously weakened Both rears (5.3.3 (b) (i))

**MOT #16**

2022-12-06 11:09

**MOT test number**

437824854614

**Result**

✗ Failed

**Fail**

Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

**Fail**

Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

**Advice**

Front Service brake fluctuating, but not excessively Both fronts (1.2.1 (e))

**Fail**

Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

**Minor**

Offside Front Tyre obviously under inflated (5.2.3 (l))

**Fail**

Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

**Fail**

Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**Advice**

Rear Suspension arm corroded but not seriously weakened Both rears (5.3.3 (b) (i))

**MOT #15**

2021-12-07 14:54

**MOT test number**

936143099262

**Result**

✓ Passed

**Advice**

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice**

Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #14**

2021-12-07 10:30

**MOT test number**

212894557230

**Result****✗ Failed**

- Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Fail** Nearside Front Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Offside Front Inner Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Pass with rectification** Windscreen washer not working (3.5 (a))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #13**

2020-12-10 14:14

**MOT test number**

656876653039

**Result****✓ Passed****MOT #12**

2020-12-09 14:58

**MOT test number**

651431647593

**Result****✗ Failed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Fail** Offside Front Coil spring with an unsafe modification strut top mounting, spring not located correctly (5.3.1 (d) (i))
- Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Offside Rear Service brake excessively binding (1.2.1 (f))
- Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #11** 2020-08-04 07:56**MOT test number** 578967852339**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #10** 2019-08-02 15:25**MOT test number** 425108095770**Result** ✓ Passed**MOT #9** 2019-08-01 15:48**MOT test number** 755138996333**Result** ✗ Failed**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #8** 2018-08-16 16:27**MOT test number** 792594066374**Result** ✓ Passed**MOT #7** 2017-09-11 16:23**MOT test number** 502703858701**Result** ✓ Passed**MOT #6** 2016-09-26 12:54**MOT test number** 278239890507**Result** ✓ Passed



|                        |                      |
|------------------------|----------------------|
| <b>MOT #5</b>          | 2016-01-08 09:45     |
| <b>MOT test number</b> | 266633197832         |
| <b>Result</b>          | ✓ Passed             |
| <b>Advice</b>          | Engine covers fitted |
| <b>Advice</b>          | Under trays fitted   |

|                        |  |
|------------------------|--|
| <b>MOT #4</b>          | 2015-01-08 08:25   |
| <b>MOT test number</b> | 476148005036   |
| <b>Result</b>          | ✓ Passed   |
| <b>Notice</b>          | Under-trays fitted obscuring some underside components           |
| <b>Notice</b>          | Middle exhaust clamp corroded                                    |
| <b>Notice</b>          | Engine covers fitted obscuring some components in the engine bay |

|                        |  |
|------------------------|--|
| <b>MOT #3</b>          | 2015-01-07 15:06   |
| <b>MOT test number</b> | 359917005074   |
| <b>Result</b>          | ✗ Failed   |
| <b>Notice</b>          | Middle exhaust clamp corroded                                    |
| <b>Fail</b>            | Rear fog lamp not working (1.3.2b)                               |
| <b>Notice</b>          | Engine covers fitted obscuring some components in the engine bay |
| <b>Fail</b>            | Rear fog lamp switch faulty (1.3.1a)                             |
| <b>Notice</b>          | Under-trays fitted obscuring some underside components           |
| <b>Fail</b>            | Rear fog lamp tell tale not working (1.3.1b)                     |



|                 |  |
|-----------------|--|
| MOT #2          | 2014-01-14 12:45   |
| MOT test number | 437834514018   |
| Result          | ✓ Passed   |
| Notice          | Engine covers fitted obscuring some components in the engine bay |
| Notice          | Under-trays fitted obscuring some underside components           |

|                 |  |
|-----------------|--|
| MOT #1          | 2013-01-08 12:45   |
| MOT test number | 849098303048   |
| Result          | ✓ Passed   |
| Notice          | Engine covers fitted obscuring some components in the engine bay |
| Notice          | Under-trays fitted obscuring some underside components           |





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 December 2024

✓  
**MOT**  
**Expires:**  
9 December 2024

|                         |                                 |
|-------------------------|---------------------------------|
| <b>Tax status</b>       | Valid until 1 December          |
| <b>Days left</b>        | 216                             |
| <b>MOT expiry date</b>  | 9 December 2024                 |
| <b>Full MOT history</b> | <a href="#">See MOT history</a> |

Tax calculation

|  |            |
|--|------------|
| <b>Vehicle class</b>                           | 49         |
| <b>Band</b>                                    | D          |
| <b>Single payment (12 months)</b>              | £ 150,00,- |
| <b>Single six month payment</b>                | £ 82,50,-  |
| <b>Total payable by 12 monthly instalments</b> | £ 157,50,- |



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |              |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

|                      |   |
|----------------------|---|
| Number of plates     | 1   |
| Current registration |  ST59XEZ |
| Plate since          | 2019-06-29  |
| Current registration |  ST59XEZ |
| Plate since          | 2019-06-29  |

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

|                   |          |      |
|-------------------|----------|------|
| Finance company   | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type    | XXXXXXXX | XXXX |
| Agreement term    | XXXXXXXX | XXXX |
| Agreement number  | XXXXXXXX | XXXX |
| Contact info      | XXXXXXXX | XXXX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 21                       |
| First mileage registration | 2010-01-15               |
| Last registration          | 2023-12-08               |
| Complete history           | <a href="#">See info</a> |



|                  |            |           |
|------------------|------------|-----------|
| Registration #1  | 2010-01-15 | 10 mi     |
| Registration #2  | 2013-01-08 | 24.278 mi |
| Registration #3  | 2014-01-14 | 32.472 mi |
| Registration #4  | 2015-01-07 | 38.324 mi |
| Registration #5  | 2015-01-08 | 38.324 mi |
| Registration #6  | 2016-01-08 | 44.583 mi |
| Registration #7  | 2016-09-26 | 49.596 mi |
| Registration #8  | 2017-09-11 | 60.847 mi |
| Registration #9  | 2018-08-16 | 72.180 mi |
| Registration #10 | 2019-08-01 | 83.968 mi |
| Registration #11 | 2019-08-02 | 83.968 mi |
| Registration #12 | 2019-08-02 | 83.968 mi |
| Registration #13 | 2019-08-02 | 83.968 mi |
| Registration #14 | 2019-08-02 | 83.968 mi |
| Registration #15 | 2019-08-02 | 83.968 mi |
| Registration #16 | 2019-08-02 | 83.968 mi |
| Registration #17 | 2019-08-02 | 83.968 mi |
| Registration #18 | 2019-08-02 | 83.968 mi |
| Registration #19 | 2019-08-02 | 83.968 mi |
| Registration #20 | 2019-08-02 | 83.968 mi |
| Registration #21 | 2019-08-02 | 83.968 mi |

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

|       |                  |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

|                |                                 |
|----------------|---------------------------------|
| NCAP rating    | ★★★★★                           |
| Adult          | 97%                             |
| Children       | 84%                             |
| Pedestrian     | 61%                             |
| Safety systems | 71%                             |
| Overall rating | 85%                             |
| Video          | <a href="#">see crash video</a> |



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1786 mm |
| Height              | 1479 mm |
| Length              | 4199 mm |
| Wheel base          | 2578 mm |
| Kerb weight         | 1299 kg |
| Max. allowed weight | 1910 kg |

Additional information

|                    |                  |
|--------------------|------------------|
| Fuel tank capacity | 55 l             |
| Fuel delivery      | Direct Injection |
| Number of doors    | 3                |

|                 |            |
|-----------------|------------|
| Number of seats | 5          |
| Number of axles | 2          |
| Engine number   | CFF 127555 |