



report date: 2024-03-29

General information

Make	FORD
Model	FUSION ZETEC
Colour	Blue
Year of manufacture	2010
Top speed	107 mph
0 - 60 mph	13.6 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	100 BHP
Max. torque	149 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	48.7 mpg
Consumption combined	37.7 mpg
CO2 emission	179 g/km
CO2 label	I





report date: 2024-03-29

Entry 2

Listing price [View report](#)

Entry 1

Listing price [View report](#)



page 2/12



MOT history

MOT expiry date	2024-08-02
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	15
Total items failed	0

MOT #13	2023-07-07 12:07
MOT test number	956101150448
Result	✓ Passed
Next expiry date	2024-08-02
Advice	Registration plate deteriorated but not likely to be misread front and rear (0.1 (b))
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

MOT #12	2023-07-07 11:28
MOT test number	412089269784
Result	✗ Failed
MAJOR	Offside Rear fog lamp not working (4.5.1 (a) (ii))
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Registration plate deteriorated but not likely to be misread front and rear (0.1 (b))

MOT #11	2022-07-08 08:04
MOT test number	700119161286
Result	✓ Passed
Advice	Power steering close to minimum mark (2.1.5 (b) (i))

**MOT #10** 2021-07-29 07:39**MOT test number** 975325866351**Result** ✓ Passed**MOT #9** 2021-07-27 15:14**MOT test number** 710207173503**Result** ✗ Failed

DANGEROUS Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

DANGEROUS Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

DANGEROUS Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MAJOR Offside Rear Position lamp not working (4.2.1 (a) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #8 2020-08-03 14:37**MOT test number** 926780571669**Result** ✓ Passed**MOT #7** 2019-04-18 14:13**MOT test number** 532613038131**Result** ✓ Passed

Advice Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #6 2018-04-12 07:55**MOT test number** 730026710873**Result** ✓ Passed

Advice Offside Rear Direction indicators slightly discoloured (1.4.A.2f)



MOT #5	2017-04-25 11:13
---------------	------------------

MOT test number	649989920358
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2016-04-13 09:54
---------------	------------------

MOT test number	996695312660
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2015-04-14 11:32
---------------	------------------

MOT test number	709424405193
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2014-04-17 11:19
---------------	------------------

MOT test number	416727104123
------------------------	--------------

Result	✓ Passed
---------------	----------

Notice	Nail in offside rear tyre
---------------	---------------------------

MOT #1	2013-05-08 15:00
---------------	------------------

MOT test number	469558123148
------------------------	--------------

Result	✓ Passed
---------------	----------



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
2 August 2024

Tax status	Valid until 1 August
Days left	93
MOT expiry date	2 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-06-24
Last registration	2023-07-07
Complete history	See info



Registration #1	2010-06-24	24 mi
Registration #2	2013-05-08	8.146 mi
Registration #3	2014-04-17	9.103 mi
Registration #4	2015-04-14	9.859 mi
Registration #5	2016-04-13	10.712 mi
Registration #6	2017-04-25	11.715 mi
Registration #7	2018-04-12	13.264 mi
Registration #8	2019-04-18	14.136 mi
Registration #9	2020-05-20	15.277 mi
Registration #10	2021-05-20	16.277 mi
Registration #11	2022-05-20	17.277 mi
Registration #12	2023-05-20	18.277 mi
Registration #13	2024-05-20	19.277 mi
Registration #14	2025-05-20	20.277 mi
Registration #15	2026-05-20	21.277 mi
Registration #16	2027-05-20	22.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2019 mm
Height	1500 mm
Length	4337 mm
Wheel base	2640 mm
Kerb weight	1314 kg
Max. allowed weight	1835 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	AP59922