



HONDA



report date: 2024-03-28

General information

Make	HONDA
Model	FR-V I-VTEC ES
Colour	Black
Year of manufacture	2009
Top speed	118 mph
0 - 60 mph	10.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	174 Nm at 4.300 rpm
Engine capacity	1.799 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.1 mpg
Consumption extra urban	44.8 mpg
Consumption combined	37.7 mpg
CO2 emission	177 g/km
CO2 label	I






Internet history

Entry 1

Date	2021-10-28
Pictures	8
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-11-22
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	26
Total items failed	3

MOT #16	2023-11-18 13:34
MOT test number	591679164066
Result	✓ Passed
Next expiry date	2024-11-22

MOT #15	2022-11-05 13:19
MOT test number	978307170109
Result	✓ Passed
Minor	Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Minor	Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

MOT #14	2021-11-23 13:22
MOT test number	598812966015
Result	✓ Passed

**MOT #13**

2021-11-22 16:32

MOT test number

906934803655

Result**✗ Failed**

- MAJOR** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #12

2021-10-13 08:44

MOT test number

854174839474

Result**✗ Failed**

- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Brake pedal rubber split
- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Minor** Offside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- MAJOR** Rear Brakes imbalanced across an axle (1.2.1 (b) (i))
- Advice** Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))
- Minor** Nearside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

MOT #11

2020-10-01 14:06

MOT test number

987534511393

Result**✓ Passed**

- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #10** 2020-10-01 10:57**MOT test number** 987506506165**Result** ✗ Failed**MAJOR** Nearside Rear Service brake excessively binding (1.2.1 (f))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #9** 2019-04-09 08:09**MOT test number** 587720683994**Result** ✓ Passed**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #8** 2018-03-23 09:50**MOT test number** 853559948547**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #7** 2017-04-20 13:26**MOT test number** 503303151656**Result** ✓ Passed**MOT #6** 2016-04-26 10:54**MOT test number** 814913594031**Result** ✓ Passed**Advice** Offside Front Inner Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Inner Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2015-04-14 13:37**MOT test number** 719784505176**Result** ✓ Passed

**MOT #4** 2015-04-14 13:37**MOT test number** 238464005462**Result** ✗ Failed**Pass with rectification** Offside Stop lamp not working (1.2.1b)**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #3** 2014-04-09 13:45**MOT test number** 946129994094**Result** ✓ Passed**Notice** N/S/F TYRE WEARING ON OUTER EDGE , O/S/F TYRE WEARING ON INNER EDGE**MOT #2** 2014-04-09 13:45**MOT test number** 658839494024**Result** ✗ Failed**Notice** N/S/F TYRE WEARING ON OUTER EDGE , O/S/F TYRE WEARING ON INNER EDGE**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #1** 2012-11-15 11:00**MOT test number** 735920522351**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
22 November 2024

Tax status	Valid until 1 October
Days left	156
MOT expiry date	22 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-10-31
Last registration	2023-11-18
Complete history	See info



Registration #1	2009-10-31	10 mi
Registration #2	2012-11-15	27.399 mi
Registration #3	2014-04-09	37.554 mi
Registration #4	2015-04-14	45.589 mi
Registration #5	2016-04-26	52.794 mi
Registration #6	2017-04-20	59.121 mi
Registration #7	2018-03-23	64.401 mi
Registration #8	2019-04-09	67.217 mi
Registration #9	2020-05-20	70.277 mi
Registration #10	2021-05-20	73.277 mi
Registration #11	2022-05-20	76.277 mi
Registration #12	2023-05-20	79.277 mi
Registration #13	2024-05-20	82.277 mi
Registration #14	2025-05-20	85.277 mi
Registration #15	2026-05-20	88.277 mi
Registration #16	2027-05-20	91.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1810 mm
Height	1610 mm
Length	4285 mm
Wheel base	2680 mm
Kerb weight	1423 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	6
Number of axles	2
Engine number	R18A13301962