



RENAULT

BV07AHD

report date: 2024-03-29

General information

Make	RENAULT
Model	KANGOO SL17 DCI 70 +
Colour	White
Year of manufacture	2007
Top speed	92 mph
0 - 60 mph	16.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	160 Nm at 1.500 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.1 mpg
Consumption extra urban	54.3 mpg
Consumption combined	51.4 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-10-05
Pictures	9
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2022-09-19
MOT pass rate	59 %
MOT passed	13
Failed MOT tests	9
Total advice items	36
Total items failed	16

MOT #22	2021-09-20 12:07
MOT test number	530751540628
Result	✓ Passed
Next expiry date	2022-09-19
Advice	Play in steering rack inner joint(s)
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

**MOT #21**

2021-09-20 09:03

MOT test number

212224988484

Result**✗ Failed**

- Advice** Nearside Rear Position lamp slightly affected by the operation of another lamp (4.2.3 (c))
- Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))
- Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Play in steering rack inner joint(s)
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Nearside Rear Hydraulic brake cylinder leaking hydraulic fluid (1.1.16 (b) (i))
- Fail** Rear Registration plate inscription illegible (0.1 (b))

MOT #20

2020-11-06 12:35

MOT test number

487231480216

Result**✓ Passed**

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Position lamp slightly affected by the operation of another lamp (4.2.3 (c))
- Advice** Rear Exhaust mounting defective rubber split (6.1.2 (a))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Front Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Play in steering rack inner joint(s) both
- Minor** Offside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #19**

2020-11-06 10:15

MOT test number

669834826770

Result

✗ Failed

Fail Front Anti-roll bar linkage pin or bush excessively worn both sides of vehicle (5.3.4 (a) (i))**Fail** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Minor** Offside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Play in steering rack inner joint(s) both**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Rear Exhaust mounting defective rubber split (6.1.2 (a))**Advice** Nearside Rear Position lamp slightly affected by the operation of another lamp (4.2.3 (c))**MOT #18**

2019-11-20 15:53

MOT test number

871890760604

Result

✓ Passed

MOT #17

2019-11-07 15:41

MOT test number

128460505179

Result

✗ Failed

Fail Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #16** 2018-11-08 16:31**MOT test number** 981274133327**Result** ✓ Passed**Advice** Offside Rear parking brake just met requirements**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #15** 2018-11-07 16:16**MOT test number** 558268357636**Result** ✗ Failed**Fail** Offside Front Wheel bearing has excessive play (5.1.3 (a) (i))**Advice** Offside Rear parking brake just met requirements**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Outer Track rod end ball joint has excessive play (2.1.3 (b) (i))**MOT #14** 2017-11-01 15:55**MOT test number** 555859434408**Result** ✓ Passed**Advice** Nearside Front Track rod end ball joint has slight play (2.2.B.1f)**MOT #13** 2017-11-01 15:55**MOT test number** 593717957786**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)**Advice** Nearside Front Track rod end ball joint has slight play (2.2.B.1f)

**MOT #12** 2016-11-04 10:54**MOT test number** 491744886001**Result** ✓ Passed

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' x5 stone chips in windscreen (8.3.1d)

MOT #11 2016-11-03 09:31**MOT test number** 967546127762**Result** ✗ Failed

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' x5 stone chips in windscreen (8.3.1d)

Fail Offside front brake binding (3.7.B.1)

Advice Front brake disc worn, pitted or scored, but not seriously weakened both discs (3.5.1i)

Fail Nearside Front Tyre(s) incorrect because tyres fitted to all steerable axle are not of the same structure tyre is a commercial tyre (4.1.A.2c)

Fail Offside Brake pad(s) less than 1.5 mm thick (3.5.1g)

MOT #10 2015-11-09 10:08**MOT test number** 762978871223**Result** ✓ Passed**MOT #9** 2015-11-09 10:08**MOT test number** 346198005725**Result** ✗ Failed

Pass with rectification Nearside Stop lamp not working (1.2.1b)

MOT #8 2015-02-10 14:45**MOT test number** 527291745022**Result** ✓ Passed

**MOT #7** 2014-01-28 17:25**MOT test number** 965428224044**Result** ✓ Passed**MOT #6** 2014-01-28 17:25**MOT test number** 139128624480**Result** ✗ Failed**Pass with rectification** Front Headlamp aim too low (1.8)**MOT #5** 2013-02-21 11:59**MOT test number** 357272953072**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2012-03-07 09:27**MOT test number** 175467062019**Result** ✓ Passed**MOT #3** 2012-03-07 09:27**MOT test number** 225617462018**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too low (1.8)**MOT #2** 2011-03-18 11:34**MOT test number** 607567071085**Result** ✓ Passed**MOT #1** 2010-02-23 15:34**MOT test number** 720764850010**Result** ✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
31 December 2021

✕
MOT

Expired:
19 September 2022

Tax status

Expired at 31 December 2021

Days left

850 days too late

MOT expiry date

19 September 2022

Full MOT history

[See MOT history](#)



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2024-03-29
Current registration	 *****
Plate since	2024-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-03-21
Last registration	2021-09-20
Complete history	See info



Registration #1	2007-03-21	9 mi
Registration #2	2010-02-23	51.740 mi
Registration #3	2011-03-18	64.140 mi
Registration #4	2012-03-07	75.727 mi
Registration #5	2013-02-21	88.040 mi
Registration #6	2014-01-28	101.079 mi
Registration #7	2015-02-10	121.166 mi
Registration #8	2015-11-09	126.099 mi
Registration #9	2015-11-09	126.099 mi
Registration #10	2016-11-03	129.146 mi
Registration #11	2016-11-04	129.146 mi
Registration #12	2016-11-04	129.146 mi
Registration #13	2016-11-04	129.146 mi
Registration #14	2016-11-04	129.146 mi
Registration #15	2016-11-04	129.146 mi
Registration #16	2016-11-04	129.146 mi
Registration #17	2016-11-04	129.146 mi
Registration #18	2016-11-04	129.146 mi
Registration #19	2016-11-04	129.146 mi
Registration #20	2016-11-04	129.146 mi
Registration #21	2016-11-04	129.146 mi
Registration #22	2016-11-04	129.146 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2031 mm
Height	1835 mm
Length	4035 mm
Kerb weight	1060 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	2
Engine number	D189258