





report date: 2024-03-28

General information

Make	FIAT
Model	TIPO EASY PLUS
Colour	White
Year of manufacture	2017
Top speed	115 mph
0 - 60 mph	12.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	94 BHP	
Max. torque	127 Nm at 4.500 rpm	
Engine capacity	1.368 cc	
Cylinders	4	
Fuel type	Petrol	
Consumption city	36.7 mpg	
Consumption extra urban	62.8 mpg	
Consumption combined	49.6 mpg	
CO2 emission	132 g/km	
CO2 label	E	



CarCheck.co.uk page 1/11



WM17WJN report date: 2024-03-28

Internet history

Entry 1

Date 2022-05-31


Pictures 14

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/11



WM17WJN report date: 2024-03-28

MOT history

MOT expiry date	2024-05-04
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	11
Total items failed	1

MOT #6	2023-04-24 13:45
MOT test number	599810892436
Result	✓ Passed
Next expiry date	2024-05-04

MOT #5	2022-05-05 14:32
MOT test number	747101891800
Result	✓ Passed

MOT #4	2021-12-03 13:36
MOT test number	329610832659

Result \(\sqrt{Passed} \)

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #3 2021-12-03 13:36

MOT test number 266344099610

Result X Failed

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Pass with rectification Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #2 2020-11-25 11:53

MOT test number 811271805904

Result
✓ Passed

MOT #1 2020-05-16 09:08

MOT test number 275356135670

Result
✓ Passed

Advice COVID-19 6 MONTH EXTENSION

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 July
Days left	64
MOT expiry date	4 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Н
First licence fee (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners di Check it in the premium report and see all owner registrations. Download the full report	
manus .	

THE REAL PROPERTY AND ADDRESS OF THE PERTY ADDRESS OF THE PERTY ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY ADDR	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Monthly of these	
Municipal of process	
Current registration	NK SIE
Plate since	
Current registration	NK SIN
Plate since	
	More info >

CarCheck.co.uk page 8/11



WM17WJN report date: 2024-03-28

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2017-05-24
Last registration	2023-04-24
Complete history	See info



Registration #1	2017-05-24	9 mi
Registration #2	2020-11-25	36.149 mi
Registration #3	2021-12-03	42.278 mi
Registration #4	2021-12-03	42.278 mi
Registration #5		11.777 es
Registration #6		71.777 66
Registration #7		11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	82%
Children	60%
Pedestrian	62%
Safety systems	57%
Overall rating	68%
Video	see crash video



Dimensions & weight

Width	1792 mm
Height	1495 mm
Length	4368 mm
Wheel base	2638 mm
Kerb weight	1270 kg
Max. allowed weight	1695 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/3

Number of axles2Engine number2245020