





report date: 2024-03-29

### General information

Make	AUDI
Model	A4 TDI QUATTRO SE TECHNIK
Colour	Black
Year of manufacture	2013
Top speed	140 mph
0 - 60 mph	7.9 seconds
Gearbox	7 speed automatic

## Engine & fuel consumption

Power	175 BHP
Max. torque	380 Nm at 2.500 rpm
Engine capacity	1.968 сс
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	60.1 mpg
Consumption combined	53.3 mpg
CO2 emission	139 g/km
CO2 label	E



CarCheck.co.uk page 1/13



report date: 2024-03-29

## Internet history

## Entry 2

Date 2021-07-28

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

#### Entry 1

Date	2021-07-27
Pictures	30

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

## MOT history

MOT expiry date	2024-12-14
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	14
Total items failed	6

MOT #13		2023-11-30 10:45
MOT test	number	628713874064
Result		✓ Passed
Next expi	ry date	2024-12-14
Advice	Offside front brake binding slightly	
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Slight damage to nearside rear wheel inner rim	

MOT #12	2022-12-08 16:27
MOT test number	662279077011
Result	✓ Passed
Advice Offside Rear Tyre slightly damaged/cracking or peris	hing (5.2.3 (d) (ii))

CarCheck.co.uk page 3/13



report date: 2024-03-29

✓ Passed

**MOT #11** 2022-12-07 15:53

**MOT test number** 930831174350

Result X Failed

Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Fail** Nearside Front Inner Tyre has a cut in excess of the requirements deep enough to reach the ply or cords Sidewall (5.2.3 (d) (i))

Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Fail** Offside Front Inner Tyre has a cut in excess of the requirements deep enough to reach the ply or cords Sidewall (5.2.3 (d) (i))

MOT #10 2021-12-15 15:18

**MOT test number** 610875103137

**Result** ✓ Passed

MOT #9 2021-12-07 16:35

MOT test number 530809506334

**Result** X Failed

Fail Rear Rear fog lamp missing (4.5.1 (a) (ii))

Result

MOT #8 2020-12-09 15:54

**MOT test number** 775279262227

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #7	2020-12-09 15:33
MOT test number	376389972730
Result	<b>×</b> Failed
Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #6	2020-04-21 10:31
MOT test number	840432119149
Result	✓ Passed
MOT #5	2019-02-12 14:15
MOT test number	822170124854
Result	✓ Passed
MOT #4	2019-02-11 16:14
MOT test number	325224238674
Result	<b>X</b> Failed
Fail Nearside Side repeater missing (4.4.1 (a) (ii))	

Tearside Side repeater missing (Title (a), (ii))	
MOT #3	2018-02-02 16:13
MOT test number	935306299419
Result	<b>✓</b> Passed
MOT #2	2017-02-10 16:41
MOT test number	867532523335
Result	✓ Passed

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #1		2016-02-25 11:19
MOT test	number	861232056681
Result		✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	(under trays and engine covers fitted unable to check certain items)	

CarCheck.co.uk page 6/13



report date: 2024-03-29

### Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	14 December 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

#### Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



MF13ZZN report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

## Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners declared the premium report and see all owner registrations. Download the full report	
***************************************	
	More info >
Plate changes	
See in this check if this AUDI had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	UK NE
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-29

#### Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

**Contact info** 

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

## Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2013-03-25
Last registration	2023-11-30
Complete history	See info



Registration #1	2013-03-25	20 mi
Registration #2	2016-02-25	18.956 mi
Registration #3	2017-02-10	25.284 mi
Registration #4	2018-02-02	34.244 mi
Registration #5	2019-02-11	40.350 mi
Registration #6	2019-02-12	40.350 mi
Registration #7	2020-04-21	51.719 mi
Registration #8	2020-12-09	59.031 mi
Registration #9		11.777 es
Registration #10		11.177 es
Registration #11		11.177 mi
Registration #12		11.177 es
Registration #13		11.177 mi
Registration #14		11.777 es
Registration #15		11.777 mi

PR P. P. P.

More info >

77. 777 mg

CarCheck.co.uk page 12/13



report date: 2024-03-29

## Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Adult	93%
Children	84%
Pedestrian	39%
Safety systems	71%
Overall rating	78%
Video	see crash video



# Dimensions & weight

Width	2040 mm
Height	1427 mm
Length	4701 mm
Wheel base	2808 mm
Max. allowed weight	2145 kg

# Additional information

Fuel tank capacity	61 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles CarCheck.co.uk	2 page 13/13

**Engine number** 

CGLC351212