



Mercedes-Benz



report date: 2024-03-28

## General information

Make	MERCEDES
Model	CLS CLS320 CDI
Colour	Blue
Year of manufacture	2008
Top speed	148 mph
0 - 60 mph	7.0 seconds
Gearbox	7 speed automatic

## Engine & fuel consumption

Power	221 BHP
Max. torque	510 Nm at 2.800 rpm
Engine capacity	2.987 cc
Cylinders	6
Fuel type	Diesel
Consumption city	27.2 mpg
Consumption extra urban	47.9 mpg
Consumption combined	27.7 mpg
CO2 emission	200 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-07-14
Pictures	1
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2025-02-01
MOT pass rate	93 %
MOT passed	13
Failed MOT tests	1
Total advice items	32
Total items failed	1

## MOT #14 2024-02-02 15:19

MOT test number 362057100457

Result ✓ Passed

Next expiry date 2025-02-01

**Minor** Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated front arm (5.3.4 (b) (i))

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**Advice** Front under tray fitted

## MOT #13 2023-01-06 15:40

MOT test number 358712264590

Result ✓ Passed

**Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))

**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**Advice** Both front brake heat shields loose

**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))

**Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

**MOT #12**

2023-01-06 09:32

**MOT test number**

111461757087

**Result**

✗ Failed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Rear Brake pipe corroded, covered in grease or other material n/s & o/s (1.1.11 (c))
- Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Fail** Fuel system component leaking under tray covered in diesel (6.1.3 (b) (i))

**MOT #11**

2022-01-04 16:38

**MOT test number**

824069467291

**Result**

✓ Passed

- Advice** Nearside Front Lower Suspension arm ball joint has slight play front (5.3.4 (a) (i))

**MOT #10**

2021-01-11 11:24

**MOT test number**

928853451931

**Result**

✓ Passed

- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Upper Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Front Upper Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. 18% (1.4.2 (a) (i))

**MOT #9**

2020-01-04 10:32

**MOT test number**

588452265883

**Result**

✓ Passed



<b>MOT #8</b>	2019-01-05 13:04
---------------	------------------

<b>MOT test number</b>	774940213650
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #7</b>	2018-01-17 09:58
---------------	------------------

<b>MOT test number</b>	822837057620
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Advice</b>	Rear exhaust mounting brackets and bracing strap broken but exhaust still supported
---------------	---

<b>MOT #6</b>	2017-01-18 09:16
---------------	------------------

<b>MOT test number</b>	335492058630
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #5</b>	2015-12-30 12:42
---------------	------------------

<b>MOT test number</b>	984941860319
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Advice</b>	Nearside Front Tyre worn close to the legal limit inner edge (4.1.E.1)
---------------	--

<b>Advice</b>	Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement as marked (2.4.G.2)
---------------	--

**MOT #4** 2015-01-17 10:03**MOT test number** 248467815027**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** O/s front tyre outer sidewall has slight damage
- Notice** Under-trays fitted obscuring some underside components
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** O/s rear exhaust mount broken

**MOT #3** 2014-01-08 09:14**MOT test number** 317438904029**Result** ✓ Passed

- Notice** O/S front brake has judder
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Notice** Rear brake discs in poor condition

**MOT #2** 2013-01-22 14:47**MOT test number** 528002323043**Result** ✓ Passed**MOT #1** 2011-09-17 08:34**MOT test number** 266050161245**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
1 February 2025

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	126
<b>MOT expiry date</b>	1 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	J
<b>Single payment (12 months)</b>	£ 365,00,-
<b>Single six month payment</b>	£ 200,75,-
<b>Total payable by 12 monthly instalments</b>	£ 383,25,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 <b>SG58ZWC</b>
Plate since	2019-06-29
Current registration	 <b>SG58ZWC</b>
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2008-09-29
Last registration	2024-02-02
Complete history	<a href="#">See info</a>



Registration #1	2008-09-29	13 mi
Registration #2	2011-09-17	19.682 mi
Registration #3	2013-01-22	28.551 mi
Registration #4	2014-01-08	34.146 mi
Registration #5	2015-01-17	41.577 mi
Registration #6	2015-12-30	50.201 mi
Registration #7	2017-01-18	60.598 mi
Registration #8	2018-01-17	74.833 mi
Registration #9	2019-01-17	89.166 mi
Registration #10	2020-01-17	103.500 mi
Registration #11	2021-01-17	117.833 mi
Registration #12	2022-01-17	132.166 mi
Registration #13	2023-01-17	146.500 mi
Registration #14	2024-01-17	160.833 mi
Registration #15	2025-01-17	175.166 mi
Registration #16	2026-01-17	189.500 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2059 mm
Height	1403 mm
Length	4913 mm
Wheel base	2854 mm

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	4
Number of axles	2
Engine number	64292040688805