





report date: 2024-03-28

### General information

Make	VOLKSWAGEN
Model	CADDY C20 TDI BLACK EDITION
Colour	Black
Year of manufacture	2017
Top speed	107 mph
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	101 BHP
Max. torque	250 Nm at 1.300 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	51.4 mpg
Consumption extra urban	70.6 mpg
Consumption combined	61.4 mpg
CO2 emission	123 g/km
CO2 label	D



CarCheck.co.uk page 1/11



### Internet history

### Entry 1

Date 2021-08-17

Pictures 26

Listing price <u>View report</u>









source: heycar.co.uk

CarCheck.co.uk page 2/11



# MOT history

MOT expiry date	2025-01-10
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	10
Total items failed	1

MOT #6	2024-01-11 12:30
MOT test number	343845924747
Result	✓ Passed
Next expiry date	2025-01-10
Advice Both rear tyres heavily cracked on inner & outer edges	

MOT #5	2022-12-16 12:26
MOT test number	741905207393
Result	✓ Passed
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #4	2021-11-18 17:39
MOT test number	843136638763
Result	✓ Passed
Minor Windscreen damaged but not adversely affecting driver's view sm	nall chip in screen (3.2 (a) (i))

CarCheck.co.uk page 3/11



**MOT #3** 2020-12-11 08:30

**MOT test number** 232249741608

**Advice** Nearside Rear Nail in tyre

Advice Nearside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))

Minor Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #2** 2020-11-28 14:29

MOT test number 241652020530

**Result** X Failed

**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords outer wall (marked) (5.2.3 (d) (i))

**Advice** Nearside Rear Nail in tyre

Advice Nearside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))

Minor Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #1 2020-06-22 15:31

MOT test number 694625852582

Advice COVID-19 6 MONTH EXTENSION

CarCheck.co.uk page 4/11



### Tax & MOT check



Tax status	Valid until 1 November
Days left	185
MOT expiry date	10 January 2025
Full MOT history	See MOT history

### Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-

CarCheck.co.uk page 5/11




Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <a href="here">here</a> for the results.

#### Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	



#### Extra VOLKSWAGEN salvage check



**Type** 

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



### Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner	history
OWITEL	HISLULY

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	
*******	
************	
**********	
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
***************************************	
Plate changes	More info >
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	NK SIN
Plate since	
	More info >

CarCheck.co.uk page 8/11



### Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >

CarCheck.co.uk page 9/11



# Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2017-06-30
Last registration	2024-01-11
Complete history	See info



Registration #1	2017-06-30	26 mi
Registration #2	2020-11-28	39.950 mi
Registration #3	2020-12-11	40.434 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es

More info >

CarCheck.co.uk page 10/11



### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	84%
Children	78%
Pedestrian	58%
Safety systems	68%
Overall rating	74%
Video	see crash video



## Dimensions & weight

Width	2062 mm
Height	1823 mm
Length	4408 mm
Wheel base	2681 mm
Kerb weight	1594 kg
Max. allowed weight	2141 kg

### Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of seats	2
CarChack calule	nago 11/11

CarCheck.co.uk page 11/11

Number of axles	2
Engine number	DFSD203111