





report date: 2024-03-28

General information

Make	NISSAN
Model	PIXO VISIA
Colour	Blue
Year of manufacture	2011
Top speed	96 mph
0 - 60 mph	14.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	90 Nm at 3.400 rpm
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	64.2 mpg
CO2 emission	103 g/km
CO2 label	В



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2021-10-29

Pictures 21

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/12



LT61KWH report date: 2024-03-28

MOT history

MOT expiry date	2024-09-06
MOT pass rate	100 %
MOT passed	10
Failed MOT tests	0
Total advice items	12
Total items failed	0

MOT #10	2023-09-04 14:16
MOT test number	349551103492
Result	✓ Passed
Next expiry date	2024-09-06
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #9		2022-09-05 15:42
MOT test	number	193081753388
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #8		2021-08-21 10:35
MOT test	number	516792466972
Result		✓ Passed
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #7	2020-08-24 12:47
MOT test number	731164164881
Result	✓ Passed
MOT #6	2019-08-29 09:46
MOT test number	243599595218
Result	✓ Passed
Advice Offside and nearside rear tyres perished cracking edge of tread	
MOT #5	2018-08-11 11:11
MOT test number	549925730772
Result	✓ Passed
MOT #4	2017-08-30 09:56
MOT test number	713950169357
Result	✓ Passed
MOT #3	2016-08-30 15:12

MO1 #3	2016-08-30 15:12
MOT test number	163928745898
Result	✓ Passed

MOT #2		2015-08-25 09:58
MOT test	number	581268779087
Result		✓ Passed
Advice	Front tyre sidewalls perished	
Advice	Offside rear tyre 3mm and worn on outer edge	

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #1		2014-08-21 12:34
MOT test	number	925053234287
Result		✓ Passed
Advice	Nearside Tyre worn close to the legal limit (4.1.E.1)	
Notice	Vehicle's internal headlight adjuster altered to recheck lights	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 January
Days left	248
MOT expiry date	6 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners have? Check it in the premium report and see all owner registrations. Download the full it	
HARMAN CO. C.	

	More info >
Plate changes	
See in this check if this NISSAN had different number plates.	
Number of plates	,
Current registration	UK SIP.
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2011-09-06
Last registration	2023-09-04
Complete history	See info



Registration #1	2011-09-06	7 mi
Registration #2	2014-08-21	15.680 mi
Registration #3	2015-08-25	19.430 mi
Registration #4	2016-08-30	24.164 mi
Registration #5	2017-08-30	28.448 mi
Registration #6	2018-08-11	32.426 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 mg

More info >

CarCheck.co.uk page 11/12



LT61KWH report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

		_		
Dim	ension	<u>c </u>	MOIO	ht.
וווט	CHSIOL	אט כו	weiu	I I L

Width	1630 mm
Height	1470 mm
Length	3565 mm
Wheel base	2360 mm
Kerb weight	855 kg
Max. allowed weight	1250 kg

Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	133813

CarCheck.co.uk page 12/12