





report date: 2024-03-28

General information

Make	CITROEN
Model	DISPATCH 1200 L2H1 ENTERPRISE HDI
Colour	White
Year of manufacture	2015
Top speed	106 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	126 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	48.7 mpg
Consumption combined	44.1 mpg
CO2 emission	168 g/km
CO2 label	Н



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 3

Date 2021-08-25

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

Entry 2

Date	2021-08-18
Pictures	13

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2021-08-17
Date	2021-00-17
Pictures	0
Listing price	View report

source: heycar.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

MOT expiry date	2024-08-13
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	23
Total items failed	2

MOT #9		2023-08-14 07:52
MOT test	number	805892064099
Result		✓ Passed
Next expi	ry date	2024-08-13
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Oil leak, but not excessive (8.4.1 (a) (i))		
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #8	2022-08-01 06:35
MOT test	number 794993007334
Result	✓ Passed
Minor	Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Minor	Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #7 2021-08-13 11:28 **MOT** test number 557059802472 Result ✓ Passed **Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) **Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b)) Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Advice Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i)) Minor Central Front Oil leak, but not excessive (8.4.1 (a) (i)) **Advice**

MOT #6 2021-08-13 11:28 174364957499 **MOT test number** Result ★ Failed **Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b)) Minor Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i)) Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) **Advice** Pass with rectification Offside Front Windscreen washer not working (3.5 (a)) Advice Central Front Oil leak, but not excessive (8.4.1 (a) (i)) **Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Pass with rectification Nearside Front Windscreen washer not working (3.5 (a))

MOT #5

MOT test number

863673183098

Result

Advice Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

Minor Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #4 2020-07-09 12:40

MOT test number 338262829780

Result X Failed

Minor Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

MAJOR Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))

MOT #3 2019-07-18 13:58

MOT test number 879679256120

Minor Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #2 2019-07-18 09:15

MOT test number 191330997336

Result × Failed

MAJOR Brake pedal anti-slip provision missing (1.1.2 (c))

Minor Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #1 2018-07-04 15:25

MOT test number 475925290249

Result
✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 October
Days left	156
MOT expiry date	13 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history	

e when mistery	
For how long did the current and previous owner(s) have this CITROEN? How many owne have? Check it in the premium report and see all owner registrations. Download the full r	

	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	
Current registration	NK SIE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >


CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2015-11-27
Last registration	2023-08-14
Complete history	See info



Registration #1	2015-11-27	11 mi
Registration #2	2018-07-04	46.121 mi
Registration #3	2019-07-18	48.747 mi
Registration #4	2019-07-18	48.747 mi
Registration #5	2020-07-09	50.933 mi
Registration #6	2020-07-10	50.973 mi
Registration #7	2021-08-13	56.891 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		11.177 mi
Registration #12		11.777 es
Registration #13		70.777 au

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Dimensions & weight

Width	1895 mm
Height	1942 mm
Length	5135 mm
Kerb weight	1732 kg
Max. allowed weight	2932 kg

Additional information

Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Number of axles	2
Engine number	DYZG4158506

CarCheck.co.uk page 12/12