



report date: 2024-03-28

General information

Make	VAUXHALL
Model	ANTARA EXCLUSIV CDTI S/S
Colour	Grey
Year of manufacture	2013
Top speed	117 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	54.3 mpg
Consumption combined	46.3 mpg
CO2 emission	160 g/km
CO2 label	G





Internet history

Entry 1

Date	2022-01-17
Pictures	22
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-03-03
MOT pass rate	57 %
MOT passed	8
Failed MOT tests	6
Total advice items	14
Total items failed	18

MOT #14	2024-03-04 14:53
MOT test number	449844560286
Result	✓ Passed
Next expiry date	2025-03-03
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13	2024-02-29 10:51
MOT test number	444216217429
Result	✗ Failed
Fail	Nearside Windscreen wiper not working (3.4 (a))
Fail	Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Offside Front Position lamp not working (4.2.1 (a) (ii))
Fail	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #12	2022-08-30 14:26
MOT test number	588164469733
Result	✓ Passed



MOT #11	2022-08-30 14:26
MOT test number	404812304332
Result	✗ Failed
Pass with rectification	Nearside Headlamp aim too far to the left (4.1.2 (a))

MOT #10	2021-09-04 10:40
MOT test number	640014836970
Result	✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened slightly lipped (1.1.14 (a) (ii))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Offside Rear Tyre worn close to legal limit/worn on edge tread on 3mm inner (5.2.3 (e))
Advice	Front Brake pad(s) wearing thin both side (1.1.13 (a) (ii))

MOT #9	2021-08-31 14:05
MOT test number	669385216653
Result	✗ Failed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened both side lipped (1.1.14 (a) (ii))
Advice	Front Brake pad(s) wearing thin both side (1.1.13 (a) (ii))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened slightly lipped (1.1.14 (a) (ii))
Fail	Rear Brake pad(s) less than 1.5 mm thick both side (1.1.13 (a) (ii))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge tread on 3mm inner (5.2.3 (e))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #8	2020-08-29 10:31
MOT test number	809562095239
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #7** 2020-08-29 10:31**MOT test number** 342148378886**Result** ✗ Failed**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #6** 2019-08-12 15:23**MOT test number** 147463653850**Result** ✓ Passed**MOT #5** 2019-08-05 12:06**MOT test number** 123531567063**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Front Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Fail** Nearside Rear Headlamp aim too high and too far to the right. (4.1.2 (a))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Front Windscreen washer provides insufficient washer liquid (3.5 (a))**Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #4** 2018-05-09 10:13**MOT test number** 298746542520**Result** ✓ Passed



MOT #3	2018-05-09 09:11
MOT test number	124015757589
Result	✗ Failed
Fail	Offside Rear Registration plate lamp not working (1.1.C.1d)
Fail	Front Windscreen washer provides insufficient washer liquid (8.2.3)

MOT #2	2017-10-12 09:14
MOT test number	285000555057
Result	✓ Passed

MOT #1	2016-09-20 08:44
MOT test number	172074983902
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
3 March 2025

Tax status	Valid until 1 April
Days left	337
MOT expiry date	3 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 BN63BYM
Plate since	2024-03-28
Current registration	 BN63BYM
Plate since	2024-03-28

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2013-09-30
Last registration	2024-03-04
Complete history	See info



Registration #1	2013-09-30	22 mi
Registration #2	2016-09-20	20.696 mi
Registration #3	2017-10-12	28.582 mi
Registration #4	2018-05-09	33.115 mi
Registration #5	2018-05-09	33.115 mi
Registration #6	2019-08-05	43.032 mi
Registration #7	2019-08-12	42.038 mi
Registration #8	2020-08-29	49.401 mi
Registration #9	2020-08-29	49.401 mi
Registration #10	2020-08-29	49.401 mi
Registration #11	2020-08-29	49.401 mi
Registration #12	2020-08-29	49.401 mi
Registration #13	2020-08-29	49.401 mi
Registration #14	2020-08-29	49.401 mi
Registration #15	2020-08-29	49.401 mi
Registration #16	2020-08-29	49.401 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2085 mm
Height	1761 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1836 kg
Max. allowed weight	2505 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	Z22D1 263998K LNQ