



report date: 2024-03-29

General information

Make	VOLVO
Model	V50 S D V50
Colour	Silver
Year of manufacture	2009
Top speed	127 mph
0 - 60 mph	9.2 seconds
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	136 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.1 mpg
CO2 emission	153 g/km
CO2 label	G





Internet history

Entry 1	
Date	2021-09-29
Pictures	4
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-07-14
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	38
Total items failed	0

MOT #15	2023-07-07 09:42
MOT test number	433302702684
Result	✓ Passed
Next expiry date	2024-07-14

MOT #14	2022-07-06 09:29
MOT test number	687188457491
Result	✓ Passed
Advice	Rear reflectors slightly damaged
Advice	Offside Rear Tyre slightly damaged (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre slightly damaged (5.2.3 (d) (ii))
Advice	Nearside outer sill trim damaged
Minor	Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

**MOT #13**

2021-07-01 10:21

MOT test number

262411805616

Result

✓ Passed

- Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Exhaust box outer skin corroded
- Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Rear reflectors x2 damaged

MOT #12

2021-07-01 08:50

MOT test number

885676968337

Result

✗ Failed

- MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Exhaust box outer skin corroded
- MAJOR** Nearside Headlamp aim too low (4.1.2 (a))
- Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Rear reflectors x2 damaged

MOT #11

2020-07-15 15:39

MOT test number

565216674963

Result

✓ Passed

- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement wishbone-rear bush (5.3.4 (a) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement wishbone-rear bush (5.3.4 (a) (i))
- Advice** Nearside Rear Inner Road wheel slightly distorted (5.2.2 (c) (i))

**MOT #10**

2019-07-09 14:24

MOT test number

925956164108

Result

✓ Passed

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

MOT #9

2019-07-09 11:01

MOT test number

950577569188

Result

✗ Failed

Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

MAJOR Exhaust emissions exceed default limit of 1.5m-1 (8.2.2.2 (b))

Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MAJOR Offside Front Outline marker lamp not working (4.2.1 (a) (ii))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

DANGEROUS Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #8

2018-07-11 08:46

MOT test number

296884618286

Result

✓ Passed

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #7** 2018-07-10 12:12**MOT test number** 780183416914**Result** ✗ Failed**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MAJOR** Exhaust emissions exceed default limit of 1.5m-1 (8.2.2.2 (b))**MOT #6** 2017-07-10 11:18**MOT test number** 695196580599**Result** ✓ Passed**MOT #5** 2016-07-04 09:44**MOT test number** 493732161040**Result** ✓ Passed**MOT #4** 2015-07-13 16:49**MOT test number** 515304695125**Result** ✓ Passed**MOT #3** 2014-08-15 13:08**MOT test number** 368417324433**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** O/S/F TYRE WEARING ON INNER EDGE



MOT #2	2013-08-30 11:50
MOT test number	345892243442
Result	✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Front Brake pad(s) wearing thin (3.5.1g)

MOT #1	2012-10-05 10:40
MOT test number	387369572448
Result	✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
14 July 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	14 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-09-17
Last registration	2023-07-07
Complete history	See info



Registration #1	2009-09-17	23 mi
Registration #2	2012-10-05	25.383 mi
Registration #3	2013-08-30	32.504 mi
Registration #4	2014-08-15	41.382 mi
Registration #5	2015-07-13	50.914 mi
Registration #6	2016-07-04	60.665 mi
Registration #7	2017-07-10	70.625 mi
Registration #8	2018-07-10	75.607 mi
Registration #9	2018-07-11	75.607 mi
Registration #10	2019-06-20	75.577 mi
Registration #11	2019-06-20	75.577 mi
Registration #12	2019-06-20	75.577 mi
Registration #13	2019-06-20	75.577 mi
Registration #14	2019-06-20	75.577 mi
Registration #15	2019-06-20	75.577 mi
Registration #16	2019-06-20	75.577 mi
Registration #17	2019-06-20	75.577 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1519 kg
Max. allowed weight	1960 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number	565929
---------------	--------