



HYUNDAI



PX60VNY


report date: 2024-03-28

General information

Make	HYUNDAI
Model	I30 COMFORT
Colour	Black
Year of manufacture	2010
Top speed	119 mph
0 - 60 mph	11.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	124 BHP
Max. torque	157 Nm at 4.200 rpm
Engine capacity	1.591 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.3 mpg
Consumption extra urban	54.3 mpg
Consumption combined	45.6 mpg
CO2 emission	152 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-01-31
Pictures	0
Listing price	<a href="#">View report</a>

source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2025-01-21
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	10
Total items failed	8

MOT #14	2024-01-22 10:06
MOT test number	450213414727
Result	✓ Passed
Next expiry date	2025-01-21
Advice	Offside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Fuel tank corroded
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Fuel tank mounting straps corroded, tank still secure

MOT #13	2023-01-10 08:55
MOT test number	105949628242
Result	✓ Passed
Advice	Rear fuel tank corroded but not leaking
Advice	Rear fuel tank mounting straps corroded, fuel tank still secure

**MOT #12** 2023-01-09 11:17**MOT test number** 717496051660**Result** ✗ Failed

- Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))
- Fail** Nearside Front Direction indicator incorrect colour (4.4.3 (a))
- Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
- Advice** Rear fuel tank mounting straps corroded, fuel tank still secure
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))
- Fail** Offside Front Direction indicator incorrect colour (4.4.3 (a))
- Advice** Rear fuel tank corroded but not leaking

**MOT #11** 2022-01-21 08:38**MOT test number** 752297461526**Result** ✓ Passed**MOT #10** 2022-01-20 14:19**MOT test number** 739240755310**Result** ✗ Failed

- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))

**MOT #9** 2020-01-22 14:39**MOT test number** 837418601273**Result** ✓ Passed

- Advice** Front Incorrect fitment but doesn't affect brake performance



<b>MOT #8</b>	2019-01-23 15:56
<b>MOT test number</b>	529257454405
<b>Result</b>	✓ Passed
<b>MOT #7</b>	2018-01-19 13:11
<b>MOT test number</b>	405538714610
<b>Result</b>	✓ Passed
<b>MOT #6</b>	2017-01-17 12:09
<b>MOT test number</b>	257675034111
<b>Result</b>	✓ Passed
<b>MOT #5</b>	2016-01-26 15:42
<b>MOT test number</b>	870913698298
<b>Result</b>	✓ Passed
<b>MOT #4</b>	2015-02-05 10:21
<b>MOT test number</b>	285116735015
<b>Result</b>	✓ Passed
<b>MOT #3</b>	2015-01-08 16:04
<b>MOT test number</b>	728408305021
<b>Result</b>	✓ Passed
<b>MOT #2</b>	2014-01-11 09:18
<b>MOT test number</b>	767201814002
<b>Result</b>	✓ Passed
<b>MOT #1</b>	2013-09-11 09:17
<b>MOT test number</b>	148754053265
<b>Result</b>	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
21 January 2025

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	94
<b>MOT expiry date</b>	21 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >





Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-09-17
Last registration	2024-01-22
Complete history	<a href="#">See info</a>



Registration #1	2010-09-17	20 mi
Registration #2	2013-09-11	18.920 mi
Registration #3	2014-01-11	19.517 mi
Registration #4	2015-01-08	29.319 mi
Registration #5	2015-02-05	29.652 mi
Registration #6	2016-01-26	37.167 mi
Registration #7	2017-01-17	42.518 mi
Registration #8	2018-01-19	49.709 mi
Registration #9	2019-01-22	55.277 mi
Registration #10	2020-01-22	55.277 mi
Registration #11	2021-01-22	55.277 mi
Registration #12	2022-01-22	55.277 mi
Registration #13	2023-01-22	55.277 mi
Registration #14	2024-01-22	55.277 mi
Registration #15	2024-01-22	55.277 mi
Registration #16	2024-01-22	55.277 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1775 mm
Height	1480 mm
Length	4245 mm
Wheel base	2650 mm
Kerb weight	1293 kg
Max. allowed weight	1720 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	G4FCAZ147266