



PEUGEOT

**YP59FPN**

report date: 2024-03-29

General information

Make	PEUGEOT
Model	207 VERVE
Colour	Black
Year of manufacture	2009
Top speed	104 mph
0 - 60 mph	15.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	72 BHP
Max. torque	118 Nm at 3.300 rpm
Engine capacity	1.360 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	56.5 mpg
Consumption combined	44.1 mpg
CO2 emission	147 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-02-03
Pictures	6
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-05-03
MOT pass rate	65 %
MOT passed	13
Failed MOT tests	7
Total advice items	84
Total items failed	2

MOT #20	2024-04-23 14:41
---------	------------------

MOT test number	163113582789
-----------------	--------------

Result	✓ Passed
Next expiry date	2025-05-03
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))
Minor	Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside sill slightly damaged
Advice	Offside Front Coil spring corroded (5.3.1 (b) (i))
Advice	Offside Front Shock absorbers has a reduced damping effect (5.3.2 (d))
Minor	Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Various underside corrosion

**MOT #19**

2024-04-22 14:50

**MOT test number**

419064896490

**Result****✗ Failed**

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside sill slightly damaged
- Minor** Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- MAJOR** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Nearside Rear Position lamp slightly affected by the operation of another lamp (4.2.3 (c))
- Advice** Nearside Rear light unit lens slightly damaged
- Minor** Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))
- MAJOR** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- MAJOR** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Various underside corrosion
- Advice** Offside Front Shock absorbers has a reduced damping effect (5.3.2 (d))
- MAJOR** Nearside Front Headlamp aim unable to be tested (4.1.2 (b))



MOT #18

2023-04-17 12:28

MOT test number

294737712189

Result

✓ Passed

- Advice

Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Minor

Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice

Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice

Offside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))
- Advice

Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice

Nearside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))
- Advice

Oil leak, but not excessive (8.4.1 (a) (i))
- Minor

Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice

Offside Front strut top mount has slight play

**MOT #17**

2023-04-14 15:10

**MOT test number**

186379086031

**Result****✗ Failed**

- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))
- Minor** Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))
- MAJOR** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Advice** Offside Front strut top mount has slight play
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Minor** Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice** Offside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))
- Advice** Nearside Front strut top mount has slight play
- MAJOR** Nearside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- MAJOR** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

**MOT #16**

2022-05-04 14:10

**MOT test number**

647421259639

**Result****✓ Passed**

**MOT #15** 2022-05-03 11:12**MOT test number** 393859833472**Result** ✗ Failed

- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- MAJOR** Windscreen washer provides insufficient washer liquid (3.5 (a))
- DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- MAJOR** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- MAJOR** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
- MAJOR** Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #14** 2022-02-16 15:31**MOT test number** 756946902767**Result** ✓ Passed**MOT #13** 2021-02-16 15:17**MOT test number** 371171349927**Result** ✓ Passed**MOT #12** 2019-06-18 11:45**MOT test number** 354539114713**Result** ✓ Passed

- Advice** Oil leak, but not excessive Sump corroded (8.4.1 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #11**

2019-06-17 09:41

**MOT test number**

771716092183

**Result****✗ Failed**

- MAJOR** Rear Exhaust system insecure (6.1.2 (a))
- Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- MAJOR** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Oil leak, but not excessive Sump corroded (8.4.1 (a) (i))
- Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- MAJOR** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

**MOT #10**

2018-07-08 10:03

**MOT test number**

274570652752

**Result****✓ Passed**

- Advice** Front engine sump corroded oil leak
- Advice** Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))



**MOT #9** 2018-07-06 15:15**MOT test number** 232155773216**Result** ✗ Failed**Advice** Front engine sump corroded oil leak**Advice** Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))**MAJOR** Offside Rear Service brake excessively binding (1.2.1 (f))**MOT #8** 2017-05-17 13:00**MOT test number** 107083284719**Result** ✓ Passed**MOT #7** 2017-05-17 11:42**MOT test number** 494993027054**Result** ✗ Failed**Fail** Exhaust system not adequately supported back box (7.1.1)**MOT #6** 2016-05-12 09:26**MOT test number** 574743886703**Result** ✓ Passed**MOT #5** 2015-05-26 09:30**MOT test number** 787056145115**Result** ✓ Passed**Advice** Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

**MOT #4** 2014-07-11 14:05**MOT test number** 908292494171**Result** ✓ Passed**Advice** Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2014-07-11 08:46**MOT test number** 495332294117**Result** ✗ Failed**Fail** Tyre has ply or cords exposed (4.1.D.1b)**Advice** Brake pad(s) wearing thin (3.5.1g)**Advice** Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2013-07-17 14:47**MOT test number** 329628093109**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Front discs corroded vehicle has been stood**MOT #1** 2012-11-06 16:30**MOT test number** 248351512399**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 May 2025

✓  
**MOT**  
**Expires:**  
3 May 2025

<b>Tax status</b>	Valid until 1 May
<b>Days left</b>	366
<b>MOT expiry date</b>	3 May 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	<b>YP59FPN</b>
Plate since	2019-03-29
Current registration	<b>YP59FPN</b>
Plate since	2019-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2009-11-27
Last registration	2024-04-23
Complete history	<a href="#">See info</a>



Registration #1	2009-11-27	29 mi
Registration #2	2012-11-06	22.356 mi
Registration #3	2013-07-17	22.370 mi
Registration #4	2014-07-11	37.577 mi
Registration #5	2014-07-11	37.577 mi
Registration #6	2015-05-26	47.157 mi
Registration #7	2016-05-12	49.199 mi
Registration #8	2017-05-17	51.173 mi
Registration #9	2017-05-17	51.175 mi
Registration #10	2018-07-06	57.582 mi
Registration #11	2018-07-08	57.582 mi
Registration #12	2019-05-20	59.557 mi
Registration #13	2019-05-20	59.557 mi
Registration #14	2019-05-20	59.557 mi
Registration #15	2019-05-20	59.557 mi
Registration #16	2019-05-20	59.557 mi
Registration #17	2019-05-20	59.557 mi
Registration #18	2019-05-20	59.557 mi
Registration #19	2019-05-20	59.557 mi
Registration #20	2019-05-20	59.557 mi
Registration #21	2019-05-20	59.557 mi
Registration #22	2019-05-20	59.557 mi

More info >





Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1920 mm
Height	1502 mm
Length	4030 mm
Wheel base	2540 mm
Kerb weight	1214 kg
Max. allowed weight	1617 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	FSW86163295