



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	FOX 16V URBAN FOX
Colour	Blue
Year of manufacture	2007
Top speed	104 mph
0 - 60 mph	13.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	124 Nm at 2.750 rpm
Engine capacity	1.390 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.1 mpg
Consumption extra urban	49.6 mpg
Consumption combined	42.2 mpg
CO2 emission	161 g/km
CO2 label	G





Internet history

Entry 2

Date	2023-10-23
Pictures	13
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2022-02-10
Pictures	14
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2025-03-17
MOT pass rate	88 %
MOT passed	15
Failed MOT tests	2
Total advice items	38
Total items failed	3

## MOT #17 2024-03-18 15:18

MOT test number 487002813450

Result ✓ Passed

Next expiry date 2025-03-17

**Advice** Offside Rear Sub-frame pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))**Advice** Rear Boot lid slightly loose (6.2.1 (a) (i))**Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Parking brake has reserve travel but not excessive**Advice** Nearside Rear Sub-frame pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Front Headlamp slightly gone opaque**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

## MOT #16 2023-02-22 12:51

MOT test number 602529373074

Result ✓ Passed**Advice** GENERAL SURFACE CORROSION TO REAR SUBFRAME**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #15** 2022-02-25 14:21**MOT test number** 840560489572**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #14** 2022-02-25 14:21**MOT test number** 209713815174**Result** ✗ Failed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Pass with rectification** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**MOT #13** 2021-03-15 16:25**MOT test number** 188136310740**Result** ✓ Passed**Advice** Rear Shock absorbers has slight external damage to the casing Advise both rears (5.3.2 (b))**Advice** Front Direction indicator slightly discoloured Advise both fronts (4.4.3 (a))**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #12** 2020-03-25 15:43**MOT test number** 198485454055**Result** ✓ Passed**Advice** Suspension component pin or bush slightly worn rear axle front bushes both sides (5.3.4 (a) (i))**Minor** Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #11** 2020-03-25 12:37**MOT test number** 775951664895**Result** ✗ Failed

**Fail** Offside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

**Advice** Suspension component pin or bush slightly worn rear axle front bushes both sides (5.3.4 (a) (i))

**MOT #10** 2019-03-19 12:50**MOT test number** 254109673986**Result** ✓ Passed

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Minor** Offside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**Advice** Engine cover and under trays fitted

**MOT #9** 2018-03-27 12:37**MOT test number** 569511708688**Result** ✓ Passed

**Advice** Rear Tyres heavily perished

**Advice** Engine cover and Undertrays fitted

**MOT #8** 2017-03-14 11:48**MOT test number** 174371457876**Result** ✓ Passed

**Advice** Engine cover and Undertrays fitted

**MOT #7** 2016-03-29 12:29**MOT test number** 218323949508**Result** ✓ Passed**MOT #6** 2015-03-16 11:54**MOT test number** 196665475449**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2014-03-18 10:16**MOT test number** 885767074091**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Advice** Inner Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #4** 2013-03-15 11:05**MOT test number** 705114473013**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #3** 2012-03-12 16:12**MOT test number** 739412572040**Result** ✓ Passed



MOT #2	2011-03-29 11:26
MOT test number	736808481001
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Notice	Undertrays fitted.

MOT #1	2010-03-03 12:18
MOT test number	373212060031
Result	✓ Passed
Advice	Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
Advice	Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
17 March 2025

<b>Tax status</b>	Valid until 1 November
<b>Days left</b>	186
<b>MOT expiry date</b>	17 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-





Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>VN07GMY</b>
Plate since	2024-03-29
Current registration	 <b>VN07GMY</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2007-04-16
Last registration	2024-03-18
Complete history	<a href="#">See info</a>



Registration #1	2007-04-16	9 mi
Registration #2	2010-03-03	18.946 mi
Registration #3	2011-03-29	24.645 mi
Registration #4	2012-03-12	29.796 mi
Registration #5	2013-03-15	36.767 mi
Registration #6	2014-03-18	42.816 mi
Registration #7	2015-03-16	48.680 mi
Registration #8	2016-03-29	54.225 mi
Registration #9	2017-03-14	60.888 mi
Registration #10	2018-03-29	66.377 mi
Registration #11	2019-03-29	71.377 mi
Registration #12	2020-03-29	76.377 mi
Registration #13	2021-03-29	81.377 mi
Registration #14	2022-03-29	86.377 mi
Registration #15	2023-03-29	91.377 mi
Registration #16	2024-03-29	96.377 mi
Registration #17	2025-03-29	101.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1660 mm
Height	1544 mm
Length	3828 mm
Wheel base	2465 mm
Kerb weight	1093 kg
Max. allowed weight	1520 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	BKR 025870