





report date: 2024-03-29

### General information

Make	FORD
Model	RANGER THUNDER DCB
Colour	Silver
Year of manufacture	2006
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	107 BHP
Max. torque	266 Nm at 2.000 rpm
Engine capacity	2.500 cc
Cylinders	4
Fuel type	Diesel



CarCheck.co.uk page 1/14



# Internet history


### Entry 1

Date 2021-10-14

Pictures 6

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



MOT history
-------------

MOT expiry date	2024-09-22
MOT pass rate	76 %
MOT passed	16
Failed MOT tests	5
Total advice items	6
Total items failed	10

MOT #21	2023-09-23 14:25
MOT test number	866156415448
Result	✓ Passed
Next expiry date	2024-09-22
Advice Nearside Rear Wheel bearing has slight play (5.1.3 (a) (i))	

MOT #20		2022-10-31 17:05
MOT test i	number	208550469988
Result		✓ Passed
Advice	Brake pipe corroded, covered in grease or other material front to rear co	orroded (1.1.11 (c))

MOT #19	2021-11-15 17:21
MOT test number	389966098453
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/14



MOT #18 2021-11-01 15:14

MOT test number 328838082367

**Result** X Failed

Advice Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

**Advice** Offside Front fog lamp not working

**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))

Fail Central Exhaust system insecure bracket broken (6.1.2 (a))

Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**Advice** Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

**Fail** Rear fog lamp missing (4.5.1 (a) (ii))

Fail Nearside Front Position lamp light intensity significantly reduced (4.2.3 (a) (ii))

**MOT #17** 2020-10-24 10:01

**MOT test number** 810469768689

**Result** 
✓ Passed

MOT #16 2020-10-24 10:01

MOT test number 610305709139

**Result** X Failed

**Pass with rectification** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps

(4.7.1 (b) (ii))

**MOT #15** 2019-10-26 10:15

MOT test number 601511122713

Result 

Passed

CarCheck.co.uk page 4/14



Result

YC06HDJ report date: 2024-03-29

✓ Passed

MOT #14 2019-10-26 10:15 719111381510 **MOT** test number Result × Failed Pass with rectification Nearside Rear Direction indicator incorrect colour (4.4.3 (a)) Pass with rectification Offside Rear Direction indicator incorrect colour (4.4.3 (a))

**MOT #13** 2018-11-05 13:16 **MOT** test number 197000267800 Result ✓ Passed Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) **Advice** 

MOT #12 2017-11-04 10:00 **MOT** test number 362963063110 Result ✓ Passed **MOT #11** 2017-11-04 10:00 **MOT** test number 885024957538 Result × Failed **Pass with rectification** 

**MOT #10** 2016-11-07 13:34 **MOT** test number 762956189175 Result ✓ Passed **MOT #9** 2015-11-04 13:02 **MOT** test number 406263124466

Rear Registration plate lamp not working (1.1.C.1d)

CarCheck.co.uk page 5/14



MOT #8		2014-11-06 12:04
MOT test number		119540614335
Result		✓ Passed
MOT #7		2013-10-31 12:44
MOT test number		477234503454
Result		✓ Passed
MOT #6		2012-11-01 11:27
MOT test number		125806402372
Result		✓ Passed
MOT #5		2011-11-07 17:36
MOT test number		499121711467
Result		✓ Passed
MOT #4		2011-04-01 15:31
MOT test number		199831491005
Result		✓ Passed
MOT #3		2010 04 21 11.42
MOT #5 MOT test number		2010-04-21 11:42 454021010162
Result		
Result		✓ Passed
MOT #2		2010-04-21 11:42
MOT test number		804161910109
Result		× Failed
		\ T uned
Pass with rectification	Offside Rear Registration plate lamp not working (1.1.C.1d)	

CarCheck.co.uk page 6/14



**MOT** test number

YC06HDJ report date: 2024-03-29

MOT #1 2009-04-25 10:56

231805619177

Result ✓ Passed

CarCheck.co.uk page 7/14



#### Tax & MOT check



Days left 187

MOT expiry date 22 September 2024

Full MOT history See MOT history

CarCheck.co.uk page 8/14



### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 10/14



### Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	NK SIX
Plate since	
Current registration	OK SIE
Flate since	
	Moro info

CarCheck.co.uk page 11/14



report date: 2024-03-29

#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 12/14



# Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2006-04-27
Last registration	2023-09-23
Complete history	See info



Registration #1	2006-04-27	18 mi
Registration #2	2009-04-25	48.630 mi
Registration #3	2010-04-21	72.827 mi
Registration #4	2011-04-01	78.109 mi
Registration #5	2011-11-07	82.497 mi
Registration #6	2012-11-01	86.964 mi
Registration #7	2013-10-31	92.285 mi
Registration #8	2014-11-06	97.433 mi
Registration #9	2015-11-04	100.868 mi
Registration #10	2016-11-07	107.270 mi
Registration #11	2017-11-04	107.590 mi
Registration #12		77,777 46
Registration #13		11.777 es
Registration #14		77,777 46
Registration #15		11.117 es
Registration #16		11.177 es
Registration #17		11.177 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 46
Registration #21		11.777 es
Registration #22		9.77 66

More info >

CarCheck.co.uk page 13/14



### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Additional information

Fuel tank capacity	70 I
Fuel delivery	Indirect Injection
Number of doors	4
Number of seats	5
Engine number	627371

CarCheck.co.uk page 14/14