





report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TOURAN S TDI DSG DPF
Colour	Silver
Year of manufacture	2008
Top speed	128 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Semi Auto

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 сс
Cylinders	4
Fuel type	Diesel
Consumption city	31.7 mpg
Consumption extra urban	52.3 mpg
Consumption combined	42.8 mpg
CO2 emission	172 g/km
CO2 label	Н



CarCheck.co.uk page 1/12



MOT history

MOT expiry date	2024-07-21
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	19
Total items failed	7

MOT #17		2023-07-21 15:15
MOT test	number	909932647027
Result		✓ Passed
Next expi	ry date	2024-07-21
Advice (6.1.1 (a)	Nearside Outer Vehicle structure is deformed but structural rigidity is not significantly.	gnificantly reduced sill
Advice	Central Front Engine mounting damaged but not to excess (6.1.8 (a) (i))	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14	(a) (ii))
Advice rear (5.3.4	Nearside Front Lower Suspension arm pin or bush worn but not resulting in 4 (a) (i))	excessive movement
Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Undertrays fitted	

MOT #16	2022-07-20 12:43
MOT test number	123995850116
Result	✓ Passed
MOT #15	2021-07-22 14:26
MOT test number	934582951903
Result	✓ Passed

CarCheck.co.uk page 2/12



KX58XOU

report date: 2024-03-29

MOT #14

MOT test number

Result

Pass with rectification

Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

 MOT #13
 2020-07-09 13:12

 MOT test number
 973087801546

 Result
 ✓ Passed

MOT test number

Fesult

Pass with rectification

Nearside Front Tyre has ply or cords damaged (5.2.3 (d) (ii))

Pass with rectification

Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Pass with rectification

Nearside Front Lower Suspension arm ball joint likely to become detached (5.3.4 (a) (ii))

MOT #11

MOT test number

Passed

Advice Oil leak, but not excessive (8.4.1 (a) (i))

CarCheck.co.uk page 3/12



MOT #10 2018-04-12 14:30

MOT test number 813783789376

Advice Offside Front Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

Advice Nearside Front Front suspension has slight movement at a wishbone pin or bush (2.5.A.1c)

Advice Nearside Front Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Rear tyre perished

MOT #9 2017-04-18 09:53

MOT test number 194915159787

Result \(\sqrt{Passed} \)

MOT #8 2016-04-11 13:55

MOT test number 149566488357

MOT #7 2015-04-04 11:23

MOT test number 738334695075

Result

Passed

MOT #6 2014-04-02 14:16

MOT test number 959502794046

MOT #5 2013-09-30 16:54

MOT test number 725393973215

Result
✓ Passed

CarCheck.co.uk page 4/12



KX58XOU

report date: 2024-03-29

MOT #4 2013-09-30 11:29

MOT test number 275263273294

Result X Failed

Notice Both centre rear seatbelt flexible stalks covers missing

Fail Nearside Inner Front Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

MOT #3 2012-10-06 10:30

MOT test number 528680382206

Result ✓ Passed

Notice 3rd row seats stowed

Notice Child seat fitted not allowing full inspection of adult belt

Notice 2nd row centre seat belt I/h buckle casing missing

MOT #2 2012-10-04 16:02

MOT test number 996708172278

Result X Failed

Notice 2nd row centre seat belt I/h buckle casing missing

Fail Offside Inner Rear Brake lining(s) less than 1.5 mm thick (3.5.1g)

Notice 3rd row seats stowed

Notice Child seat fitted not allowing full inspection of adult belt

Fail Offside Inner Front Brake lining(s) less than 1.5 mm thick (3.5.1g)

MOT #1 2011-10-20 14:54

MOT test number 367033991261

Result \rightarrow Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 July
Days left	62
MOT expiry date	21 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date

Category

Type

Damage 2

Date

Category

Type



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



More info >

Owner history

C Miles Miscory	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dov here.	

STREET, STREET	

Plate changes	More info >
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	NK SIES
Plate since	100.00

CarCheck.co.uk page 9/12



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-09-01
Last registration	2023-07-21
Complete history	See info



Registration #1	2008-09-01	28 mi
Registration #2	2011-10-20	28.692 mi
Registration #3	2012-10-04	42.295 mi
Registration #4	2012-10-06	42.357 mi
Registration #5	2013-09-30	57.621 mi
Registration #6	2013-09-30	57.621 mi
Registration #7	2014-04-02	64.876 mi
Registration #8	2015-04-04	67.489 mi
Registration #9	2016-04-11	71.437 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		71.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 au

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air condition
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

here.

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1820 mm
Height	1472 mm
Length	4765 mm
Wheel base	2709 mm
Kerb weight	1671 kg
Max. allowed weight	2090 kg

Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	4
CarChaglegande	2000 12/13

CarCheck.co.uk page 12/12

Number of seats	5
Number of axles	2
Engine number	BKP 284781