





report date: 2024-03-28

General information

Make	BMW
Model	530 530I SE
Colour	Grey
Year of manufacture	-
Top speed	152 mph
0 - 60 mph	7.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	228 BHP
Max. torque	300 Nm at 3.500 rpm
Cylinders	6
Fuel type	Petrol
Consumption city	19.9 mpg
Consumption extra urban	37.7 mpg
Consumption combined	28.5 mpg



CarCheck.co.uk page 1/14



Internet history

Entry 1

Date 2021-10-01

Pictures 8

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



MOT history

MOT #18 2022-06-13 13:13

MOT test number 735267849016

Result ✓ Passed

Next expiry date 2023-06-16

MOT #17 2021-06-17 15:16

MOT test number 531286378294

Result \(\sqrt{Passed} \)

Advice Nearsid

Nearside Rear Exhaust mounting defective (6.1.2 (a))

MOT #16 2021-06-17 08:26

MOT test number 497458901179

Result X Failed

MAJOR Front Windscreen washer not working (3.5 (a))

DANGEROUS Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure outer side wall (5.2.3 (d) (ii))

Advice Nearside Rear Exh

Nearside Rear Exhaust mounting defective (6.1.2 (a))

Pass with rectification Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

CarCheck.co.uk page 3/14



report date: 2024-03-28

MOT #15 2020-04-24 09:42 836566511553 **MOT** test number ✓ Passed Result **Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Advice Nearside Rear hub has slight play in it Advice Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c)) Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c)) Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Nearside Front tyre has damage on the outer sidewall Oil leak, but not excessive (8.4.1 (a) (i)) Advice **Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #14		2017-08-08 12:33
MOT test	number	785908052880
Result		✓ Passed
Advice	Headlamp deteriorated but light output not reduced both (1.7.5a)	
Advice	Offside Rear Lower Suspension arm has slight play in a pin/bush (2.4.G.2)	
Advice	Nearside Rear Lower Suspension arm has slight play in a pin/bush (2.4.G.2)	

CarCheck.co.uk page 4/14



report date: 2024-03-28

MOT #13 2017-08-04 09:41

MOT test number 334393220669

Result X Failed

Advice Headlamp deteriorated but light output not reduced both (1.7.5a)

Advice Nearside Rear Lower Suspension arm has slight play in a pin/bush (2.4.G.2)

Fail Offside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

Fail Brake pipe excessively corroded front to rear (3.6.B.2c)

Advice Tyre pressure monitoring system warning lamp does not illuminate (4.1.D.4)

Advice Offside Rear Lower Suspension arm has slight play in a pin/bush (2.4.G.2)

Fail Offside Rear Tie bar/rod has excessive play in a pin/bush (2.4.G.2)

MOT #12 2016-07-28 09:47

MOT test number 992220282394

Result \(\sqrt{Passed} \)

Advice Offside Front Brake pipe slightly corroded (3.6.B.2c)

Advice Under-trays fitted obscuring some underside components

Advice Nearside Rear Brake pipe slightly corroded (3.6.B.2c)

MOT #11 2015-07-15 15:09

MOT test number 968316795107

Result ✓ Passed

MOT #10 2015-07-15 11:58

MOT test number 237576995133

Result X Failed

Fail Nearside Rear Upper Suspension arm has excessive play in a ball joint (2.4.G.2)

Fail Offside Rear Lower Trailing arm has excessive play in a pin/bush (2.4.G.2)

CarCheck.co.uk page 5/14



report date: 2024-03-28

2013-12-23 10:06 MOT #9 788907653357 **MOT test number** Result ✓ Passed Notice Play in steering rack inner joint(s) Nearside Front Brake pipe slightly corroded (3.6.B.2c) Advice Advice Offside Rear Brake pipe slightly corroded (3.6.B.2c) Notice Child seat fitted not allowing full inspection of adult belt Notice Engine covers fitted obscuring some components in the engine bay Advice Offside Front Brake pipe slightly corroded (3.6.B.2c) Notice Under-trays fitted obscuring some underside components

MOT #8		2012-12-17 11:41
MOT test	number	477432652499
Result		✓ Passed
Notice	Under-trays fitted obscuring some underside components	
Notice	Engine covers fitted obscuring some components in the engine bay	

MOT #7	2011-12-30 14:32
MOT test number	926314961351
Result	✓ Passed

CarCheck.co.uk page 6/14



report date: 2024-03-28

MOT #6 2011-12-23 09:59

MOT test number 545277151308

Result X Failed

Notice Play in steering rack unable to inspect thoroughly further inspection recommended

Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT #5 2010-12-18 09:39

MOT test number 532402350358

Result
✓ Passed

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #4 2009-12-24 10:29

MOT test number 753028359323

MOT #3 2008-12-20 10:24

MOT test number 831675158321

Result
✓ Passed

MOT #2 2007-12-21 10:16

MOT test number 102165557381

Result \rightarrow Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Notice Child seat fitted not allowing full inspection of adult belt

CarCheck.co.uk page 7/14



MOT #1 2006-12-15 10:44

MOT test number 611139346372

Result ✓ Passed

Notice Nail in nearside front tyre

CarCheck.co.uk page 8/14



report date: 2024-03-28

Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners defect it in the premium report and see all owner registrations. Download the full report		re?

	More info	>
Plate changes		
See in this check if this BMW had different number plates.		
Number of plates		
Current registration	UK C	
Plate since		
Current registration	NK NA	
Plate since		
	More info	>

CarCheck.co.uk page 11/14



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >


CarCheck.co.uk page 12/14



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2003-12-31
Last registration	2022-06-13
Complete history	See info



Registration #1	2003-12-31	21 mi
Registration #2	2006-12-15	28.052 mi
Registration #3	2007-12-21	35.631 mi
Registration #4	2008-12-20	44.302 mi
Registration #5	2009-12-24	47.420 mi
Registration #6	2010-12-18	50.759 mi
Registration #7	2011-12-23	58.333 mi
Registration #8	2011-12-30	58.400 mi
Registration #9	2012-12-17	62.648 mi
Registration #10	2013-12-23	66.752 mi
Registration #11		9.79 es
Registration #12		11.777 es
Registration #13		9.79 es
Registration #14		11.777 es
Registration #15		9.79 es
Registration #16		11.777 es
Registration #17		9.79 es
Registration #18		11.777 es
Registration #19		D.777 es
Registration #20		n.m.

More info >

CarCheck.co.uk page 13/14



Car features

50225	Air conditionin
50295	
60482	
60501	
60566	
60567	
60569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1846 mm
Height	1468 mm
Length	4841 mm
Wheel base	2888 mm
Kerb weight	1560 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of axles	2
Engine number CarCheck.co.uk	30053150 page 14/14